Remington Arms Co., Inc. Product Service Legal Case #:3575

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 170092 6/25/2009 6/26/2009 6/26/2009

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact

Reporter John Hood 138 N. Sterling St. Morganton NC 28655

H 828-217-3764
E goldstuf@bellsouth.net

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

PΙ

PD Cause:4006 Altered Adjustments or

S Components Unknown

Gun fires when moved from Concern:1007 Fired on Safe Release

Safe to Fire

Customer reported: Please inspect the firearm. When you go from Safe to Fire the gun will go off 1/2 the time. dmf

Firearm Information

Model/Ga. **SKU** Serial Bbl. **DOM** Mfg. Type CF/BA 7/308 WIN 24743 S7605102 00 7/23/1994 Remington Where Purchased Accessories **Original Owner Date Purchased** 6/15/2009 **COTTER & CO** N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/7/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Settlement Date APV APV

Repair at 1/2 normal charges

Repair/Replacement Repair/Replacement Cost Date

7/2/2009

7/2/09: Trigger set screws altered. Trigger has no return. Replace TPA, check over @ 1/2 normal charges. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		6/26/2009
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
	Jr 1551gilou 10		1.501.1(1

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=3575&Type=Case

7/2/2009

Cause	4006	Altered Adjustments or Components	
	Description		20" 308 WIN
	Date Code		00
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	j
Receiver	Bulged	False	
Safety	Description		STANDARD M/7 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6919	False	
	Condition	Slightly Worn; Not Functioning	TRIG. NOT RETURNING
Trigger	Pull	Select	3#
Tugger	Altered	True	SET SCREWS ALTERED
L	Sub-Assembly	Other Remington	_]

Repair Inquiry					
Repail Number RE00170092	Serial \$7605102 Model 7 C 308 WIN Produced: 07/23/19	994	Robert/Frink airing 6/26/2009 8:30,06 /	TT VSSS	
enly Repair.] ddress Information		Sum   144	alling Brzerzous B. 30,06 F	M	
Customer: Name: JOHN HOOD	<ul> <li>Received From</li> </ul>	Fletum Fo:  JOHN HOOD	C Received From		
ddiess 1: 138 N STERLING ST		138 N STERLING ST	andino di Salama a monana		
ddress 2: City: MORGANTON	PO Box	MORGANTON	PO Boxd		
State: NC Zip Code, 28655	Country: US	State NC Zip Code: [28655	Country US		
	And the second s			2.00	
Contact // Condition	Problems E	stimate History / Status	Shipping / Billin		
			Current Status		
Date UserID	Desc1 Repair information change	Desc2 • Shipping Hold	Repairing		
6/25/20097/12.5 pencerl	Expedite From: Check In	To: Repair B: InterFace Hold  Status: Appro Estimate Sent	6/26/2009 8:30:06 System	S.M.	
6/25/2009:12:46 frinkre 6/25/2009:12:50 Travisbw	Estimate Update Repair Maintenance	Status: Repai	Gallery		
6/25/200912:51 frinkre 6/26/20098:29:5 frinkre	Estimate Update Estimate Update	Status: Repai Passed Inspec	Repair Location		
6/26/2009 8:30 C System	Immediate SAP Allocation	I Helum As Hec	The second secon		
6/26/2009/2/06/1 pencerl	From: Repair Bench	Tα Gallery 🛨 🗔 Has been Appr □ □ Internal Repair	oved Transfer Numbe		
			liste series		
Repair Search			Refresh   Clo	3 <b>0</b>	
	The same and the s				
		A STATE OF THE STA			
				i un compositore de la propieta de la compositore de la compositore de la compositore de la compositore de la c La compositore de la	75 1 201
Berger British	The second secon				

	DE NUL	<u> [</u>	1	W.	
M	JUN	2	9	2009	
B	Y:				•



Model Number: Seven	Serial Number: S7605102
Are you the original owner?: YES 🗹 NO	
Name: John Hood	Date of Purchase: 6-15-2009
Address (no PO Boxes): 138 N. Sterling St.	
City: Morganton	State: NC Zip: 28655
Phone (Daytime): 828-217-3764	Fax:
E-mail Address:(if e-mail address is provided, notificent) goldstuf@bellsouth.net	cation of receipt and shipment will be
E-mail Address:  I would like to receive future e-mail updates from	n Remington.
Please describe your problem and date of occurr Please inspect this firearm. When you place the gun sa about half the time when you move the safety to the "F"	fety on the "S" position once you open and close the bolt
TRIQ. Setscieus Alte TRIQ. HAS NO ILETURN. +PA. clerkoven AT	red. Rephace
to A cleck over AT 1  Do Aunt changes.  272 characters left	
Ammunition Information:	
Manufacturer:	Туре:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
	Powder Weight:
740510°	Primer Used:
7605102	Primer Used:  Reloader Used:
7605102	Primer Used:  Reloader Used:
7605102	Primer Used:  Reloader Used:
7605102	Primer Used:  Reloader Used:

http://www.remington.com/support/repair\_services/factory\_repair\_form.asp

6/18/2009