Remington Arms Co., Inc. Product Service Legal Case #:2595

Case Information

RE# **Date Opened** 8/9/2008

Date Opened(PS) 8/11/2008

Date Closed 8/11/2008

Incident Date

Obsolete

148977 Customer Information

Business Type

First Name

Last Name

Street

City

State Zip Age Contact

Lit

Incident

Russell

Wheatley

102 Washington Ave

Lake Mary

FL 32746

H 407-947-4529 E rwheatley@cfi.rr.com

Incident Information

Claims

Codes

Repair Est.

Medical Treatment

Medical Status

PI

PD

Cause: 4015 Improper Maintenance

Unknown

S Fired on safe release

Concern: 1007 Fired on Safe Release

TA is rusty, the detent ball is missing, and the adjustments have been altered.

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial S7642165 Rbl.

DOM

Remington

CF/BA

7/7mm-08 Accessories

24741 **Original Owner**

Date Purchased

Where Purchased SPORTS SOUTH INC

U

3/14/2001 10:24:56 AM

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Cash

Reim. Date Cash Date

Settlement

Release of Claims

Release Date

Reimbursement

Settlement

APV APV

Repair/Replacement Cost Repair/Replacement Date

8/11/2008

8/11/2008 I spoke with customer - he said that he never had the trigger worked on and that he has not had the safety off. However, the detent ball is missing and the settings appear to have been altered. Since he had the accidental discharge I agreed to clean the action and install the new X-Mark Pro trigger assembly at n/c as a gesture of goodwill fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		Supry
	Exam Date		8/11/2008
	Product Type		RF
	Action Type		A
	Assigned To		Supry
Cause	4015	Improper Maintenance	Sticky residue, altered adjustments, rust
Barrel	Description		20 inch Model 7 Stainless 7mm- 08
	Date Code		
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown	Slightly Worn;	7

L	Condition	Functioning	J	
Bolt	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		·
	Face	Slightly Worn; Functioning		·
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning	sometimes it would stick due to build up of residue	
	Condition	Slightly Worn; Functioning		
	Cut Condition	Slightly Worn; Functioning		
[Ext/Eject Test	False]	F
	Block Condition	Select	1	
Locking	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Slightly Worn; Functioning		
Magazine	Condition	Slightly Worn; Functioning		
	Box Condition	Select	1	
Overall	Exterior Condition	Slightly Worn; Functioning		
	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	Select] .	
Receiver	Condition	Slightly Worn; Functioning		
	Bulged	False]	
	Description		Model 7	
Safety	Function	Abused; Functioning		
	Sub-Assembly	ISS]	
Sear	Lift	Select	<u> </u>	·
	Notch	Slightly Worn; Functioning		
		Condition	*Modified	The set screw positions have been altered, the detent ball was missing from the safety.
Pull	Trigger	Select	not measured	
Altered	Trigger	True		-
Sub- Assembly		M/700 Non-Bolt Lock		

BARBER - Kinzer PPS GAL RE0008548

The state of the s	System				
		iols (CSR Tools) Reports Table Mainter			
pai/Number RE00148977	Serial: \$7642185 Model 7. C rich barrel: Caliber: 7MM-08 F \$YN Produced: 03/14/2001		New 6/8/2008 9:11:58 PA		Professional Control of the Control
dress Information Customer Name RUSSELL WHEATLEY	Received From Rec	Return To: RUSSELL WHEATLEY	C: Received Fro	m.	
tiess 1 TO2 WASHINGTON AVENUE tiess 2 City LAKE MARY State: FL Zip Code (32746)	PO:Box: US	102 WASHINGTON AVENUE LAKE MARY State FL Zip Code	PO:Box		
Contact / Condition F	Christian and Market State of				
ate Code User ID		Desc2 Supplied Figure 1 Supplied Suppli	Current Status Hold New Hold 8/8/2008.9.11:56 bijgidowwr Check In eved Repair Localid spection Received Current Localid Approved	DPM	
Repair <u>S</u> earch			<u>Refresh</u> <u>C</u> lo	ose	
Suproff 8713					

I spoke with customer and agreed to install a new X-mark fro trigger and clean action at NR as gesture of goodwill.

Factory Repair Form
BARBER - Kinzer PPS GAL RE0088540

18977

- Mark PRO 23014 | 08

Check over completely

Remington.

Factory Repair Form

Return to Previous Page

NOTE: Please complete and print this form, and then include it with your firearm.

	<u>,</u>				
Model Number: MODEL SEUEN	Serial Number: 57642165				
Are you the original owner?: 😾 YES 🗀 NO					
Name: Russell Wheatift	Date of Purchase: 2001				
Address (no PO Boxes): 102 WASL Sugton AUE					
City: Lake maly	State:				
Phone (Daytime): 407-447-4509	Fax:				
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) Rukent(E) B CFI RR-CO,					
E-mail Address: I would like to receive future e-mail updates from Remington.					
AS I was sighting In My Rifle, as I took It off of the safe position, the gun ciled without me touching the unitget, It almost Milled my Brother is he was showing Beside me is I was sighting the gun In. Does Reminister have other situations like this, Please call me to talk about this situation					
Ammunition Information:					
Manufacturer: Reming for	Type: (40 (REAT				
Other (i.e. bullet weight/type, shot size, powder):					
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					
Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds)					
the Seeson					