Remington Arms Co., Inc.
Product Service
Legal Case #:2932

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

156159 12/2/2008 12/3/2008 12/3/2008

Customer Information

TypeBusinessFirst NameLast NameStreetCityStateZipAgeContactReporterA.W. Peterson Gun Shop, IncA.W. Peterson G4255 W. Old US 441Mt. DoraFL32757W 352-

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

TT 1

S Fired on bolt closing

olt closing Concern: 1008 Fired on Bolt Closing

Unknown

C

Customer said whe he closed the bolt, the safety was on and he was not touching the trigger, and the gun went off.

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/3006 SPR
 27410
 71052875
 AW
 3/13/2002 4:19:51 AM

Date Purchased Where Purchased Accessories Original Owner

WAL-MART DC 6003R-REGULAR SCOPE BASE U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim, Date Cash Date

APV APV

répair at no charge, goodwill

Repair/Replacement Cost Repair/Replacement Date

65.00 12/3/2008


12/3/2008 returned to AS to install a new TA to restore the customers confidence in the rifle. We could not duplicate the concern fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/3/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		AW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

i.	(1		
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
n:	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	

BARBER - Kinzer PPS GAL RE0008581



BARBERW. FIRTHER GAL RE0008582 GUN SHOP, INC. 4255 W Old U.S. 441

4255 W. Old U.S. 441 MT. DORA, FLORIDA 32757-3299 2932

10. AU 3/075#

(352) 383-4258 (352) 383-0595 FAX (352) 735-1001	DATE SHIPPED WARRANTY REPAIR	
то .,	SHIPPED VIA	.0
Kon opher Amar Commy	OUR MERCHANDISE	
14 Harthan Browns Brown Straw	(1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	,0
IMM MAN 13357	CREDIT RETURN	
MODEL MAKE AND CALTIGATES	SINT SINT SINT SINT SINT SINT SINT SINT	AME (TO)
JOB OESCRIPT	JON 100 TO THE TOTAL THE T	ng Engagn
Currence and and in which he	Company that bold the star	
Alety was our and he was		
	•	<u> </u>
No the year fresh off		
Plene De pour na mercon	for and they diffe a	م انگهای مرقاعه
is safe and project recole		
<u> </u>		~~~~
<u> Nog gunstinin prese Cor</u> bya 47 - 312-381-4285 Am	1 Phi A W. A. H. Marrier &	er British
has AT 352-383-4258 Alma	1914 Fra Born	
·		
	A second to the second	
	Howard Stores	
	Section of the second section of the section of the second section of the section o	

71052875 Could NO

Model: 710

RE00156159

Could Not duplicate concein Rephase TPA TO restore confident in 12 fte, chech owen clean. X/C # 230145

Thank You