

Remington Arms Co., Inc.
Product Service
Legal Case #:2458

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
146204	6/10/2008	6/11/2008	6/11/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	BJ Gunsmithing	BJ Gunsmithing		309 E Adler Ave	Davis	OK	73030		W 580-369-3772

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	fires on safe release Concern:1007 Fired on Safe Release			
C				

6/13/08--correspondence from repair-rifle had trigger replaced under SMP back in 2004. Customer claims that the gun fires when the safety is released.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	20000	6604515	RW	1/1/1900
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMMONS GUN SPEC OLATHE KAN	TWO PIECE SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	35	6/13/2008				

6/13/08-replace TA at n/c-goodwill.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/11/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	NEW TRIGGER ASSM INSTALLED BY RARC
Barrel	Description		22" 243 WIN
	Date Code		RW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

BARBER - Kinzer PPS GAL RE0008608

	Fired while Obstructed	
	Muzzle/Crown Condition	Worn; Functioning
Bolt	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Worn; Functioning
	Handle	Worn; Functioning
	Stop	Slightly Worn; Functioning
Extractor	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
	Ext/Eject Test	False
Locking	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
	Notch Condition	---Select---
Overall	Exterior Condition	Worn; Functioning
	Stock Condition	Worn; Functioning
	Fore End Condition	---Select---
Receiver	Condition	Worn; Functioning
	Bulged	False
Safety	Description	STANDARD M/700 SAFETY
	Function	Like new; Functioning
	Sub-Assembly	Non-ISS
Sear	Lift	---Select---
	Notch	Like new; Functioning
	Tests	Test Fired
Feeding Test		False
Trigger	Condition	Slightly Worn; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	M/700 Non-Bolt Lock
Non-Remington Components	Description	TWO PIECE SCOPE BASE

PURCHASE ORDER

430118

TO Remington Arms Co		DATE 5/29/08	
ADDRESS 14 Roetter Ave		DATE REQUIRED	
CITY, STATE, ZIP Elion, NY 13357		TERMS	
SHIP TO B&J Gunsmithing		HOW SHIPPED	
ADDRESS 309 E Adler Ave		REQ. NO. OR DEPT.	
CITY, STATE, ZIP DAVIS, OK 73030		FOR 580-369-3772	
QUANTITY	DESCRIPTION	PRICE	UNIT
1	This Rifle had the trigger replaced under the safety recall on 12-15-04. The customer complains the gun fires when the safety is released. This rifle is being returned to factory per Lyte Wheelock		
2			
3			
4			
5			
6			
7			
8			
9	Could not duplicate concern		
10	replace TPA, check over, clean		
11	AT N/C #23045		
12			
IMPORTANT			

COPIES OF YOUR
BILL OF LADING.

Number: 6604515

Model: 700



RE00146204