

Remington Arms Co., Inc.
Product Service
Legal Case #:3221

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
161852	2/11/2009	2/12/2009	2/12/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Seminole County Sheriff Ofc	Eric Bryant	Seminole County	100 Bush Blvd	Sanford	FL	32773		W 407-474-7950 E ebryant@seminolesheriff.org

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S C	Cause:4006 Concern:1008	Altered Adjustments or Components Fired on Bolt Closing	Unknown	

After firing one "cold shot" he chambered a secondary round and at that time the weapon discharged without pulling the trigger. dmf

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	*	E6551324	KT	5/1/1999
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE WITH EXTENTION,AFTER MKT STOCK	U			

CONCERN:FBC

Ammunition Information

Mfg.	Type	Cal./Ga.	SKU	UPC	DOM	Mfg. Code
*	/					
Concern	Other	Factory	Reload			
0:						

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair at 1/2 normal charges as goodwill gesture	Repair/Replacement Cost	Repair/Replacement Date				
		2/16/2009				

2/16/09: Repair at 1/2 normal charges per Fred S. Estimate for \$76.32 sent to customer. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/12/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
	Description		26" 308 WIN HB
	Date Code		KT

PrintDisplay

Page 2 of 2

Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.016
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY AND STICKY
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Trigger Assembly settings altered
and TA has sticky residue coating.

We are quoting new TA & cleaning action at $\frac{1}{2}$ normal charges (total of \$76.32.)

RECEIVED
FEB 13 2009

BY: _____

FRED 2/12/09



Seminole
County

Sheriff Donald F. Eslinger

An Internationally Accredited Agency

Commission on Accreditation for Law Enforcement Agencies
Commission for Florida Law Enforcement Accreditation
Florida Corrections Accreditation Commission
National Commission on Correctional Health Care
Public Safety Communications Accreditation

Deputy Eric Bryant
Seminole County Sheriff's Office
Special Weapons and Tactics
100 Bush Blvd.
Sanford, Florida

Remington Arms Services
Attention: Consumer Repairs
14 Hoefler Ave.
Ilion, New York 13357

Serial Number: **E6551324**
Model: **700**

RE00161852

Dear Sirs:

Enclosed you will find one Remington 700 .308 caliber tactical rifle, serial # E6551324 that is mounted within an Accuracy International AI stock.

During a recent training exercise one of our snipers experienced the following problem.

After firing one "cold shot" he chambered a secondary round and at that time the weapon discharged without pulling the trigger.

Please examine the rifle for any defects or safety issues and advise me of the cost to repair same.

If the trigger and safety can be upgraded please let me know as well.

My email address is ebryant@seminolesheriff.org, phone number 407-474-7950.

Sincerely,

Eric Bryant

could not duplicate concern.
Trig. Assm. Set & screws altered.
replace TPA, check over, clean
AT 1/2 normal charges.

Quote