

Remington Arms Co., Inc.
Product Service
Legal Case #:2459

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
146238	6/10/2008	6/11/2008	6/11/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Capital Sports & Westernwear	Al	Charrat	1092 Helena Ave	Helena	MT	59601		W 406-443-2978

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	fired on bolt closing Concern:1008 Fired on Bolt Closing			
C				

6/13/08-correspondence from repair-fired on bolt closing and also when safety was moved from safe to fire.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	B6418548	AD	3/1/1983
Date Purchased	Where Purchased	Accessories	Original Owner			
	G & G WHLSE DOUGLASVILLE GA	TWO PIECE SCOPE BASE	U			

CONCERN:FSR,FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair at discount						
	Repair/Replacement Cost	Repair/Replacement Date				

6/13/08-quote sent to repair at discount. 1/2 normal charges. Altered set screws.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/11/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SPR
	Date Code		AD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2459&Type=Case>

6/13/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED FOLLOWS DOWN
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00146238** Serial: 86418548 Model: 700 LH Center Fire Caliber: 3006 SPRG Produced: 03/21/1983 Repairman: Status: New 6/10/2008 6:39:55 AM

Verify Repair

Address Information

Customer: Received From Return To Received From

Name: **CAPITAL SPORTS WESTERN** **CAPITAL SPORTS WESTERN**

Address 1: **1092 HELENA AVE** **1092 HELENA AVE**

Address 2: **PO Box** **PO Box**

City: **HELENA** **HELENA**

State: **MT** Zip Code: **59601** Country: **US** State: **MT** Zip Code: **59601** Country: **US**

FEL

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	Code	User ID	Desc1	Desc2
6/10/2008 5:57:0	New	valentds	Repair Added	
6/10/2008 6:02:3	Update	valentds	Repair information change	
6/10/2008 6:05:1	Update	valentds	Repair information change	
6/10/2008 6:06:0	Expedite	valentds	From: Check In	To:
6/10/2008 6:39:5	Update	valentds	Repair information change	
6/11/2008 7:40:1	Expedite	pencerl	From: Check In	To: Repair Bench

Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair ☐

Current Status

New

6/10/2008 6:39:55 AM

valentds

Repair Bench

Repair Location

ILN

Current Location

ILN

Transfer Number

Repair Search Refresh Close

supryll 6/11/2008 9:59 AM CAPS NUM JMS SCPL

Start Inboxes Microsoft Outlook Microsoft PowerPoint Microsoft Excel Arms Services Repair

Repairman to Quote repair at 1/2 normal charges
altered adjustments.

MEMO LETTER

CAPITAL SPORTS & WESTERN
& ALL SEASONS SPORT SHOP1092 HELENA AVENUE
HELENA, MONTANA 59601
PHONE (406) 443-2978 FAX (406) 442-8136

2459

34
22
AD 3/53
012TO
Remington Arms
14 Hoefler Ave.
ILION N.Y. 13357

DATE

5-28-08 L.H.

SUBJECT

700 BDL 30-06

B6418548

WEAVER BASES

DEAR SIRS.

OUR CUSTOMER SAYS THIS RIFLE HAS FIRED ON
BOLT CLOSING AND ALSO WHEN SAFETY WAS MOVED FROM
'SAFE' TO 'FIRE'FIRING ASSM SET SCREWS ALTERED
WILL FOLLOW DOWN. replace TPA,
checkover clean AT 1/2 NORMAN

PLEASE CHECK AND ADVISE.

COST - Quote

THANKS

Number: B6418548

Model: 700



RE00146238

SIGNED

AL Charvat