

Remington Arms Co., Inc.
Product Service
Legal Case #:1908

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
138774	12/28/2007	1/2/2008	1/2/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Sanny	Cogliandro	640 Norcova Dr.	Chesapeake	VA	23320		H 757-547-1314

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S fired on safe release	Concern:1007 Fired on Safe Release			
C				

1/7/08-correspondence from repair-gun fired on safe release and had some delayed firing.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	A6481080	OO	7/13/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	S S KRESGE FAIRLESS HILLS PA	SEE THRU BASE/RINGS	U			

CONCERN:DELAYED FIRING

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
	Repair/Replacement Cost	Repair/Replacement Date				

1/7/08-quote sent to replace TA under smp.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/2/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	TRIG ASSM VERY DIRTY/STICKY
Barrel	Description		22" 3006 SPR
	Date Code		OO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=1908&Type=Case>

1/7/2008

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	STICKING
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY/STICKY
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SEE THRU BASES/RINGS

10 BARBER - Kinzer PPS GAL RE0008662
FROM: S.J. Cugliandro
640 NORCOVA DR
CHESAPEAKE VA. 23320

1908

12/8/07

007/7
6#
22"
10/12

Gentlemen,

Enclosed, please find my Rifle. This is a Model 700 in 30.06 Cal. Serial # A-6481080. I have owned this Rifle since the 1970's and have enjoyed good service with it since. A problem has just recently come up. While attempting to take a buck, the rifle failed to fire. This was not a misfire, but rather a non fire situation. I pulled the trigger (after in fire position) and could not pull the trigger. I emptied the chamber and put in a new round. with the same result. I again, emptied the chamber and, again cycled in another Round. By this time the Buck Moved out. I pulled the trigger again this ~~the~~ time, the trigger snapped ~~to~~ But the rifle did not fire right away. It was a delayed fire. At this point I cycled in another round to see if I had really had a delayed fire, and it again fired after I pulled the trigger. I cycled in one more Round and when I Closed the Bolt The Gun fired ~~and the Buck~~ I became concerned about the over-

Condition of this rifle, and ~~am~~ now
 Sending it to you to check out.
 If you would check this rifle
 but especially the firing
 Mechanism, I would greatly
 appreciate it. Also please
 apply any safety requirements
 to this rifle to insure safe
 operation under your safety
 program.
 Thank you for your
 consideration in this matter.

Sincerely,
 SANNY J. Coggin, JR.
 640 Norcova Dr.
 Chesapeake, VA
 23320

Photo# ~~807~~

could not duplicate concern 757-547-1314
 TRIG. ASSM VERY DIRTY & STICKY CAUSING PARTS TO BIND.
 Replaced TRIG. ~~and~~ check over, clean under bolt lock
 program Ron \$20.00 + S+H. Quote

Serial
 Number:

A6481080

Model: 700



RE00138774