

Remington Arms Co., Inc.
Product Service
Legal Case #:2065

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
140575	1/23/2008	1/24/2008	1/24/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Mike	Jones	509 N Hollow Rd	Coudersport	PA	16915		H 814-274-0462

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	fires on safe release Concern:1007 Fired on Safe Release			
C				

1/25/08-gun fires when safety is taken off. Sent gun in 2002 for same thing. lw 1/29/08-cust called Consumer Serv, did not make any adjustments, doesnt feel he should have to pay. I okd charges to be removed, goodwill.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	27476	E6884048	EP	10/24/1995

Date Purchased	Where Purchased	Accessories	Original Owner
7/1/2002	SHYDAS GUN SHOP	SCOPE BASE,BOTTOM HALF OF RINGS	U

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c						

Repair/Replacement Cost	Repair/Replacement Date
35.00	1/29/2008

1/29/08-quoted to replace at 1/2 price. Customer adamant that he did not make any adjustments. Took off charges, goodwill.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/24/2008
	Product Type		RF

	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	TRIG SET SCREWS ALTERED
Barrel	Description		22" 270 WIN
	Date Code		EP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		CROSS BOLT SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,BOTTOM HALF RINGS

RECEIVED
JAN 25 2008
BY: *[Signature]*

EP 10/95
3.5#
22"
10/11

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Serial Number: **E6884048**

Model: 700



RE00140575

Brand of lubricant used: