Remington Arms Co., Inc. Product Service Legal Case #:2990

Case Information

RE# **Date Opened** 12/16/2008 157234

Date Opened(PS) 12/17/2008

Lazaris

**Date Closed** 12/17/2008

**Incident Date** 

Pre Lit

Obsolete

Customer Information

Type **Business**  First Name Last Name Street

City

Zip

Contact H 608-577-7655

Incident

John G.

2249 Fox Ave

Madison

WI 53711

E lazaris@charter.net

Incident Information

Claims

S fired on safe release

Codes

Repair Est.

State

**Medical Treatment** 

Age

**Medical Status** 

PΙ

PD

Cause:4038

Could Not Duplicate Concern Concern: 1007 Fired on Safe Release

Unknown

Customer says he put the safety in the fire position and it went off.

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington **Date Purchased** 

CF/BA Where Purchased 700/270 WIN

20000

A6854940 OA 7/21/1980

Accessories

Original Owner

OUTDOOR SPT HQ WILLOWBROOK IL TWO PIECE SCOPE BASE

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement Cash Settlement Reim. Date APV Cash Date APV

**BLM Program** 

Repair/Replacement Cost Repair/Replacement Date

45.00

12/18/2008

12/17/2008 returned to AS to install a new TA and clean action. Quoting \$20 under the bolt lock modification program fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/17/2008
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		OA
,	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	·

ı •	[ <del></del>	-1	=
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	]
Overall	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
<u> </u>	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	]
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.008
Sear	Notch	Like new; Functioning	
	r	Test Fired	False
Feeding Test	Tests	False	,
	Condition	Like new; Functioning	
Trigger	Pull	Select	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Arms Services Repair & Estir		ods : (CSR (Tods ) Reports : Table:Mair	<b>tenance</b> System Manatena ice	Help	
Repair Inquiry  Repair Number   RE00157234  Verity Repair	Serial: AS854340 Model 70 270 WIN LH: Produced: 07		Bluce Travis  ApprovalHild 12/17/2008 5 32:	III X	
Address Information  Customer  Name: JJOHN G. LAZARIS	Received From	Return To:   JOHN G. LAZARIS	C Received Fro		
Addiess 1 2249 FOX AVENUE Address 2 Gay MADISON State WI Zip Code: [537]	PO Box:	2249 FOX AVENUE  MADISON  State: WI Zip Code: 53711	PO Box		
Date   Code	User ID Desc1 sanguinegl Repair Added sanguinegl From: Check In ArmEmail Repair Received ArmEmail Receipt Travistow From: Product Servic Travistow Estimate Update pencerl From: Repair Bench	To: ChineFa  LAZARIS@CHARTE LAZARIS@CHARTE LAZARIS@CHARTE Cas To: Repail Bench Status: ApprovalHot To: ApproveRack To: ApproveRack	Current Status  19 Hold ApprovalHold  ce Hold 12/17/2008 6:32:3  te Sent ApproveFack teceived Repair Locatio  1 Inspection LIN  As Received Current Locatio  en Approved	GAME I	
Repair Search			Refresh Cio	ise 1	
Start 🔘 Inbox - Micro	1/2/17/2008 2:58 PM osoft Out	Repair III	ING SORE		( O. H. esseni

REturned to AS For boil lock modifications
program
FLS 12/17/08

2990



## General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

2211 4# 400

Model Number: 700BDL LH	Serial Number: A6854940		
Name: John G. Lazaris	Date of Purchase: 1980		
Address (no PO Boxes): 2249 Fox Avenue			
ity: Madison	State: Wi Zip: 53711		
hone (Daytime): (608)577-7655	Fax:		
-mail Address: lazaris@charter.net			
lease describe your problem:			
While unloading my gun , I put the safety in the fire position at earning firearms safety at a young age- the muzzle was point affering this service.			
280 characters left			

could not duplicate concern.

Replace TPA checkover, clean

under bolt Lock program

Ron \$ 20.00 + S+H

Quote

http://www.remington.com/support/repair services/general repair form.asp

12/4/2008