

Remington Arms Co., Inc.
Product Service
Legal Case #:3107

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
159373	1/20/2009	1/21/2009	1/21/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Mark	Makima	314 Young St	Cheboygan	MI	49721		W 231-627-6548

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4038	Could Not Duplicate Concern	Unknown	
C	Concern:1007	Fired on Safe Release		

1/22/09 Letter with rifle states, it has fired twice when pushing the safety to the off position.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	25793	B6562337	AE	3/1/1984
Date Purchased	Where Purchased	Accessories	Original Owner			
10/16/1984	JOHNS SPORTING GDS CANTON OH	TWO PIECE SCOPE BASE	Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
repair at no charge, goodwill						
	Repair/Replacement Cost	Repair/Replacement Date				
	62.39	1/22/2009				

1/22/09 Could not duplicate concern. Safety works hard. Replace TPA, check over, clean at n/c.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/21/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		AE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Slightly Worn; Functioning	
Sear	Lift	---Select---	.015
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SAFETY WORKS VERY HARD
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Repair Inquiry

Repair Number: **RE00159373** Serial: B6562337; Model: 700; Center Fire; Caliber: 30-06 SPRG; Produced: 04/11/1984 Repairman: Bruce Travis
 Verify Repair Status: PartsHold 1/21/2009 8:47:44 AM

Address Information

Customer: ☒ Received From Return To: ☒ Received From

Name: MARK MAKIMA BUILDERS, INC. MARK MAKIMA BUILDERS, INC.
 Address 1: 314 YOUNG STREET 314 YOUNG STREET
 Address 2: PO Box PO Box
 City: CHEBOYGAN CHEBOYGAN
 State: MI Zip Code: 49721 Country: US State: MI Zip Code: 49721 Country: US
 FFL: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Descr	Current Status
1/20/2009 10:04	New	sanguinegf	Repair Added	<input type="checkbox"/> Shipping Hold
1/20/2009 10:09	Update	sanguinegf	Repair information change	<input type="checkbox"/> InterFace Hold
1/20/2009 10:10	Expedite	sanguinegf	From: Check In	<input type="checkbox"/> Estimate Sent
1/20/2009 10:13	Expedite	sanguinegf	From: Product Services	<input type="checkbox"/> Parts Received
1/21/2009 8:07:1	Expedite	travisbw	From: Product Services	<input type="checkbox"/> Passed Inspection
1/21/2009 8:47:4	Estimate	travisbw	Estimate Update	<input type="checkbox"/> Return As Received
				<input type="checkbox"/> Has been Approved
				<input type="checkbox"/> Internal Repair

Repair Search Refresh Close

3539
 12
 15
 62.39

RECEIVED
 JAN 22 2009
 BY:

AE 3/84
22"
3.5"
.015



MARK MAKIMA BUILDERS, INC.

314 YOUNG STREET
CHEBOYGAN, MICHIGAN 49721

LICENSED AND INSURED

PHONE 231-627-6548

3107

DEAR REMINGTON & CO,

~~11-25-00~~
1-5-09

I PURCHASED YOUR MODEL 700 BDL IN A 30-06 CALIBER RIFLE BACK IN 1984 FROM A LICENSED GUN DEALER HERE IN MICHIGAN AS A BRAND NEW RIFLE. I SINCE HAVE USED IT EVERY YEAR FOR DEER HUNTING AND REALLY ENJOY THE FEEL AND LOOKS OF THE RIFLE. BUT I HAVE A FEAR OF USING IT ANYMORE AS IT HAS FIRED PREMATURELY TWICE NOW WHEN PUSHING THE SAFETY TO THE OFF POSITION, I LOST MY RESPECT FOR THIS MODEL OF YOUR RIFLE AND WANT YOUR INPUT AS TO GETTING IT REPAIRED OR REPLACED.

PLEASE HELP ME WITH THIS MATTER.

SERIAL # IS B6562337

REMINGTON MODEL 700 BDL DELUXE

30-06 CALIBER

BOUGHT 10-16-84

#1521
CHECK ENCLOSED
\$35.00

THANK YOU,

SINCERELY,

REMINGTON CO.
1-800-243-9700

MARK MAKIMA
314 YOUNG ST.
CHEBOYGAN, MICH 1
49721

231-627-6548

PLEASE RETURN WITH MY
ORIGINAL AND THANK U

1-5-09

DEAR SIR @ REMINGTON CO.

MY REMINGTON 700 BDL
 0-06 CALIBER HAS MISFIRED
 ON ME TWICE NOW AND I
 NEED THE SAFETY MECHANISM
 REPLACED AS IT HAS FIRED
 WHEN PUTTING THE SAFETY
 ON THE OFF/FIRE POSITION.
 PLEASE HELP ME WITH
 THIS MATTER

SERIAL #

THANKS,

B 656 2337

 PURCHASED
 10-16-84

 MARK MAKIMA
 314 YOUNG ST,
 CHEBOYGAN, MICH.
 49721

231-627-6548

B6562337

Model: 700



RE00159373

could not duplicate concern.
 Safety works hard. Replace
 TPA, check over, clear w AT
 R/c

#230145