Remington Arms Co., Inc. Product Service Legal Case #:2355

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

144607 4/18/2008 4/21/2008 4/21/2008

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Terry Oliver 1405 Samuels Road Sandpoint ID 83864 C 208-290-4118

**Incident Information** 

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern

Unknown

S fired on safe release Concern:1007 Fired on Safe Release

C

4/28/08-correspondence from repair-rifle fired when safety released.lw

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/300 WM 27130 S6402122 CY 5/22/2002 2:15:41 PM

Date Purchased Where Purchased Accessories Original Owner

6/4/2002 SPORTSMAN SURPLUS HARD CASE Y

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date Settlement APV APV

Replace TA at

n/c

Repair/Replacement Repair/Replacement

Cost Date

35.00 4/28/2008

4/28/08-replaced TA at n/c goodwill.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/21/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2355&Type=Case

4/28/2008

Barrel	Description		24" 300 WM W/BREAK
	Date Code		CY
	Bore Plugged	False	
	Bulged	False	Ī
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	Ī
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
n i	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.011
Sear	Notch	Like new; Functioning	
	Togta	Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
Trigger	Pull	Select	4.5#
Trigger	Altered	False	]
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		HARD CASE

CArmos Cerviscis Reportis l'estatimento System  File: Add Repair: Estimate Repair: Expèdité Repair: Enquiry: Repair Tools: CSR Tools: Reports: Table Maintenance: System Maintenance: Help: Signification of the Company	g noting of cooks and cooks and cooks are considered to the cooks and cooks are considered to the cooks and cooks are cooks and cooks are cooks and cooks are cooks are cooks and cooks are cooks are cooks and cooks are cooks ar
RepairNumber   RE00144507   Serial S6402122 Model-700 Center Fire Caliber   Repairman   300 WIN MAG Produced 95/22/2002   Status   New 4/21/2008 7 48-17 6M	
Addiess 1:   1405 SAMUELS ROAD	
Contact / Condition	
Repair Search Close	
suppli 4/23/2008 10:40 AM CAFS NUM INS SCRI	PHARMA (CAN SERVICE

Also changing bolt to NON-185 Style per request. 2355

C4 4/04

April 08, 2008

Terry E. Oliver 1405 Samuels Road Sandpoint, Idaho 83864 S6402122

Model: 700

PEQQ1446Q7

Keith @ Remington's Custom Shop

## Keith,

As per our previous conversations, here is how the rifle malfunctioned. My wife was shooting it at the range in preparation for a moose hunt, so I was coaching her and giving her instructions. She had ejected a spent shell casing and before closing the bolt, she put the safety in the "safe" position. No, I didn't tell her to do this! Anyway, she proceeded to close the bolt, putting a live round in the chamber. I didn't think the bolt would allow this to happen, so I never gave it another thought. When she was ready to shoot, she nudged the safety forward into the "fire" position, and the gun fired! Her thumb was all that was touching the gun as the rest of her hand was out to the side. I taught her to do this so her finger would never be on the trigger when the safety was put in the "fire" position. I was watching her the entire time, so I can verify that this is exactly what happened. I tried to duplicate this action several times, with an empty chamber, but was never able to do so.

When you and I discussed this, you thought it might be the fault of the "locking bolt". I would really appreciate you replacing this bolt with the old style bolt that doesn't have this goofy feature. Also, could you please test the trigger to see what the pull weight is and if it is over four pounds, could you please adjust it to four pounds?

could not deplicate concern. check ouen completely. Reproce TPA, clean Function lest.

Thanks, and if you need to reach me, my no. is 208 290-4118.

Terry E. Oliver

**BARBER - Kinzer PPS GAL RE0009051** 

Brand of lubricant used:

## Remington

**Factory Repair Instructions** (NOTE: Please print and complete this form, and then include it with your firearm.) Serial Number: < Model Number: Are you the original owner?: Date of Purchase: Address (no PÓ Boxes): State: Phone (Daytime): E-mail Address: would like to receive future e-mail updates from Remington. Please describe your problem: **Ammunition Information:** Manufacturer: MOMAN Other (i.e. bullet weight/type, shot size, powder): Handload Information: Powder Used: Powder Weight: Case/Hull Used: Primer Used: Bullet Type/Shot Size: Reloader Used: Firearms Care (Cleaning and Lubrication): Brand of cleaning solution used: Swats 1.67 SOLVANA How often do you clean the bore? (Months or Number of rounds) How often do you clean the action? (Months or Number of rounds) How often do you clean the trigger assembly? (Months or Number of rounds)

**BARBER - Kinzer PPS GAL RE0009052** 

4/7/2008 4:30:05

Sorial	Sold	Re	port.
Brady's	Sports	man	eulqru2 &

Filters: Serial Log	# equals 25050						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Pag
Serial # Log #	Serial Group Serial Type	ltem # Vendor	Manufacturer Model	Name City, State Zip		Trans Date Status Recy Date Recy Inv #	Unit Cost	Pı
\$6402122/ -25050 /	FIREARMS	04770027130 REM	REMINGTON 700 KS MT REM	OLIVER, TERRY KOOTENAI, ID 8384	6/4/2002	5/31/2002		
Total 1					V	1 6		7
N/ M	#7	1153		1//	Pychase	date	•	
			Marcolan	u'DUI	<i>,</i>			
Avial F	<u>+</u>		THE PROPERTY OF THE PROPERTY O	ddress	•			

200 263-1842