

Remington Arms Co., Inc.
Product Service
Legal Case #:3047

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
158289	1/8/2009	1/9/2009	1/9/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Andrew M.	Ridilla	204 Highview Street	Latrobe	PA	15650		H 724-537-2907 C 724-953-4801

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4038	Could Not Duplicate Concern	Unknown	
C	Gun fired when moved from Safe to Fire	Concern:1007 Fired on Safe Release		

Occasionally the safety sticks in the off position and the gun fired when safety was pushed from Safe to Fire position. Gun was purchased in the early 1970's. dmf

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR		6716434	LY	2/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replaced trigger						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$47.38	1/14/2009				

1/14/09: Customer received estimate of charges and he called, approved, and paid by credit card \$37.10. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/9/2009
	Product Type		RF
	Action Type		A
	Assigned To		F. SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		LY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	

Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.009
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Arms Services Database System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00158289** Serial: 6216434 Model: 700 Center Fire Caliber: 30-06 SPRG Repairman: Bruce Travis
 Verify Repair Status: Approval Hold: 1/9/2009 9:18:27 AM

Address Information

Customer: ☒ Received From Return To: ☐ Received From

Name: **ANDREW M. RIDILLA** **ANDREW M. RIDILLA**
 Address 1: **204 HIGHVIEW STREET** **204 HIGHVIEW STREET**
 Address 2: PO Box: PO Box:
 City: **LATROBE** **LATROBE**
 State: **PA** Zip Code: **15650** Country: **US** State: **PA** Zip Code: **15650** Country: **US**
 FFL: ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing																												
<table border="1"> <thead> <tr> <th>Date</th> <th>Code</th> <th>User ID</th> <th>Desc</th> </tr> </thead> <tbody> <tr> <td>1/8/2009 9:48:16</td> <td>New</td> <td>sanguinegl</td> <td>Repair Added</td> </tr> <tr> <td>1/8/2009 9:53:14</td> <td>Expedite</td> <td>sanguinegl</td> <td>From: Check In</td> </tr> <tr> <td>1/9/2009 8:58:43</td> <td>Expedite</td> <td>Travisbw</td> <td>From: Product Services</td> </tr> <tr> <td>1/9/2009 9:18:16</td> <td>Estimate</td> <td>Travisbw</td> <td>Estimate Update</td> </tr> <tr> <td>1/9/2009 9:18:27</td> <td>Maint</td> <td>Travisbw</td> <td>Repair Maintenance</td> </tr> <tr> <td>1/9/2009 9:31:53</td> <td>Expedite</td> <td>pencarl</td> <td>From: Repair Bench</td> </tr> </tbody> </table>			Date	Code	User ID	Desc	1/8/2009 9:48:16	New	sanguinegl	Repair Added	1/8/2009 9:53:14	Expedite	sanguinegl	From: Check In	1/9/2009 8:58:43	Expedite	Travisbw	From: Product Services	1/9/2009 9:18:16	Estimate	Travisbw	Estimate Update	1/9/2009 9:18:27	Maint	Travisbw	Repair Maintenance	1/9/2009 9:31:53	Expedite	pencarl	From: Repair Bench	☐ Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has Been Approved ☐ Internal Repair	
Date	Code	User ID	Desc																													
1/8/2009 9:48:16	New	sanguinegl	Repair Added																													
1/8/2009 9:53:14	Expedite	sanguinegl	From: Check In																													
1/9/2009 8:58:43	Expedite	Travisbw	From: Product Services																													
1/9/2009 9:18:16	Estimate	Travisbw	Estimate Update																													
1/9/2009 9:18:27	Maint	Travisbw	Repair Maintenance																													
1/9/2009 9:31:53	Expedite	pencarl	From: Repair Bench																													
			Current Status Approval Hold: 1/9/2009 9:18:27 AM Travisbw Approve Rack Repair Location: ILN Current Location: ILN Transfer Number:																													

Repair Search Refresh Close

supryl 1/9/2009 2:00 PM CAPS NUM INS SCUL

Start Inbox - Micros... 2 Microsoft O... Arms Services Part Search by... Search for a Se... Stock Over vie... 2:00 PM

Bolt Lock Modification program

Ser # 6716434

~~3097~~
3097

Dec 18, 2008

LY 2/74

204 Highview St

2211
2551

Sakabe, Pa 15650

009

724-537-2907

Call ph. 724-953-4801

Dear Sir;

Here is the rifle that I called in about yesterday. Occasionally the safety sticks in the off position and a number of times when I push it from the from the Safe to Fire position, it fires causing me to lose skin on my thumb and in last Saturday's incidence it fired as I was getting a bead on an 8 pt buck. This was the last straw so I decided to do something about it.

My date of purchase is unknown, somewhere in the early 70's from a small shop in Blairsville, PA. called Clauson & Millers. They have been out of business since the 90's.

I was told on the phone that repairs might be about 35.00 so I'd chance a C.O.D.

This rifle has brought down a number of deer so I don't want to lose it. Thank you

Andrew M. Ridilla
Andrew M. Ridilla

could not duplicate concern.
Replace TPA, check over, clean
under ISOCT low program
Ron \$ 20.00 x SSA.

Quote

Serial Number: 6716434

Model: 700



RE00158289