

BARBER - Kinzer PPS GAL RE0009120

Remington Arms Co., Inc.

Product Service

Legal Case #:2120

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
140795	2/9/2008	2/11/2008	2/11/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sharp Shooters Knife & Gun	Sharp Shooters		5062 50th St	Lubbock	TX	79414		H 806-791-1231 F 806-791-2904

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance	Unknown	
S	rifle discharges when raising bolt	Concern:1020 Fired on Bolt Opening		
C				

2/13/08-correspondence from repair-while raising bolt, the firearm discharges.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/2506 REM	20000	A6284581	CI	4/5/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAMMES GUNS BELEFONTAINE OH	SCOPE BASE,RINGS	U			

CONCERN:FIRED AS BOLT IS RAISED

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA under SMP						
Repair/Replacement Cost	Repair/Replacement Date					

2/13/08-quote sent to replace ta under smp.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/11/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	TRIG ASSM VERY DIRTY,STICKY PARTS WORK SLUGGISH
Barrel	Description		24" 2506 REM
	Date Code		CI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2120&Type=Case>

2/15/2008

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	WORKS SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	BEDDING ALTERED
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	7#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,RINGS

TRIG. ASSM. VERY DIRTY & STICKY
PARTS WORK SLUGGISH.
Replace TPA, check over, clean 7#
~~As if to be made~~
UNDER BOLT LOCK PROBLEM CI 4/76
for 8000 TSH

Quote

24"
.012Serial
Number:

A6284581

Model: 700



RE00140795

RECEIVED
FEB 13 2008

SHARP SHOOTERS KNIFE & GUN EXCHANGE BY: *dw*

5062 50th Street
LUBBOCK, TEXAS 79414
(806) 791-1231 Fax (806) 791-2904

Gun Return

Customer's Order No.		Date		1-16-20-08	
Name		Si Conner			
Address		506 946-7186			
		806 495-3207			
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RETD.
QUAN	DESCRIPTION			PRICE	AMOUNT
	Ship to: Remington				
	Model 700 Cal. 25-06				
	White Raising Bolt the				
	Rifle arm discharged				
	Serial A6284581				
	Model 70 Cal. 270				
	this Rifle arm goes				
	off White Raising Bolt				
	Serial 6808770				
All claims and returned goods MUST be accompanied by this bill					TAX
0032564 Received By					TOTAL

GS-2022
PRINTED IN U.S.A.



Thank You