Remington Arms Co., Inc. Product Service Legal Case #:3137

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

159955 1/26/2009 1/27/2009 1/27/2009

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Charles Stringer 15 Walnut Lane Essex Junction VT 05452 H 802-264-9765 E cjstringer@comcast.net

Incident Information

Claims Codes Repair Medical Medical Status

ΡI

PD Cause:4038 Could Not Duplicate

S Concern Unknown

C Fired when moved from Concern:1007 Fired on Safe Release

Safe to Fire

The firearm malfunctioned during hunting season. The firing pin dented the primer on 5 cartridges, but did not fire. 6th cartridge was inserted and the safety was moved to the fire position the rifle discharged. dmf

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/280 REM
 n/a
 C6247989
 CI
 4/19/1988

Date Where Accessories Original Owner

LEW HORTON TWO PIECE SCOPE BASE, FRT SIGHT

1/23/1989 DIST CO ASSM,FLOOR PLATE AND MAG ASSM

CONCERN:FSR

Ammunition Information

Mfg. Type Cal./Ga. SKU UPC DOM Mfg. Code

Remington SP CL/150 GR 280 REM

Concern Other Factory Reload

0: Y · ·

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Date Date
Settlement APV APV

Repair at 1/2 normal charges as goodwill gesture

Repair/Replacement Repair/Replacement Cost Date

1/30/2009

1/30/09: Could not duplicate concern. Repair and clean at 1/2 normal charges - goodwill gesture. Estimate was mailed to customer. dmf

Examination[Remington/CF/BA]

_				
	Part	Sub-Part	Code	Comment
ΙĒ				

BARBER - Kinzer PPS GAL RE0009158

. PrintDisplay

Page 3 of 3

	Sub-Assembly	M/700 Non-Boit Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE,FRT SIGHT ASSM,FLOOR PLATE AND MAG ASSM

3/37



Factory Repair Form		Return to Previous Page
OTE: Please complete and print this form, and then include	e it with your firearm.	NECEIVE
Model Number: 700	Serial Number: C6247989	UL JAN 29 2009
Are you the original owner?: VES NO		BY:
Name: Charles Stringer	Date of Purchase: 1/23/198	39
Address (no PO Boxes): 15 Walnut Lane		
City: Essex Junction	State: VT	Zip: 05452
Phone (Daytime): 802-264-9765	Fax:	
E-mail Address:(if e-mail address is provided, notificati sent) cjstringer@comcast.net	ion of receipt and shipment will b	e ·
E-mail Address: would like to receive future e-mail updates from R	emington.	
did not fire. When the sixth cartridge was inserted into the a discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the	dition. The misfire situation happene fire position.	ed last year as
discharged. This happened twice. This is a very unsafe con-	fire position.	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left	fire position.	in the boy his the fixeam.
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information:	fire position. Please return used to sh Thu	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington	Type: Soft Point Core Lock	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information:	Type: Soft Point Core Lock	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington	Type: Soft Point Core Lock	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington Other (i.e. bullet weight/type, shot size, powder): 150 gr	Type: Soft Point Core Lock	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington Other (i.e. buillet weight/type, shot size, powder): 150 gr. Handload Information:	Type: Soft Point Core Lock	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington Other (i.e. buillet weight/type, shot size, powder): 150 gr. Handload Information: Powder Used:	Type: Soft Point Core Lock Powder Weight:	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington Other (i.e. buillet weight/type, shot size, powder): 150 gr. Handload Information: Powder Used: Case/Hull Used:	Type: Soft Point Core Lock ain280 caliber Powder Weight: Primer Used:	
discharged. This happened twice. This is a very unsafe conwell, but not the discharge when the safety is moved to the Master Card # Credit Card # redacted 27 characters left Ammunition Information: Manufacturer: Remington Other (i.e. bullet weight/type, shot size, powder): 150 gr. Handload Information: Powder Used: Case/Hull Used: Bullet Type/Shot Size:	Type: Soft Point Core Lock ain280 caliber Powder Weight: Primer Used:	

http://www.remington.com/support/repair_services/factory_repair_form.asp

1/1/2009

How often do you clean the action? (Months or Number of rounds) each time used					
How often do you clean the trigger assembly? (Months or Number of rounds) each time used					
Brand of lubricant used: Rem Oil					
How often do you lubricate the bore? (Months or Number of rounds) each use					
How often do you lubricate the action? (Months or Number of rounds) each use					
How often do you lubricate the trigger assembly? (Months or Number of rounds) each use					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) never serviced					
What were the services performed?) n/a					
NOTE: In order to better service our customers some firearms/parts are sent to a certified Remington Premier Authorized Repair Center. Ship your ENSURED firearm by either UPS or Parcel Post to: Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
700 RE00159955	U FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND				

©2008 Remington Arms Company, Inc. All Rights Reserved. Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Alemaini, dana

suphree TPA, checkover, clear AT 1/2 NORMAL CHARGES.

Other Sites ,

Quote

http://www.remington.com/support/repair_services/factory_repair_form.asp

1/1/2009