

Remington Arms Co., Inc.
Product Service
Legal Case #:2422

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 145795 | 5/23/2008 | 5/23/2008 | 5/23/2008 | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|----------|------------|-----------|--------------|---------|-------|-------|-----|----------------|
| Reporter | | Mitchell | Szajda | 55 York Road | Lebanon | CT | 06249 | | H 860-642-7083 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|--|-------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4006 Altered Adjustments or Components | | Unknown | |
| S | Concern:1007 Fired on Safe Release | | | |
| C | fires on safe release | | | |

5/29/08-correspondence from repair-gun fires by itself when you release safety.lw

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl | DOM |
|----------------|------------------------------|----------------------|----------------|----------|-----|-----------|
| Remington | CF/BA | 700/22-250 REM | 20000 | A6257061 | BI | 1/22/1976 |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | C GREENBLATT HEMPSTEAD LI NY | TWO PIECE SCOPE BASE | U | | | |

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|----------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Replace TA under SMP | | | | | | |
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |

5/29/08-quote sent to replace TA under SMP.lw

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|--------------|-----------------------------------|----------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 5/23/2008 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | F.SUPRY |
| Cause | 4006 | Altered Adjustments or Components | |
| Barrel | Description | | 24" 22-250 REM |
| | Date Code | | BI |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |

| | | | |
|--------------------------|------------------------|----------------------------|---------------------------------|
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Slightly Worn; Functioning | |
| | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | STANDARD M/700 BOLT LOCK SAFETY |
| | Function | Like new; Functioning | |
| Sear | Lift | ---Select--- | .009 |
| | Notch | Like new; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | | False | |
| Trigger | Condition | Slightly Worn; Functioning | |
| | Pull | ---Select--- | 5.5# |
| | Altered | True | SET SCREWS ALTERED |
| | Sub-Assembly | M/700 Bolt Lock | |
| Non-Remington Components | Description | | TWO PIECE SCOPE BASE |

Bolt Lock modification program

General Repair Form

2422


 BT 1/76
 5.5#
 24"
 .009

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

| | | | |
|--|--|--------------------------------|-------------------|
| Model Number: <u>700</u> | | Serial Number: <u>A6257061</u> | |
| Name: <u>MITCHELL SZAJDA</u> | | Date of Purchase: <u>?</u> | |
| Address (no PO Boxes): <u>55 YORK RD</u> | | | |
| City: <u>LEDANON</u> | | State: <u>CT</u> | Zip: <u>06249</u> |
| Phone (Daytime): <u>860 6427083</u> | | Fax: | |
| E-mail Address: | | | |
| Please describe your problem: <u>GUN FIRES BY ITS SELF WHEN YOU</u> <u>RELEASE SAFETY</u> | | | |
| 500 characters left | | | |
| NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time. | | | |
| <p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <ul style="list-style-type: none"> Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. | | | |

 ©2008 Remington Arms Company, Inc. All Rights Reserved.
 Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Websites

Other Sites

Remington.

could not duplicate concern.
 Trig set screws Altered. Replace
 TPA, check over, clean under
 Bolt lock program Roll \$ 20.00
 + S&H.

Quote

Number: **A6257061**Model: **700**

RE00145795