

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2623

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 149341 | 8/20/2008   | 8/21/2008       | 8/21/2008   |               |         |     |          |

## Customer Information

| Type     | Business           | First Name | Last Name | Street          | City     | State | Zip   | Age | Contact                                      |
|----------|--------------------|------------|-----------|-----------------|----------|-------|-------|-----|----------------------------------------------|
| Reporter | Tejas Trading Post |            |           | 2121 W. Hwy 290 | Giddings | TX    | 78942 |     | W 979-542-3885<br>E tejastrading@verizon.net |

## Incident Information

| Claims | Codes                 | Repair Est.                        | Medical Treatment | Medical Status |
|--------|-----------------------|------------------------------------|-------------------|----------------|
| PI     |                       |                                    |                   |                |
| PD     | Cause:4038            | Could Not Duplicate Concern        |                   |                |
| S      | Fired on bolt closing | Concern:1008 Fired on Bolt Closing |                   | Unknown        |
| C      |                       |                                    |                   |                |

Could not get the rifle to malfunction under any of the tests performed. Bolt lock style rifle will be changed to non-bolt lock under the bolt lock modification program fls.

## Firearm Information

| Mfg.           | Type                    | Model/Ga.      | SKU            | Serial | Bbl. | DOM      |
|----------------|-------------------------|----------------|----------------|--------|------|----------|
| Remington      | CF/BA                   | 700/222 REM MA | 20000          | 157644 | PM   | 6/1/1965 |
| Date Purchased | Where Purchased         | Accessories    | Original Owner |        |      |          |
|                | PREC TOOL GUN ITHACA NY |                | U              |        |      |          |

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

| Settlement  | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| BLM Program |                         |                         |               |                 |                |               |
|             | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|             | 65.00                   | 8/21/2008               |               |                 |                |               |

8/21/2008 returned to AS to repair under the bolt lock modification program fls.

Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code | Comment   |
|-------------|--------------|------|-----------|
| Examination | Examiner     |      | B.TRAVIS  |
|             | Exam Date    |      | 8/21/2008 |
|             | Product Type |      | RF        |
|             | Action Type  |      | A         |
|             | Assigned To  |      | F.SUPRY   |

|              |                        |                             |                                   |
|--------------|------------------------|-----------------------------|-----------------------------------|
| Cause        | 4038                   | Could Not Duplicate Concern |                                   |
| Barrel       | Description            |                             | 24" 222 REM MAG                   |
|              | Date Code              |                             | PM                                |
|              | Bore Plugged           | False                       |                                   |
|              | Bulged                 | False                       |                                   |
|              | Fired                  | False                       |                                   |
|              | Fired while Obstructed |                             |                                   |
|              | Muzzle/Crown Condition | ---Select---                |                                   |
| Bolt         | Firing Pin             | Slightly Worn; Functioning  |                                   |
|              | Shroud                 | Slightly Worn; Functioning  |                                   |
|              | Face                   | Slightly Worn; Functioning  |                                   |
|              | Handle                 | Slightly Worn; Functioning  |                                   |
|              | Stop                   | Slightly Worn; Functioning  |                                   |
| Extractor    | Condition              | Slightly Worn; Functioning  |                                   |
|              | Cut Condition          | Slightly Worn; Functioning  |                                   |
|              | Ext/Eject Test         | False                       |                                   |
| Locking      | Block Condition        | ---Select---                |                                   |
|              | Lug Condition          | Slightly Worn; Functioning  |                                   |
|              | Notch Condition        | ---Select---                |                                   |
| Overall      | Exterior Condition     | Slightly Worn; Functioning  |                                   |
|              | Stock Condition        | Slightly Worn; Functioning  |                                   |
|              | Fore End Condition     | ---Select---                |                                   |
| Receiver     | Condition              | Slightly Worn; Functioning  |                                   |
|              | Bulged                 | False                       |                                   |
| Safety       | Description            |                             | STANDARD M/700 BOLT LOCK SAFETY   |
|              | Function               | Like new; Functioning       |                                   |
| Sear         | Lift                   | ---Select---                | .006                              |
|              | Notch                  | Slightly Worn; Functioning  | BLACK GREASE ON SEARCAM           |
|              | Tests                  | Test Fired                  | False                             |
| Feeding Test |                        | False                       |                                   |
| Trigger      | Condition              | Slightly Worn; Functioning  | EXCESSIVE BLACK GREASE ON SEARCAM |
|              | Pull                   | ---Select---                | 3#                                |
|              | Altered                | False                       |                                   |
|              | Sub-Assembly           | M/700 Bolt Lock             |                                   |

**Arms Services Repair & Estimate System**

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

**Repair Inquiry**

Repair Number: **RE00149341** Serial: 157644 Model: 700 Center Fire Caliber: 222 REM. MAG. Produced: 06/17/1970 Repairman: Robert Frink  
 Verify Repair Status: ApprovalHold 8/21/2008 5:59:15 AM

**Address Information**

Customer: Received From: Return To: Received From:

Name: **TEJAS TRADING POST** **TEJAS TRADING POST**

Address 1: **2121 W HWY 290** **2121 W HWY 290**

Address 2: **GIDDINGS** **GIDDINGS** PO Box: **GIDDINGS** PO Box:

City: **GIDDINGS** **GIDDINGS**

State: **TX** Zip Code: **78942** Country: **US** State: **TX** Zip Code: **78942** Country: **US**

FEL **5 74 287 01 11 02016 082011**

| Contact / Condition | Problems   | Estimate | History / Status   | Shipping / Billing     |
|---------------------|------------|----------|--------------------|------------------------|
| Date                | Code       | User ID  | Desc1              | Desc2                  |
| 8/14/2008 6:17:4    | New        | sanguis  | Repair Added       |                        |
| 8/14/2008 12:05     | EmailSent  | ArmEm    | Repair Received    | TEJASTRADING@VERIZON.N |
| 8/14/2008 12:05     | EmailVerit | ArmEm    | Receipt            | TEJASTRADING@VERIZON.N |
| 8/20/2008 6:26:3    | Expedite   | pencer   | From: Check In     | To: Repair Bench       |
| 8/20/2008 1:09:3    | Estimate   | frinkre  | Estimate Update    | Status: Estimating     |
| 8/21/2008 5:59:1    | Estimate   | frinkre  | Estimate Update    | Status: ApprovalHold   |
| 8/21/2008 7:50:5    | Expedite   | pencer   | From: Repair Bench | To: ApproveRack        |

Shipping Hold ☐ InterFace Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ ReturnAs Received ☐ Has been Approved ☐ Internal Repair ☐

Current Status: ApprovalHold 8/21/2008 5:59:15 AM  
 frinkre  
 ApproveRack  
 Repair Location: ILN  
 Current Location: ILN  
 Transfer Number:

Repair Search Refresh Close

suprjvl 8/21/2008 8:32 AM CAPS NUM INS SCRI

start Inbox - Micros... Microsoft Exce... Arms Services... Search for a S... Current Cases... Part Search by... 8:32 AM

Bolt Lock modification Program

# TEJAS TRADING POST

PO BOX 546

LIFE MEMBER

2121 W HWY 290

LIFE MEMBER

NRA

GIDDINGS, TX 78942

TSRA

979-542-3865 TEJASTRADING@VERIZON.NET

GUN LOCK

DATE 8-11-08

Remington Arms Co., Inc.  
Bolt Safety Modification  
14 Hoefler Ave  
Ilion, NY 13357

| QUANTITY | DESCRIPTION             | AMOUNT |
|----------|-------------------------|--------|
|          | Remington 700 BDL       |        |
|          | 222 Rem Mag             |        |
|          | Sn # 157644             |        |
|          | Gun may fire and has    |        |
|          | fired when you close    |        |
|          | the bolt. Please repair |        |
|          | under warranty. Do      |        |
|          | not keep this gun.      |        |
|          | Customer says it is     |        |
|          | a family gun.           |        |
|          | Thanks                  |        |
|          | Bob White               |        |
|          | FFL Attached            |        |

Serial Number:

157644

Model: 700



RE00149341

COULD NOT DUPLICATE CONCERN.  
Replaced TPA, check over, clean  
under bolt lock program  
for \$20.00 + GST

Quote