BARBER - Kinzer PPS GAL RE 0009411

Remington Arms Co., Inc. Product Service Legal Case #:4971

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Obsolete Pre Lit Lit 11/4/2010 1/3/2011 215512 12/19/2010

Customer Information

Zip Business First Name Last Name Street City Type State Age Contact H 518-753-4221 175 Stillwater Bridge Rd. Incident Edwin Batchelder Schaghticoke 12154 W 518-429-1519

Incident Information

Repair Est. **Medical Status** Claims Codes Medical Treatment

PΙ

S

Cause: 4006 Altered Adjustments or Components PD Concern: 1007 Fired on Safe Release

Unknown

C FSR

11/4/10: Customer called in. He stated that he has been looking on the Internet & saw that we had a "recall". He had a FSR while dry firing rifle. df

Firearm Information

Model/Ga. SKU Serial Bbl. DOM Mfg. Type 7/7MM-08 7750760 CT 4/26/1999 Remington CF/BA 24786 Date Original Where Purchased Accessories Owner Purchased

AMCHAR WHOLESALE

U

TWO PIECE SCOPE BASE, BOTTOM HALF OF INC RINGS

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/7/CF/BA

Cash Reim. Date Cash Date Release of Claims Release Date Reimbursement Settlement APV APV Settlement

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

11/4/10: Sending ARS, ltr, form, box. Box order# 1155657. df 1/9/11: Per Ilion - Will follow down. TA rusty & set screws altered. Replace TA, clean & test fire @ 1/2 normal cost - quote. df 1/10/11: I spoke w/cust. He apprvd quote & pd by credit card. df

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|--------------|--------------------------------------|-----------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 1/3/2011 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | T.NAGLE |
| Cause | 4006 | Altered Adjustments or Components | |
| Barrel | Description | | 18.5" 7MM08 REM |
| | Date Code | | СТ |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | | | |

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4971&Type=Case

1/10/2011

BARBER - Kinzer PPS GAL RE 0009412

| } | Fired while Obstructed | | |
|-----------------------------|---------------------------|--------------------------------|---|
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Wom; Functioning | |
| | Shroud | Slightly Wom; Functioning | |
| | Face | Slightly Wom; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| | Condition | Slightly Worn; Functioning | |
| Extractor | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | Select | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | Select | |
| | Exterior Condition | Slightly Worn; Not Functioning | |
| Overall | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | Select | |
| Receiver | Condition | Slightly Worn; Functioning | |
| Receiver | Bulged | False | |
| | Description | | M/7 SAFETY |
| Safety | Function | Like new; Functioning | |
| | Sub-Assembly | Non-ISS | |
| Sear | Lift | Select | N/A |
| | Notch | Slightly Worn; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | Tests | False | |
| Trigger | Condition | Slightly Worn; Not Functioning | RUSTY |
| | Pull | Select | N/A |
| | Altered | True | SET SCREWS ALTERED, SEAR ENGAGEMENT TO FAR IN |
| | Sub-Assembly | Other Remington | |
| Non-Remington Components | Description | | TWO PIECE SCOPE BASE, BOTTOM HALF OF RINGS |

Remington.

18.5

4971

November 4, 2010

Edwin Batchelder 175 Stillwater Bridge Rd. Schaghticoke, NY 12154 Ph: 518-753-4221

Ref: #4971

Dear Mr. Batchelder,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

DECERVED JAN 0 5 2011

BY:----

enclosure

7750760 Model: 7 RE00215512 will follow down. T.A. Musty at set screws Altered. Ryphice TOA, clean & Test Rine At 1/2 Normal with

Quote

Remington Arms Company, Inc. ◆ 870 Remington Drive ◆ P.O. Box 700 ◆ Madison, NC 27025 Phone 800-243-9700 ◆ www.remington.com

| Model Number: | Serial Number: | | | | |
|---|----------------|-------------------|--|--|--|
| MODEL SEVEN 7MMO8 | 7750760 | | | | |
| Name: Edwin BATCHELDER | | Date of Purchase: | | | |
| Address (no P | | 78 | | | |
| Address (no PO Boxes): | | | | | |
| 175 Stillwater Bridge City: Schaglacoke | State: | Zip: 17 154 | | | |
| Phone (Daytime): 5/8 429 15/9 | Fax: | , | | | |
| E-mail Address: | | | | | |
| Please describe y | our problem: | | | | |
| FIREING PIN ENGAGES as soon AS SAFETY is in off Position. | | | | | |
| | | | | | |
| 500 characters left | | | | | |
| NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time. | | | | | |
| WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) | | | | | |
| Remove all accessories from your firearm to prevent loss or damage. Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. | | | | | |
| Print | Reset | | | | |



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

| DATE: | | 11/4/2010 | REQUESTED BY: | Dell |
|--|--------------------|--------------------------|---------------|-------|
| QUANTITY: 1 | | WEIGHT PER PACKAI 10 lbs | | |
| PLEASECHECKONE MEDIA COORDINATOR TO MAIL | | | | XXXXX |
| DESCRIPTION: | Ref# 4971 Rifle | | | |

LABEL INFORMATION

MAIL LABEL TO: Edwin Batchelder
175 Stillwater Bridge Rd.
Schaghticoke, NY 12154
Ph: 518-753-4221

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

RPILEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

```
AXX596 NOV 4, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
FRHCKINGH 124XX5969065849046
REF 1:EDWIN BATCHELDER/CD/DMF
REF 2:4971/RIFLE

HANDLING CHARGE 0.00
STNGLE-PIECE PUB RATE CHRCS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DC 0.00 DG 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 7.24
```







