

Remington Arms Co., Inc.
Product Service
Legal Case #:5003

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
211865/215592/216414	11/30/2010	11/8/2010	12/2/2010	11/7/2010			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Randy	Vondal	608 Mountain Ae	Walhalla	ND	58282		H 701-549-3609
Incident		Tyler	Vondale						

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when safety released	Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release		Unknown
C				

11/8/10 Per call from Randy, his daughter had her Model 7 out yesterday and when she went to take the safety off it fired without her touching the trigger. Mr. Vondale bought another Model 7 for his other daughter and has 3 700's that have the Walker trigger. He wants to send them all for inspection. He may not send all at one time.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	7/260 REM	24781	7758598		1/10/2000
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILL HICKS & CO LTD		Y			

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	7/	20000	7758503		
Date Purchased	Where Purchased	Accessories	Original Owner			
			Y			

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	20000	6308060	AT	3/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner			
	GAMBLE SKOGMO MINN MINN TWO PIECE SCOPE BASE		U			

CONCERN:FSR

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	7/260 REM	24781	7758083	BU	1/10/2000
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILL HICKS & CO LTD		U			

CONCERN:FSR

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	25933	S6319870	CR	4/18/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	CRAIG * WALTER INC.	STK AMMO BOOT	U			

CONCERN:FSR

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5003&Type=Case>

1/14/2011

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/7/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, install new TPA no charge as goodwill	Repair/Replacement Cost	Repair/Replacement Date				
	230.83	12/2/2010				

11/8/10 Mailing 5 ARS labels.cm 12/2/10 Per Ilion, could not duplicate concern. Excessive oil in trigger assm. Install new trig assm no charge as gesture of goodwill. Spoke with Randy's son-in-law about the inspection and repair and to let him know it has shipped.cm 1/5/11 Vondal approved repair charges for repair 215592 on 1/4/11.cm 1/10/11 Repair # 216414, will follow down. Trigger and pin rusty. Replace TPA, clean, test at no charge. Repair # 215685, could not duplicate concern, trigger assm set screws altered. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm 1/14/11 Vondal was not happy with the charges. He agreed to pay the shipping and test charges at full price and I would take off the charge for the trigger.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		supry
	Exam Date		11/30/2010
	Product Type		RF
	Action Type		A
	Assigned To		Supry
Cause	4038	Could Not Duplicate Concern	Could not duplicate concern, the trigger pull seemed a little heavy and the initial movemnet of the safe arm was hard.
Barrel	Description		20 inch Model 7 260 caliber
	Date Code		
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
		Slightly Worn;	

	Stop	Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	True	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		Model 7
	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	not measured
	Notch	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	Excess oil noted under receiver and on trigger housing.
Pull	Trigger	---Select---	5.75 lbs
Altered		False	
Sub-Assembly		M/700 Non-Bolt Lock	

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/28/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	I HAVE THE PHOTOS IN A SEPERATE FOLDER
	Description		22" 243 WIN
	Date Code		AT
	Bore Plugged	False	

Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	HAVE PHOTOS FOR R#216414 IN SEPARATE FOLDER
Barrel	Description		20" 260 REM
	Date Code		BU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/7 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Tests	Test Fired	False	
	Feeding Test	False	
	Condition	Like new; Not	TRIG AND PIN RUSTY

Trigger		Functioning	
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	Other Remington	

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	PHOTOS IN SEPARATE FOLDER
Barrel	Description		24" 7MM REM MAG SS
	Date Code		CR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/700 SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.013
	Notch	Like new; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
	Condition	Slightly Worn; Functioning	

Trigger	Pull	---Select---	3.5#
	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		STK AMMO BOOT





