BARBER - Kinzer PPS GAL RE 0009591 Remington Arms Co., Inc.

Product Service Legal Case #:5372

Case Information

Incident Date RE# Date Opened Date Opened(PS) **Date Closed** Pre Lit Lit Obsolete 215744 12/21/2010 12/9/2010 1/4/2011 X

Customer Information

First Last **Business** Street State Zip Age Contact Type Name Name

W 337-706-1818

Kraft Gatz Lan Incident Benjamin LLC

Jamison

600 Jefferson St, Ste 410

Lafayette LA 70501

F 337-706-1828 E

wkj@kgdlawllc.com

Incident Information

Medical Medical Claims Codes Repair Est. Treatment Status

PΙ

Cause: 4038 Could Not Duplicate Concern PD

Concern:1005 Unexplained Discharge Safe discharged with safety

Walter K

Ш

Unknown

on

C

12/9/10 Per an email sent to Remington.com, incid #101129-000056, "I have a model 600 which I acquired in early 70s. I put it in storage after the firearm discharged with the safety on. I now desire to sue it again and I see there was a recall and I need to know if there is a local gun smith that can perform the recommended repairs."cm

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 600/308 WIN SKU n/a

Serial Bbl.

DOM 56801 RM 11/1/1965

Date Purchased

Where Purchased

Accessories SCOPE BASE, SLING

Original Owner

U

CONCERN:FSO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/600/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Cash Date Date

APV

APV

Per Ilion, replace TPA, clean, test fire at no charge

Repair/Replacement Repair/Replacement

Cost

Date

60.06

1/12/2011

12/9/10 Mailing ARS.cm 1/12/11 Per Ilion, could not duplicate concern. Old style trigger has not been updated. Replace TPA, clean and test fire under trigger recall at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5372&Type=Case


1/12/2011

PrintDisplay	COAL DE ACCOSO		Page 2 of
BARBER - Kinzer PP	Examiner		B.TRAVIS
Examination	Exam Date		1/4/2011
	Product Type	Ī .	RF
	Action Type	7	A
	Assigned To	Ħ	T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		18.5" 308 WIN
Barrel	Date Code	i	RM
	Bore Plugged	False	
	Bulged	False	╡
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	7
	Firing Pin	Slightly Worn; Functioning	Ħ
	Shroud	Slightly Worn; Functioning	7
Bolt	Face	Slightly Worn; Functioning	7
	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	7
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	7
	Ext/Eject Test	False	i
	Block Condition	Select	=
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	<u> </u>
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/600 SAFETY
Safety	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	O/S DOUBLE
	Tests	Test Fired	False
Feeding Test	10313	False	
	Condition	Slightly Worn; Functioning	DIRTY,RUSTY O/S
Гrigger	Pul1	Select	3.5#
1115501	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description	_	SCOPE BASE, SLING

BARBER - Kinzer PPS GAL RE 0009593

Remingion.

18.5" RM 1/6"



Walter K. Jamison, III Kraft Gatz Lane Benjamin LLC 600 Jefferson Street, Suite 410 Lafayette, LA 70501

Subject: #5372, Model 600

Dear Mr. Jamison,

27 15 18.06

Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
christy.mitchell@remington.com

JAN 0 5 2011 | BY:

56801 Model: 600 RE00215744 could not diplicate concern.

0/5 TRig. has not been updated

Up her TPA, cleanextest fine

under TAR AT N/C

230145

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 ● www.remington.com ZON

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 600	Serial Number: 568
Are you the original owner?: YES NO	
Name: Walter Jamison	Date of Purchase:
Address (no PO Boxes): 600 Jeffers on	St # 410 to fauth LA 9050
city: Lotagette	State: 14 Zip: 7050/
Phone (Daytime): 3377061977	Fax:
E-mail Address: (if e-mail address is provided, notification sent) Comparison	of receipt and shipment will be
I would like to receive future e-mail updates from Ren	nington.
Please describe your problem and date of occurrence:	
Will discharge when	
sofety us on.	
500 characters left	3
Ammunition Information:	
Manufacturer:	Type:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

5372



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	8-Dec REQUESTED	BY: christy	
QUANTITY:	1 WEIGHT PER	PACKAGE:	10
PLEASE OFFERKONES	•		
MEDIA	1		
COORDINATOR	ľ	xx	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
	600		

LABEL INFORMATION

MAIL LABEL TO:	Walter K. Jamison, III Kraft Gatz Lane Benjamin LLC 600 Jefferson Street, Suite 410 Lafayette, LA 70501	
RETURN ITEM TO	: Rem Prod Serv	

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

AXX596 DEC 9, 2010 ALL CURR USD 1 OF 1
SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969065561436
REF 1:WALTER K JAMISON/KRAFT/CD/CM
REF 2:600

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.45 PUB+HANDLING 9.45

