BARBER - Kinzer PPS GAL RE 0009716
Remington Arms Co., Inc.

Product Service

Legal Case #:4930

Case Information

RE# Date Opened(PS) **Date Closed Date Opened Incident Date** Pre Lit Lit Obsolete 11/23/2010

11/18/2010 210847

11/2/2010 10/30/2010

Customer Information

Type **Business** First Name **Last Name** Street State Contact City Zip Age

Incident

Robert Archibald 1318 N. 400 East Nephi UT 84648

C 801-573-9110

Incident Information

Repair Medical Medical Claims Codes Est. **Treatment** Status

PI

PD Altered Adjustments or Cause:4006

Fired when setting the S

Components

Unknown

safety

Concern: 1006 Unexplained Discharge Safe OFF

C

11/2/10 Per call from Archibald, he was shooting his 700 on Saturday and he had cocked the gun and as he set the safety it discharged. He says that when it fired it put a hole in his son's Suburban. He says he bought this rifle new a few years ago.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

700/22-250 **REM**

27353

G6470124 LZ

2/10/2005 4:22:25 PM

Date Pürchased

Where Purchased

Accessories

Original Owner

12/1/2008

ACUSPORT (MT) CORPORATION

He believes he bought it new a few yrs ago and is the original owner. CONCERN:MISFIRES

Ammunition Information Mfg.

Type CL/45 Cal./Ga. 22-250

SKU

UPC

DOM

Mfg. Code

Remington Concern 0:

Other

Factory Y

Reload N

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Cash Date APV

Date APV

Replace TPA, clean, ship at 1/2 normal charges

> Repair/Replacement Cost

Repair/Replacement Date

11/2/10 Told him that we would pay shipping and do inspection for free then contact him with the results.cm 11/3/10: Customer called back & wants a box. Box order# 1155165. df 11/23/10 Called Archibald and gave him condition of trigger. Quoted 1/2 price for trigger, shipping, test, totaling \$75.50. He approved. He said that he had adjusted the trigger. He asked that we adjust this new one down to lowest factory specs before sending.cm


http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4930&Type=Case

11/23/2010

PrintDisplay Page 2 of 2

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/19/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		24" 22-250 REM
	Date Code	1	LZ
	Bore Plugged	False	
Barrel	Bulged	False	=
	Fired	False	
,	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	_
	Shroud	Slightly Worn; Functioning	=
Bolt	Face	Slightly Worn; Functioning	_
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	Ħ
Ü	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	=
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
•	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Like new; Functioning	
- Jui		Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Not Functioning	TRIG WILL NOT RETURN
	Pull	Select	2#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	



47.00 17.5hp-11.50 test 75.50

NOV 2 2 2010 BY:---- 4930

24"
122/0
2^{*}
2013

November 2, 2010

Robert Archibald 1318 N. 400 East Nephi, UT 84648

Subject: #4930, Model 700

Dear Mr. Archibald,

Per our phone conversation, enclosed is a prepaid UPS ground shipping label for shipment of the firearm to our factory for inspection. Please include a copy of the attached letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry". I will contact you after inspection with the results.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700	Serial Number: 46470124				
Are you the original owner?: YES NO					
Name: Robert Auchibald	Date of Purchase: 12-08				
Address (no PO Boxes): 13/8 N 400	E				
city: NEPHI	State: WT Zip: 84648				
Phone (Daytime): 801-573-9110	Fax:				
E-mail Address: (if e-mail address is provided, notification sent) archiebs@ MSN. Cow					
E-mail Address:					
I would like to receive future e-mail updates from Ren	nington.				
Please describe your problem and date of occurrence:					
Misfires causing DAM	Age to Shrburshn				
FLOOR BOARD-					
	. ·				
	Ħ				
500 Characters left					
Ammunition Information:					
Manufacturer: Remington	Type: Covelok:				
Other (i.e. bullet weight/type, shot size, powder): 45	9+4in - 22.250				
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:					
	Primer Used: 1				



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/2/2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKA	GE:	10
NGX8E @HE®K®NE			
MEDIA			
COORDINATOR	·	XX	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
	700		
	66470124		

LABEL INFORMATION

MAIL LABEL TO:	Robert Archibald 1318 N. 400 East Nephi, UT 84648
RETURN ITEM TO:	Rem Product Service

PLEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 SVC GNDCOM			2010 ACT	ut :	ALL 10.0	CURR LBS	USD	1 01	=
TRACKINGH 1Z	4XX59	690	66027	048					
REF 1:ROBERT	ARCH	180	ALD/CD	/CM					
REF 2:700/66	47012	4							
HANDLING CHAP	RGE 0	.00)						
SINGLE-PIECE PUB RATE CHRGS:							SVC	T/P USD	
DV 0.00			COD	(A)	Ûď		RS	0.59	
DC 0.00			DGD	0.	ØØ		SD	C.00	
AH 0.00			PR	0.	9 9		SP	0.00	
TOT DUE CHO	11 70	ŧ		Pull	3+H:A	HDL1N	G	11 79	

