7_

Remington Arms Co., Inc.
Product Service
Legal Case #:5010

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

211402 11/23/2010 11/8/2010 11/24/2010

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Nick Deplaces 6019 12th Ave North Grandville ND 58741 H 701-728-6376

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

ΡI

PD Cause: 4006 Altered Adjustments or

Fired on Safety Components Unknown

S Release Concern: 1007 Fired on Safe Release

C

11/8/10 Per call from Deplazes, he has a 700 left-hand rifle that he bought second hand that has fired when the safety was released.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/30-06 SPR
 n/a
 A6352356
 DI
 9/15/1976

Date Purchased Where Purchased Accessories Original Owner

BERNS WHLSE DENVER CO

N

CONCERN:FSR

CONCERT: SIC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Settlement APV APV

Per Ilion, replace TPA, clean at BLSM program price

Repair/Replacement Cost Repair/Replacement Date

Jost Dat

30.23 11/29/2010

11/8/10 Mailing ARS.cm 11/29/10 Per Ilion, will follow down, no trigger return. Trigger set screws atered. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping. Nick approved by phone call.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		11/24/2010
Lxammation	Product Type		RF

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5010&Type=Case

11/30/2010

Α.	
√	

	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description]	22" 30-06 SPR
	Date Code]	DI
	Bore Plugged	False	
Barrel	Bulged	False	
Darrei	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description]	STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN.NO TRIG RETURN
Trigger	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Add Repair Estimate F	epair Expedite Repair Inq	quiry Repair Tools CSR T	Tools Reports Table Maintenan	ce System Loc	ation		
	••						
				5 Er! 24			
	frmREInquiry - Rep		<u> </u>	2+ 55 t#2	<u>X</u> ELE:		
	Repair Number RE00211402	Serial A6352356 Model 700 3006 SPRG L/H Produced: 0	09/15/1976 SKU: 20000	2007	okoronjistnike <u>p</u>		
	Verify Repair ADDRESS INFORMATION		Status	Repairing 11/24/2010 1	1:24:49 AM		
	Customer	 46699 * 1100(46.080s) 46 6 46.00 700 10 m. 	ceived from Return To	C Rec	eved from		
	Name NICK DEPLAZES Address 1: 6019 12TH AVE N	5 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NICK DEPLAZES 5019 12TH AVE NORTH		-::::::::::::::::::::::::::::::::::::::	W. Asia	<u>.</u>
	Addless 2	PO Box		PO Box		NA.	b
	City: GRANVILLE State: ND Zip Code:	: 58741 Country US	GRANVILLE ND Zip Code 50741	Country	-100		
		Name and the second		'''' '''''''			
	Contact / Condition Problems E	stimate History / Status Shipping	g / Billing			W i	
	Date Code	User ID Desc1	Desc2 🛣 🎵 Shipping Hold	Current S Repa			
	11/23/2010 12 EmailSent	ArmEmail Repair Received 1 ArmEmail Receipt	DLPLAG Interface Hold DLPLAG Estimate Sent	1.00			hay the solid
	11/24/2010 11 Maint	Travisbw Repair Maintenanc	F Barb	a Repair	Bench		Year sell
	11/24/2010 11 Updale	williamsed Address, Billing, or	Ship M. from App Felum as Rec	Alori		1. 4 S. C.	
	11/24/2010 11 Comment	williamscd CONSUMER CALL	LEO T SURE W Has Been App.	A STATE OF THE PARTY OF THE PAR		7 T	1
Sec. 1			Exclude TATC	0.57499786465 12.576674 2.665765			
1.50	Repair Search			🚁 🔌 Refresh	Close	A.	
					27 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1		<i>.</i>
			n energy N.S.				•
	The state of the s				, d		* .
				A STATE OF THE PARTY OF THE PAR			
			e man in musi include a state of the second side.	1000			
							1
•		W.H. F.	医巨斑囊斑				
		Y SWAN	•				
supryfi - ILN/Prod	frmREInquir	Pentencia con appartant	D1102R7XPIL	AND SHAPE THE SECOND PROPERTY.	inesday, Nov 24 2010	9:59 ÁM	

Trig. N/c Ship. #17.00 Labor \$20 Test \$N/c

1/29/10 Epailed quote/inspection to him.

NECEIVE Nov 2 9 2010 By: 5010

722" DI9/76 3.5#

November 8, 2010

Nick Deplazes 6019 12th Ave North Granville, ND 58741

Subject: #5010, Model 700

Dear Mr. Deplazes,

Per our conversation, enclosed is the prepaid UPS ground shipping label for shipment of the firearm to our factory for inspection. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



Will follow down, Noticy heturn, T.A. set screws altered. Typhice TOP, clear etcs+ fine under BCP fon \$20.00 + Sup

Quote

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 ● www.remington.com



NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 LH	Serial Number: A 635 2 3 5 6
Are you the original owner?: YES (NO)	
Name: NICK DEPLAZES 0	Date of Purchase: . G -10-10
Address (no PO Boxes): 60/3 /2 AV [v
City: GRANVICKE	State: NO Zip: 5874/
Phone (Daytime): 70/ 728 637 C	Fax:
E-mail Address: (if e-mail address is provided, notification sent)	
E-mail Address: DEPCA @ 5RT. C	
Please describe your problem and date of occurrence: RIFICE FIRED WACH S NOV-5-2010	Afety moved jusiks
500 characters left	
Ammunition Information:	
Manufacturer: Federal	Type: PUWER 5 WOK
Other (i.e. bullet weight/type, shot size, powder):	0 C/R
	-1
Handload Information:	
Powder Used: 4064	Powder Weight: 5 /
Case/Hull Used: w, nCh 15TeR	Primer Used: CC/
Bullet Type/Shot Size: 150 SPITZER	Reloader Used: RCB5

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/8/2010 REQUEST	TED BY: christy	
QUANTITY: 1	WEIGHT	PER PACKAGE:	10
PLEASE GHEOKONE:			
MEDIA			
COORDINATOR		xxxxxx	
TO MAIL	I WILL MA	AIL	
DESCRIPTION:			
	700		
A6352356			

LABEL INFORMATION

MAIL LABEL TO:	Nick Deplazes 6019 12th Ave North Granville, ND 58741	
RETURN ITEM TO	: Rem Product Service	

ARMEASE COMPRESEAULPARTIS CORTHIS FORM: AND SEND TO THE MEDIA COORDINATION

4XX596 N SVC GNDGOM TRACKINGH 1Z4X REF 1:NICK DEP REF 2:700/A635	LAZES/	ACT 667090	JT 10.0	CURR USD LBS	ı GF	1
HANDLING CHARC SINGLE-PIECE F DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 9	SUB RAI	E CHRO COD DGD PR	0:00 0:00 0:00 0:00 PUB+HA	RS SD SP	1/P USD 0.50 0.00 0.00 0.45	





