

BARBER - Kinzer PPS GAL RE 0010588

Remington Arms Co., Inc.

Product Service

Legal Case #:4986

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
209129	11/3/2010	11/5/2010	11/5/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Rodney	Earnhardt	3413 Holt Circle	Pensacola	FL	32526		H 850-380-5112 E rmc4@cox.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	possible to fire on safety release	Cause:4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release		Unknown
C				

PI

PD

S possible to fire on safety release

Cause:4006 Altered Adjustments or Components

Concern:1007 Fired on Safe Release

Unknown

C

11/15/10 Per note with firearm, "It is possible that the firearm will fire by merely going from safety "on" to the "fire" position without pulling the trigger."cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	6714375	LY	2/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	MERCANTIL SALES CO ST LOUIS MO	TWO PIECE SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean at BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
30.23	11/15/2010

11/15/10 Per Ilion, will follow down, trig set screws altered. Trig assm very dirty & sticky. Check over, replace TPA, clean and test fire under bolt lock program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/5/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 308 WIN
	Date Code		LY
	Bore Plugged	False	
	Bulged	False	

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4986&Type=Case>

11/15/2010

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	TRIGGER WILL NOT PROPERLY RETURN
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	
	Pull	---Select---	5.5#
	Altered	True	SET SCREWS ALTERED DIRTY/STICKY
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

frmRepairMain - FGI Repairs

File

Add Repair

Estimate Repair

Expedite Repair

Inquiry

Repair Tools

CSR Tools

Reports

Table Maintenance

System

frmREInquiry - Repair Inquiry

Repair Number: RE00209129

Serial: 6714975 Model 700, Center Fire Caliber: 308

Reparman: Charles Swenson

Status: ApprovaHold 11/5/2010 12:55:18 PM

Verify Repair

Customer

Received from

Return To

Received from

Name: RODNEY EARNHARDT

Address 1: 3413 HOLT CIRCLE

Address 2: PO Box

City: PENSACOLA

State: FL Zip Code: 32526 Country: US

Name: RODNEY EARNHARDT

Address 1: 3413 HOLT CIRCLE

Address 2: PO Box

City: PENSACOLA

State: FL Zip Code: 32526 Country: US

FFL:

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

Date	Code	User ID	Desc1	Desc2	Status
11/5/2010 12...	Estimate	swansonch	Estimate Update		Status: A
11/5/2010 12...	ApprovaH...	System	Immediate SAP Allocation		
11/5/2010 1:0...	Estimate	swansonch	Estimate Update		Status: A
11/5/2010 1:2...	Expedite	pencelr	From: Repair Bench	To: Appl	
11/5/2010 3:3...	ApprovaH...	BatchJob	Quotation Control		

☐ Shipping Hold
 ☐ Interface Hold
 ☒ Estimate Sent
 ☐ Parts Received
 ☐ Passed Inspection
 ☐ Returns Received
 ☐ Has Been Approved
 ☐ Internal Repair
 ☐ Exclude TATC

Current Status

ApprovaHold

11/5/2010 12:55:18 PM

swansonch

ApprovaHeld

Repair Location

ILN

Current Location

ILN

Transfer Number

Repair Search

Refresh

Close

supryfl: ILN/Prod

frmREInquiry

D:102R7XPIL

Wednesday, Nov 3 2010

1:25 PM

start

ODS Desktop

frmRepairMain

DISK DRIVE

Microsoft

3:53 PM

RECEIVED
NOV - 3 2010

BY:.....

BARBER - Kinzer PPS GAL RE 0010590

PS 12478

Model Number: 700		Serial Number: 6714375	
Name: Rodney Earnhardt		Date of Purchase: 1984 (e)	
Address (no PO Boxes): 3413 Holt Circle			
City: Pensacola	State: FL	Zip: 32526	
Phone (Daytime): (850)380-5112		Fax: N/A	
E-mail Address: rme4@cox.net			
<p>Please describe your problem:</p> <p>Safety modification program to remove the bolt-lock mechanism. It is possible that the firearm will fire by merely going from safety "on" to the "fire" position without pulling the trigger!</p>			
309 characters left			

22"
44 2/3"
5.5"
.001

Number: 6714375
Model: 700



RE00209129

contact the Repair Center for services provided and repair time.

IT SHELLS IN YOUR FIREARM OR IN THE VIOLATION OF FEDERAL LAW. IF YOU PLEASE SEND THEM IN A SEPARATE BOX (WITH ZIP CODE), TELEPHONE AND NUMBER OF YOUR FIREARM.

your firearm before sending it. to further damage in shipping and handling. ship in a box(es) may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset

will follow down.
Trig. set screws altered
Trig. Assm very dirty & sticky.
check over, replace TPA, clean
& test fire under bolt lock
program for 20.00

Quote