R - Kinzer PPS GAL RE 0010665

Remington Arms Co., Inc. **Product Service** Legal Case #:5013

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 210813 11/18/2010 11/8/2010 11/19/2010

2807 Irvington Dr Pearland TX 77584

Customer Information

Type Business First Name Last Name Street City State Zip Age

Contact H 713-917-9728 E kfaseler@mhinc.com

Incident Information

Claims Codes

Keith

Repair Est. Medical Treatment Medical Status

PΓ

Incident

PD Fired on safety

Cause:4038 Could Not Duplicate Concern

S release Concern: 1007 Fired on Safe Release

Faseler

Unknown

11/8/10 Per call from Faseler, he bought his 700 BDL 2nd hand 10 years ago and had if fire on safety release this weekend. He was able to do it three times afterward but it does not now.cm

Firearm Information

Mfg. Remington Type

Model/Ga.

SKU

Serial Bbl. DOM

Date

CF/BA

700/270 WIN

n/a Original C6433014 WJ 8/31/1989

Purchased

Where Purchased

Accessories

Owner

ARKANSAS IMPORT & DISTRIB. CO.

SCOPE, RINGS, BASE

N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date APV

Cash Date APV

Per Ilion, replace TPA, clean at 1/2 normal charges

> Repair/Replacement Cost

Repair/Replacement Date

11/8/10 Emailing letter and ARS.cm 11/22/10 Per Ilion, could not duplicate concern. Trig assm very dirty and rusty. Parts working sluggish. Can offer to replace TPA, clean and test fire at 1/2 normal charges. Emailed quote to Faseler.cm 11/23/10 Spoke with Faseler by phone, explained condition. I agreed to remove the shipping as goodwill and he will pay the remaining. He said he had not adjusted trigger but he bought it 2nd hand. Emailed picture of trigger and info on how to clean and oil as well as link to online owner's manual.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5013&Type=Case


11/23/2010

, ,	Exam Date	j	11/19/2010
Examination	Product Type	ĺ	RF
	Action Type		A
	Assigned To	,]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	-
	Description		22" 270 WIN
	Date Code	ĺ	WJ
	Bore Plugged	False	·
	Bulged	False	<u> </u>
Barrel	Fired	False	<u> </u>
	Fired while Obstructed		_
	Muzzle/Crown	Slightly Worn;	٦
	Condition	Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	_
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACTION VERY DIRTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A (SCOPED)
	Notch	Slightly Worn;	
	INOICH	Functioning	
	Tests	Test Fired	False
Feeding Test		False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5013&Type=Case

11/23/2010

	Condition	Slightly Worn; Functioning	VERY DIRTY,RUSTY
	Pull	Select	5#
	Altered	III FIIE	SEALANT REMOVED,PULL SCREW ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE



BARBER - Kinzer PPS GAL RE 0010668

72" VUS 8/89 5th

5013

November 8, 2010

Keith Faseler 2807 Irvington Dr Pearland, TX 77584

Subject: #5013, Model 700

Dear Mr. Faseler,

Per our phone conversation, you should receive an email with your prepaid UPS ground shipping label for shipment of the firearm to our factory within the next 24-48 business hours. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

C6433014 Model: 700 RE00210813 could not suplicate concern.

Titio. 455m very dirty+ musty.

parts working sluggish, can

often to replace TPA, clean +

restfice at 1/2 worms!

changes

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com Remington.
www.remington.com

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

B

ARS LABEL REQUEST FORM

DATE:	11/8/2010			christy
QUANTITY:	1	WEIGHT	DED DVCAVCE	
PLEASE OHEOK ONE		T		
MEDIA	Email to him at:	[
COORDINATOR	kfaseler@mhinc.com	}		
TO MAIL		I WILL	,	
DESCRIPTION:				A
	700		1	<i>-</i>
			1	(N) /
			√	
			kfaseler@mhi	nc.com

LABEL INFO

MAIL LABEL TO:	Keith Faseler 2807 Irvington Dr Pearland, TX 77584	 4XX596 NOV 9, 2010 ALL CURR USD 1 OF SYC GNOCOM TRACKING: 1Z4XX5969066169976 REF 1:KEITH FASELER/CD/CM REF 2:700
RETURN ITEM TO:	Email to him at: kfaseler@mhinc.com Rem Product Service	HANDLING CHARGE 0 00 SINGLE-PIECE PUB RATE CHRES: SVC T/P USD DV 0.00 COD 0.00 RS 1.00 DC 0.00 DCD 0.00 SD 0.00 AH 0.00 PR 0 00 SP 0.00 TOT PUB CHG 11 04 PUB-HANDLING 11 04

PLEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION



