Remington Arms Co., Inc. Product Service Legal Case #:5197

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 211399
 11/23/2010
 11/24/2010
 12/10/2010

Customer Information

City **Business** Type **First Name** Last Name Street State Zip Contact 373 North Willowbrook W 517-279-2900 Reporter Gander Mtn. Gander Mtn. Coldwater MI 49036

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4038 Could Not Duplicate Concern

Unknown

S C Fired on bolt closing

Dealer wrote in a note that customer is having issues with firearm discharging while unloading. df

Concern: 1008 Fired on Bolt Closing

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/270 WIN
 n/a
 A6888773
 KA 5/8/1980

Date Purchased Where Purchased Accessories Original Owner

SPORTS SOUTH SHREVEPORT LA SCOPE BASE AND RINGS U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Settlement Date APV Cash Date APV

Repair @ n/c goodwill gesture

Repair/Replacement Cost Repair/Replacement Date

\$76.60

12/10/2010

Per Ilion - Could not duplicate concern. TA dirty & sticky, replace TA clean & test fire under BLM program - quote. df 12/10/10: Anne Harper sent an email stated that Gander Mtn contacted her & cusotmer does not want to pay \$37 to replace TA on 30 yr old gun. I offered to remove charges as gesture of goodwill. I'm waiting to hear back from Gander Mtn. df 12/10/10: Roy Christensen @ Gander Mtn stated that the customer would apprv. repair if we removed the charges. I have done that & apprvd repair as requested. df

Examination[Remington/CF/BA]

Part Sub-Part		Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		11/24/2010	
	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4038	Could Not Duplicate Concern		
Barrel	Description		22" 270 WIN	
	Date Code		KA	
	Bore Plugged	False		
	Bulged	False		
	Fired	False		
	Fired while Obstructed		-	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5197&Type=Case

12/10/2010

1	Muzzle/Crown Condition	Slightly Worn; Functioning	٦
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	=
Bolt	Face	Slightly Worn; Functioning	=
Doi:	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	STICKS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	-
Litta Goto.	Ext/Eject Test	False	
	Block Condition	Select	
 Locking	Lug Condition	Slightly Worn; Functioning	i
	Notch Condition	Select	j .
	Exterior Condition	Slightly Worn; Functioning	-
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	<u> </u>
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning]
·	Sub-Assembly	Non-ISS	<u> </u>
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	SOME LITE RUST, STICKY
Trioner	Pull	Select	7.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE AND RINGS

		Reports Table Maintenance System Lo	cation	
		A Committee of the Comm		
•				
	EfrmREInquiry - Repair Inquiry			
	Repai Number: RE00211399 Serial A5888773 Model 700 Cents WIN/LEFT HAND Produced 15/18	s: Fire: Caliber: 270 Reparman		
, section of	Verily Repair PEADDHESS INFORMATION	Status: Repairing 11/24/2011	117:22:05 AM	in .
	Custamer	<u> </u>	eceived from	
	Name: GANDER MOUNTAIN Address 1 ATTN CINDY KILBRIDE	GANDER MOUNTAIN 373 NORTH WILLOWBROOK		
	Address 2: 180 E 5TH ST. SUITE 1300 PO Box	PO Box		
	Cey SAINT PAUL State MN Zip Code: \$5101 Country US	COLDWATER MI Zip Code: 49036 County US		
	A PARTIE DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DEL CONTRACTION DE LA C	Warrage		
	Contact / Condition Problems Estimate History / Status Shipping / Billin	g		
		Desc2 T Shapping Hold Current	Status paing	
3 (11/23/2010 TL. New Icpateff Repair Added	Interface Hold: 11/24/201	0.11:22:05.AMI patell	
	11/24/2010 11 Maint Travisbw Repair Maintenance	Parts Received Rep	# Bench coation	
		- Case of the County of the Co	LN Location	
		I Has Been Approved	LN Number	
		Exclude TATC	A township to the	
	Repair Search	Refres	h Close	1
	Anna Maria Maria			
. 18			Egy	
				pr
		Control of the Contro	A CONTRACTOR OF THE PARTY OF TH	
		non de Maria marante de la comercia	and the same and	

	ZC	15	<u> </u>	.₩7 <u>1</u> 2013	
	MOV	C	9	2013	
В	Y:				



Service Request

Service Order # 2843

22" KAS/8 7.5[±]

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357 Attn: repair dept

Date Shipped: 11/15/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-38-023-62-00-00000

Attn: Gun Parts Dept. 373 North Willowbrook Coldwater, MI 49036

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type: Rifle

Serial Number: A6888773

Model:

700LH

Cal/Ga.: 270

Cased?:

DESCRIPTION OF ITEM RETURNED:

700LH

REASON FOR RETURN:

customer is having issues with firearm discharging while unloading

ATTENTION VENDOR

Please contact me with any questions or concerns.

Jesse Grauman (517) 279-2900

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain

Attn: Cindy Kilbride

180 E. Fifth Street Suite 1300

St. Paul, MN 55101

could not duplinate concern.

T.A. Dinty + Sticky, Replace TPA,

Clean + test fine anden 36P

Ron & 20.00 + Ship

Quole

A6888773

RF00211399





