Remington Arms Co., Inc. **Product Service**

Legal Case #:4911 Case Information RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 213011 12/7/2010 11/1/2010 12/8/2010 Customer Information Business First Name Last Name Street City State Zip Age Contact H 724-766-7750 162 Southbridge Dr. Cranberry Twp. Incident Grumski PA 16066 E kpgrum@zoominternet.net Incident Information Claims Codes **Medical Treatment Medical Status** ΡI Cause: 4038 Could Not Duplicate Concern PD Unknown Concern: 1028 Fired With Safe ON C Fired with Safety on Customer sent in an email. He stated that his Model 700 fired with the safety on. Wanted to know if there was a recall. Wanted to know if he should continue to use it. df Firearm Information SKU Serial Bbl. DOM Model/Ga. Mfg. Type 700/270 WIN Remington CF/BA n/a B6557370 AE 3/1/1984 **Date Purchased** Where Purchased **Original Owner** Accessories UDISCO SALT LAKE CITY UT SCOPE, RINGS, TWO PIECE BASE U CONCERN:FBC Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Date Cash Date Release of Claims Release Date Settlement Reimbursement Settlement APV APV Per Ilion - Repair @ n/c Repair/Replacement Repair/Replacement Cost Date \$64.73 12/14/2010 11/1/10: Sending ARS, letter, form. df 12/14/10: Per Ilion - Could not duplicate concern. Is hard off safe. Replace TA, clean & test fire @ n/c. Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		12/8/2010
Product Type		RF
Action Type		A
Assigned To		T.NAGLE
4038	Could Not Duplicate Concern	
Description		22" 270 WIN
Date Code		AE
Bore Plugged	False	
Bulged	False	
Fired	False	
Fired while Obstructed		
	Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged Fired	Exam Date Product Type Action Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged False Bulged False Fired False

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4911&Type=Case

12/14/2010

	Muzzle/Crown Condition	Slightly Worn; Functioning]
Bolt	Firing Pin	Slightly Worn; Functioning]
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False]
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning	1
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning]
Overall	Stock Condition	Slightly Worn; Functioning	<u>]</u>
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False]
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning]
	Sub-Assembly	Non-ISS]
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning]
	Tests	Test Fired	False
Feeding Test	16313	False]
Trigger	Condition	Slightly Worn; Functioning	HARD OFF SAFETY
	Pull	Select	5#
	Altered	False	<u>]</u>
	Sub-Assembly	M/700 Non-Bolt Lock]
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE

12/08/10 13:46:21 🖏 frmRepairMain - FGI Repairs. Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Location 🖪 frmREInquiry - Repair Inquiry Serial: B8557370 Model:700; Center, Fire Caliber: 2701; Repairman: Dale Lewis / 1 Repair Number: RE00213011 Verify Repair. Status: Repairing 12/8/2010 1:30:04 PM ADDRESS INFORMATION Customer C Received from • Received from Return To Name: KENNETH GRUMSKI KENNETH GRUMSKI Address 1. 162 SOUTHBRIDGE DR 162 SOUTHBRIDGE DR Address 2 PO Box CIV. CRANBERRY TOWNSHIP CRANBERRY TOWNSHIP State PA Zip Code 16066 PA Zip Code: 16066 Country. US Country: US Contact / Condition | Problems | Estimate | History / Status | Shipping / Billing Current Status Date Code Juser D Shipping Hold Repairing Interface Hold 12/7/2010 7:5... New Repair Added 12/8/2010 1:30:04 PM lopatafl Estimate Sent . . System 12/7/2010 7:5... Expedite lopatafi From: Check In Factory ▼ Parts Received 12/8/2010 11:... Repair Maintenance Travishw Status: R Repair Location Passed Inspection Section (ILNE) Estimate Status: P 12/8/2010 1:2... lewisdo Estimate Undate Return as Received Current Location -12/8/2010 1:3... Repairing System Immediate SAP Allocation CAS ILNICA Has Been Approved Transfer Number Internal Repair Exclude TATC Repair Search Refresh Close nagletj - ILN/Prod NAGLETJ Monday, Dec 6 2010.

DEC 1 0 2010

72" A£3/8"

4911

COPY

November 1, 2010

Ken Grumski 162 Southbridge Dr. Cranberry Twp., PA 16066 Ph: 724-766-7750

Ref: #4911

Dear Mr. Grumski,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Mr. Supry will be inspecting the firearm and will contact me with the results.

Fax: 336-548-7872

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

B6557370 Model: 700 RF00213011 could not dupliante concern.

15 hard off safe. Replace TPA,
cleane Testfine ATN/C

#230/45

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number:	Serial Number:				
Name: KENNETH GRUMSKI	Date of Purchase: CAN NOT Remember				
Address (no P 162 Southridge Drive	Address (no PO Boxes):				
City: CRAW BERRY TWP	State: PA	Zip: 16066			
Phone (Daytime): 724-312-3081	Fax:				
E-mail Address: KPGR	um @ 200min	ster wet. NET			
Please describe y	our problem:				
The rifle has mis.	fire twice	once while			
loading and once					
bolt After firing					
500 characters left					
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.					
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.					
Print	Reset				

10/29/2010 02:57 PM

4911

Reference # 101028-000132

Status Updated

Assigned To

Administrators Dell -

Product Firearms

SLA Not specified

Queue CSR

Date Created 10/28/2010 09:13 PM

Initial Response 10/29/2010 02:03 PM

Last Updated 10/29/2010 02:57 PM

Customer SmartSense +2 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

mis fired with safety on

Discussion Thread

Customer (Ken & Paula)

Dell;

Per your request:
Rifle information:
Model 700 – 270 win
Serial #: B6557370
Owner Information:
Kenneth Grumski
162 Southridge Drive
Cranberry Twp, PA 16066
724-766-7750

From: Remington Information [mailto:info@remington.com]

Sent: Friday, October 29, 2010 2:03 PM

To: kpgrum@zoominternet.net

Subject: mis fired with safety on [Incident: 101028-000132]

Response (Dell -)

10/29/2010 02:03 PM

Dear Mr. Grumski, We would like the rifle to come into our Product Services Department at our factory for examination. Please reply back to me with the serial number of the rifle, caliber, your mailing address and phone number. We would like to send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened, when this occurred and what you are

Sincerely, Dell

Note (Daniel -)

fwd to dell

10/29/2010 08:36 AM

Customer (Ken & Paula) 10/28/2010 09:13 PM

Dear Sirs

My Remington 270 model 700 has miss fired with the safety on. Is there safety recall on this model? Please respond. Should I continue to use it?

Ken Grumski 724-766-7750

Primary Contact

First Name: Ken & Last Name: Paula Organization:

Login: kpgrum@zoominternet.net

Title: Contact Type:

Email: kpgrum@zoominternet.net

Email - Alternate #1: Email - Alternate #2:

Office Phone: Mobile Phone: Fax: Assistant Phone: Home Phone:

> Street City State/Province Postal Code Country

Additional Information



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/1/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACKA	4(10 lbs
PLEASE CHECKONE MEDIA COORDINATOR TO MAIL			 WILL MAIL 	XXXXX
DESCRIPTION:	Ref# 4911 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Ken Grumski

162 Southbridge Dr.

Cranberry Twp., PA 16066

Ph: 724-766-7750

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX556 NGV 1, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT UT 10.0 LBS
TRACKINGH 1Z4XX5969067280156
REF 1:KEN GRUMSKI/CD/DMF
REF 2:4911/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRCS: SVC 1/P USD DV 0.00 CD 0.00 RS 0.50 DC 0.00 DC 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHC 7 45 PUB+HANDLING 7.45





