

GUN # - XC 1059

DATE - 5-20-99

SHOOTER - JH

M/710 EET SAMPLE RIFLES
100 ROUND PROOF TESTTRACKING # TLW 9142G
PROJECT # 241095

AMMO PRF 30.00 REM				LOT # F21G C0526			
MALFUNCTIONS				MALFUNCTIONS			
			INS.				
1	1	HEADSPACE		51	1		
2	2	HEADSPACE		52	2		
3	3	HEADSPACE		53	3		
4	4	HEADSPACE		54	4		
5	5	HEADSPACE		55	5		
6	6	HEADSPACE		56	6		
7	7	HEADSPACE		57	7		
8	8	HEADSPACE		58	8		
9	9	HEADSPACE		59	9		
10	10	HEADSPACE ✓		60	10		
11	1			61	1		
12	2			62	2		
13	3			63	3		
14	4			64	4		
15	5			65	5		
16	6			66	6		
17	7			67	7		
18	8			68	8		
19	9			69	9		
20	10	HEADSPACE ✓		70	10		
21	1	Sear pin gun out of fire control - replaced.		71	1		
22	2			72	2		
23	3			73	3		
24	4			74	4		
25	5			75	5		
26	6			76	6		
27	7			77	7		
28	8			78	8		
29	9			79	9		
30	10	HEADSPACE ✓		80	10		
31	1			81	1		
32	2			82	2		
33	3			83	3		
34	4			84	4		
35	5			85	5		
36	6			86	6		
37	7			87	7		
38	8			88	8		
39	9			89	9		
40	10	HEADSPACE ✓		90	10		
41	1			91	1		
42	2			92	2		
43	3			93	3		
44	4			94	4		
45	5			95	5		
46	6	Connector Broken spring in fire control replaced w/ one out of lower		96	6		
47	7			97	7		
48	8			98	8		
49	9			99	9		
50	10	HEADSPACE ✓		100	10	HEADSPACE ✓	

INS. = Inspected w/ bore scope
chamber, lugsLook at firing pin, extractor
bolt lugs

ET19850