

**BARBER - Kinzer PPS GAL RE 0010898**

Remington Arms Co., Inc.

Product Service

Legal Case #:5498

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
215210	12/17/2010	12/28/2010	12/28/2010				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Don	Hamilton	610 S Connor	Odessa	MO	64076		H 816-807-9844

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

1/10/11 Per letter with rifle, pushed safety to fire and gun fired without pulling trigger.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	A6881526	LA	2/1/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMMONS GUN SPEC OLATHE KS	BOTTOM HALF OF SEE THRU MOUNTS	Y			

CONCERN:FSR

## Ammunition Information

Mfg.	Type	Cal./Ga.	SKU	UPC	DOM	Mfg. Code
Remington	CL/180					
Concern	Other	Factory	Reload			
0:		Y	N			

## Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	60.40	1/10/2011				

1/10/11 Per Ilion, could not duplicate concern. Trigger assm very dirty. Replace TPA, clean, test fire under BLSM program price of \$20 + shipping and tax.cm 1/11/10 Left voice message for Hamilton with quote/inspect info. Awaiting reply.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/28/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5498&amp;Type=Case

1/11/2011

Barrel	Description	22" 3006 SPR
	Date Code	LA
	Bore Plugged	False
	Bulged	False
	Fired	False
	Fired while Obstructed	
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning
	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Slightly Worn; Functioning
	Handle	Slightly Worn; Functioning
	Stop	Slightly Worn; Functioning
Extractor	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
	Ext/Eject Test	False
Locking	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
	Notch Condition	---Select---
Overall	Exterior Condition	Slightly Worn; Functioning
	Stock Condition	Slightly Worn; Functioning
	Fore End Condition	---Select---
Receiver	Condition	Slightly Worn; Functioning
	Bulged	False
Safety	Description	STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning
	Sub-Assembly	Non-ISS
Sear	Lift	---Select---
	Notch	Slightly Worn; Functioning
	Tests	Test Fired
Feeding Test	False	False
Trigger	Condition	Slightly Worn; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	M/700 Bolt Lock
Non-Remington Components	Description	BOTTOM HALF OF SEE THRU MOUNTS

5498

22"  
LA 2/80  
7#  
1011

# Remington

## Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700		Serial Number: A6881526	
Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: DON HAMILTON		Date of Purchase: 1976	
Address (no PO Boxes): 1010 S. CONNOR			
City:		State: MO	Zip: 64076
Phone (Daytime): 816-807-9844		Fax:	
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem: Pushed SAFETY to Fire + Gun Fired without Pulling Trigger.			
Ammunition Information:			
Manufacturer: Remington		Type: Core Lok	
Other (i.e. bullet weight/type, shot size, powder):		180 GRAIN	
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: Hopps			
How often do you clean the bore? (Months or Number of rounds) 1 time per year			
How often do you clean the action? (Months or Number of rounds) 1 time per year			
How often do you clean the trigger assembly? (Months or Number of rounds) 1 Time per year			
Brand of lubricant used: Hopps			

RECEIVED  
JAN 04 2011

BY:.....

How often do you lubricate the bore? (Months or Number of rounds)	1 Time Per Year
How often do you lubricate the action? (Months or Number of rounds)	1 Time Per Year
How often do you lubricate the trigger assembly? (Months or Number of rounds)	1 Time Per Year
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Comments: Only use gun 1 week per year	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
What were the services performed?	
Ship your INSURED firearm by either UPS or Parcel Post to:	
<b>REMINGTON ARMS CO., INC</b> <b>ATTN: Arms Service Division</b> <b>1000 Miller Ave</b> <b>Y 13357</b>	
<p>IN YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND</p> <p>ing it.</p> <p>mage in shipping and handling. Preferably,</p> <p>e returned.)</p> <p>oss or damage.</p> <p>le the box. Shipments without a proper</p>	
<p>return address will be refused.</p> <p>:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> <p>Charge repairs will be processed using the following guidelines:</p> <p>:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)</p> <p>:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.</p>	

Serial Number:

A6881526

Model: 700



RE00215210

could not duplicate concern  
 T.A. very dirty. Replace JPA,  
 clean & test fire under BLP  
 for \$20.00 + ship

Quote

Parts/Repairs 800-243-9700  
Fax 336-548-7801

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order Number RE00215210 Account # - R-	Description/Serial Number A6881526	Date Received - 12/17/2010 Estimate Date - 1/4/2011 Current Date - 1/10/2011
Customer DON HAMILTON 610 S CONNOR  ODESSA. MO 64076 US		Return To DON HAMILTON 610 S CONNOR  ODESSA. MO 64076 US
Phone (H) (816)-807-9844 Phone (W)		Fax Email

Please Circle One  
VISA MC AMEX DISCOVER Card No. \_\_\_\_\_ Exp. Date \_\_\_\_\_  
PO Number \_\_\_\_\_  
Daytime Phone (\_\_\_\_) \_\_\_\_\_ Time To Call \_\_\_\_\_ Open Acct. R \_\_\_\_\_  
Approval: Customer Signature \_\_\_\_\_ Date \_\_\_\_\_  
☐ If You Desire Any Change Please Use The Reverse Side For Your Comments And Mark This Box  
Notice: We process checks electronically through Check 21

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTIO	M123	FORWARD TO PRODUCT SERVICE F

Technician's Comments

ProblemNotes could not duplicate concern, trigger assem very dirty. Replace trigger assembly, clean and test fire under bolt lock program for \$20 + shpg

Estimate **C.O.D./Shipping and Handling Charges are NOT Included in this Quote						
Material #	Material Description	Qty	Warranty Y/N	Price/Unit	Discount Percent	Extended Amt
<b>Part</b>						
F305570B	X-MARK PRO 700 TRIG ASSB RH BLACK (O	1	Y	\$94.00	0%	\$0.00
<b>Service</b>						
4000114	GR-SHIPPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000116	GR-LABOR	1	N	\$20.00	0%	\$20.00
4000119	GR-TEST	1	Y	\$23.00	0%	\$0.00
4000294	GR-CHECK TPA	1	Y	\$17.00	0%	\$0.00
Sub Total:						\$37.00
Est. Sales Tax:						
Grand Total:						\$37.00









