

Remington Arms Co., Inc.  
Product Service  
Legal Case #:4998

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
209015	11/2/2010	11/8/2010	11/8/2010				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Michael	Kormash	38 Hickory Way	Mt. Arlington	NJ	07856		H 973-398-1301 E mjk262@verizon.net

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Unexplained Discharge			

Customer wrote on our repair form - In regard to recent tv show, he had an accidental trigger fire and has the bolt lock mechanism. Please check to ensure this model is safe to operate. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06 SPR	n/a	A3206493	AA	3/5/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
10/16/1980	SOUTHERN GUN OPA LOCKA FL		Y			

CONCERN:CHECK SAFE OPERATION OF TPA

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair under BLM program						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$77.73	11/16/2010				

11/16/10: Per Fred S. - Could not duplicate concern. Check over, replace TA, clean & test fire under BLM program - quote. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/8/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 30-06 SPR
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4998&Type=Case>

11/16/2010

	Fired while Obstructed	
	Muzzle/Crown Condition	Slightly Worn; Functioning
Bolt	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Slightly Worn; Functioning
	Handle	Slightly Worn; Functioning
	Stop	Slightly Worn; Functioning
Extractor	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
	Ext/Eject Test	False
Locking	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
	Notch Condition	---Select---
Overall	Exterior Condition	Slightly Worn; Functioning
	Stock Condition	Slightly Worn; Functioning
	Fore End Condition	---Select---
Receiver	Condition	Slightly Worn; Functioning
	Bulged	False
Safety	Description	STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning
	Sub-Assembly	Non-ISS
Sear	Lift	---Select---
	Notch	Like new; Functioning
	Tests	Test Fired
Feeding Test		False
Trigger	Condition	Like new; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	M/700 Bolt Lock

~~Offering~~<sup>Quoting</sup> Bolt Lock modification program

RECEIVED  
NOV - 9 2010

BY: \_\_\_\_\_

4998

22"  
AA 3/80  
SH  
007**Remington.****Factory Repair Instructions**

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 BDL 3006		Serial Number: A3206493	
Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: MICHAEL KORMASH		Date of Purchase: 10/16/1980	
Address (no PO Boxes): 38 HICKORY WAY			
City: MT. ARLINGTON		State: NJ	Zip: 07856
Phone (Daytime): 973 3981301		Fax:	
E-mail Address: mjk262@verizon.net			
<input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
AS PER PHONE CONVERSATION IN REGARD TO RECENT TV SHOW RE: ACCIDENTAL TRIGGER FIRE AND BOLT LOCK MECHANISM PLEASE CHECK TO ENSURE THIS MODEL IS SAFE TO OPERATE			
ALSO PLEASE GIVE ME 3 PCS PART # 17034 RECEIVER PLUG SCREW I LOST ONE & 2 WILL BE EXTRA (SEE ATTACHED PARTS LIST)			
Ammunition Information:			
Manufacturer:		Type:	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: HOPKES OR REMINGTON			
How often do you clean the bore? (Months or Number of rounds) AFTER EACH USE & MONTHLY			
How often do you clean the action? (Months or Number of rounds) AFTER EACH USE & MONTHLY			
How often do you clean the trigger assembly? (Months or Number of rounds) AFTER EACH USE & MONTHLY			
Brand of lubricant used: HOPKES OR REMINGTON			

How often do you lubricate the bore? (Months or Number of rounds) **AFTER EACH USE & MONTHLY**

How often do you lubricate the action? (Months or Number of rounds) **AFTER EACH USE & MONTHLY**

How often do you lubricate the trigger assembly? (Months or Number of rounds) **AFTER EACH USE**

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

☒ YES ☐ NO

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? **N/A**

What were the services performed? **NONE**

Ship your **INSURED** firearm by either UPS or Parcel Post to:

**REMINGTON ARMS CO., INC**  
**ATTN: Arms Service Division**  
**14 Hoefler Ave**  
**Ilion, NY 13357**

A3206493

Model: 700



RE00209015

IN YOUR FIREARM OR IN THE SAME BOX WITH THE  
 IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE  
 ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND--

ing it.  
 image in shipping and handling. Preferably,  
 be returned.)  
 loss or damage.  
 de the box. Shipments without a proper  
 ost. Remington is not responsible for  
 purchase insurance from your carrier.  
 delines:

Under repairs will be processed. C.O.D. (To avoid C.O.D. Charges, please  
 include your credit card number and expiration date with your gun)

**VISA** **REDACTED** **3612** **EXPIRATION 8/12**  
 :: For Repairs over \$75.00, you detailing the nature of the repair, applicable taxes  
 and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order,  
 or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over  
 \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

could not duplicate cust concern.  
 check over, replace TPA, clean and test  
 Fire under bolt lock program to \$20.00  
 (Include Rec. Plug screws)

Quote

700BDC 3006

COPY OF ORIGINAL  
SALES RECEIPT

SN A3206493

NOTE:

THIS IS MY  
OLD ADDRESS  
MY CURRENT  
ADDRESS IS:MICHAEL KORMASH  
38 HICKORY WAY  
MT. ARLINGTON, NJ  
07856

## RAY'S SPORT SHOP, INC.

SPORTING GOODS

WHOLESALE - RETAIL

201-561-4400-01-02

559 HIGHWAY 22

NORTH PLAINFIELD, N.J. 07060

ARCHERY EQUIPMENT • POLICE EQUIPMENT • AMMUNITION & RELOADING SUPPLIES  
ARCHERY LANES • INDOOR RIFLE & PISTOL RANGE  
FISHING TACKLE • HUNTING & FISHING ACCESSORIES • GUNS & GUN SMITHINGType of Transaction CASH Date 1/15/93 1993Name Michael KormashAddress 38 Hickory StNorth Plainfield, N.J. Zip 07060

Sold by <u>(Signature)</u>	Cash <u>X</u>	Check	AMX	Deposit on Acct.	Paid Out	Other	Cashier
Co-sign			BAC		Ring #		
			MC				
			HC				
Quantity	Description					Amount	
1	NEW REMINGTON 760					322	00
	BAY STATE RIFLE						
	30-06 RFL						
Serial #	A7-6000						
N.J.F.ID. #	678430 A						
DR. LIC. #	K6615 54471 09562						
OTHER ID.							
D.O.B.	9-7-53						
PHONE #	204-7194						
REF. #							
SHOP REPAIR #	DELIVERED IN FULL						

All claims and returned goods MUST be accompanied by this bill.