Remington Arms Co., Inc.
Product Service
Legal Case #:5050

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 215279 12/17/2010 11/10/2010 12/28/2010

Customer Information

Type Business First Name Last Name - Street City State Zip Age Contact

Incident Zach Lloyd 209 Caldwell St. Sulphur Springs TX 75482

C 903-243-0958 E zachloyd@hotmail.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

S

PD Cause: 4054 As received Follows Down

Concern: 1007 Fired on Safe Release

Unknown

C FSR

11/10/10: Customer called in. He stated that he had a FSR 3 wks ago. No damage - No injury. df

Firearm Information

Mfg.
Remington

Type CF/BA Model/Ga.

SKU 26438.

Serial Bbl.

DOM

Date Purchased

Where Purchased SPORTS SOUTH INC

700/300 SAUM
Accessories Or

Original Owner Y S6464343 BX 1/17/2003 4:54:45 PM

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Cash Date Date

Date APV

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

11/10/10: Mailing ARS, ltr, & form. df 1/4/11: Per Ilion - Will follow down. Action & TA dirty & is contaminated with sand, trigger binds - not returning. Replace TA, clean & test fire @ 1/2 normal cost - quote. df 1/5/11: I spoke w/customer. He apprvd repair & asked me to have it sent back COD. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		12/28/2010	
	Product Type]	RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4054	As received Follows	POOR MAINTENENCE	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5050&Type=Case

Barrel	Description Date Code Bore Plugged Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop Condition	False False False False Slightly Worn; Functioning Slightly Worn; Functioning	BX BX
Barrel	Date Code Bore Plugged Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop	False False Slightly Worn; Functioning	BX
Barrel	Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop	False False Slightly Worn; Functioning	
Barrel	Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop	False Slightly Worn; Functioning	
Bolt	Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop	Slightly Worn; Functioning	
Bolt	Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop	Functioning Slightly Worn;	
Bolt	Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop	Functioning Slightly Worn;	
Bolt Extractor	Condition Firing Pin Shroud Face Handle Stop	Functioning Slightly Worn;	
Bolt Extractor	Shroud Face Handle Stop	Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning	
Bolt S	Face Handle Stop	Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn;	
Extractor	Handle Stop	Functioning Slightly Worn; Functioning Slightly Worn;	
Extractor	Stop	Functioning Slightly Worn;	
Extractor			1
Extractor	Condition		BINDS
[Slightly Worn; Functioning	
<u></u>	Cut Condition	Slightly Worn; Functioning	
ii.	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	·
	Notch Condition	Select	
	Exterior Condition	Like new; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
Receiver	Condition	Slightly Worn; Functioning	
I=	Bulged	False	
	Description		M/700 SAFETY
· 1	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	ACT.AND T.A.DIRTY AND HAS SAND IN IT.TRIG NOT RETURNING WILL FOLLOW DOWN
Trigger [Pull	Select	10+#
	Altered	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5050&Type=Case

Sub-Assembly M/700 Non-Bolt Lock

QUOTATION: - Kinzer PPS GAL RE 0011330 870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

ESTIMATING REPORT

Parts/Repairs

800-243-9700 336-548-7801

www.remington.com infa@remington.com

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order	Number	Description/Serial N	umber		Date R	eceived -	12/17/2010
RE00215279		S6464343				te Date -	1/4/2011
Account # - R-					Currer	it Date -	1/4/2011
Customer				Return T	0		
ZACK LOY	D			ZACK L			
209 CALDW				209 CAL		ST.	
	-	•		,		-	
SULPHUR S	SPRINGS. TX 75482 US			SULPHU	JR SPRIN	NGS. TX 7	5482 US
Phone (H)	(903)-243-0958		Fax				
Phone (W)	(903)-2+3-0738		Email	zachloyd(a	normail a	com	
7 110110 ()				2.001110/04/0	0,110,011101111		
Please Circle Or							
VISA MC A	MEX DISCOVER Card No	·		Exp. 1	Date		
PO Number							
Daytime Phone		Time To Call		Оро	n AcctR		
Approval: Cust	omer Signature						
If You E	Desire Any Change Please Use T	he Reverse Side For Y	our Comments	And Mark T	his Box	-	
	Not				IIIS DOX		
Company of the second	A William A Managara of the constitution	arma de Problema	ems	AMERICA BIE	Add a Alak	- Warpellad	al Fores SA
Reported			Found		5.15		
M100	SEE CUSTOMERS LET	TER	M103	RUTT	PLATE	RECOIL	PAD IS BROK
M123	FORWARD TO PRODU		M123				T SERVICE F
177.123	FOR INSPECTIO	01 02111102					
	1 311 11101 20 110						
Ł	-						
		Technician's	Comments :	V. 45***		4441	
							the hade in the state of the state of the said
ProblemNotes	•				and,trigge	r binds,not	
	returning.replace trigger	assem clean and test	t fire at 1/2 no	rmai cost.			
İ							
	Estimate_**C.O.D./S	hipping and Handling	Charges are	NOT Includ	ed in this (Quote	E PERMI
1	Material Description			Warranty	Price/	Discount	Extended
	•		_ 	Y/N	Unit	Percent	Amt
Part							
	X-MARK PRO 700 TRIG A	SSB RH BLACK () i	N	\$94.00	50%	\$47.00
Service			-			20,0	
4000114	GR-SHIPPING & HANDLI	NG (GIIN REPAIR)	1	N	\$17.00	50%	\$8.50
	GR-TEST	140 (doi1 idi Aiit)	, i I	N	\$23.00	50%	\$11.50
	GR-CHECK TPA		1	Y	\$23.00	30% 0%	\$0.00
4000254	OR-OTHOR ITM		1	1			
,					Sub Total		\$67.00
]	Est. Sales T	Гах:	\$4.52

\$71.52

Grand Total:

Print :	Reset						
Model Number: Reminster model 700 300 50 m	Serial Number: ১ ৬4 ১4 3 4 3						
Are you the original owner?: YES NO							
Name: Zach Loyd	Date of Purchase: Bought at 645 buns 8 of 1909 a						
Address (no PO Boxes):							
209 Caldwell St							
City: Sulphur Springs	State: χ Zip: 75482						
Phone (Daytime): 903-243-0959	Fax:						
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) Zach loyd at hotmail. com							
E-mail A	ddress:						
I would like to receive future e	e-mail updates from Remington.						
Please describe your problem and date of occurrence: I was sighting my rifle in and the 1st shot was a kay							
the next shot when it went from safety to five it went off and broke my thumb because i wasn't expecting it to go off							
500 characters left							
Ammunition Information:							
Manufacturer: Reminsten	Type: Premier 165gr Gae-lokt						
Other (i.e. bullet weight/type, shot size, 300 short action powder):							
Handload Information:							
Powder Used:	Powder Weight:						
Case/Hull Used:	Primer Used:						
Bullet Type/Shot Size:	Reloader Used:						
	M JAN 0 4 2011						
Firearms Care (Cleaning							
	BY:						

http://www.remington.com/asp/factory repair form.asp

Page 2 of 3

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) before and after deer seeken
How often do you clean the action? (Months or Number of rounds) Before and after deep season
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Remington cil
How often do you lubricate the bore? (Months or Number of rounds) before and after deer sussin
How often do you lubricate the action? (Months or Number of rounds) before and after described
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☐ YES ☑ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services
performed?)

56464343 Model: 700 Her UPS or Parcel Post to:

WILL Collow deline, Act. + T.A.

1 Arms Co., Inc.

Service Division

With SAND, TRIQ. BINDS—

Ifler Avenue

NOT 124-125 LINE AT 12 LORNAL

LOST.

PENT SHELLS IN YOUR FIREARM OR IN

YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

:: Record the serial number of your firearm before sending it.

:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,

ship in a firearm box. (Note: Original boxes may not be returned.)

:: Remove all accessories from your firearm to prevent loss or damage.

:: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory repair form.asp

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/10/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PAC	CKA 10 lbs
RIEASECHEOKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 5050 Rifle			·

LABEL INFORMATION

MAIL LABEL TO: Zack Lloyd
209 Caldwell St.
Sulphur Springs, TX 75482
Ph: 903-243-0958

111. 303-243-0336

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

TPUBASE COMPUBIE AUL PARTISIO PTRISTRORM. AND SEND TO THE MEDIA COORDINATION

AXX596 NOV 11, Z010 ALL CURR USD 1 OF 1
SVC GNDCOM ACT WIT 10.0 LBS
TRACKING# 124XX5969065617550
REF 1:ZACK LLOYD/CD/DMF
REF 2:5050/FIFLE

HANDLING CHARGE 0 00
SINGLE-PIECE PUB RATE CHRGS SVC T/P USD
DV 0 00 COD 0 00 RS 0 50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0 00 SP 0.00
TOT PUB CHG 9.45 PUE+HANDLING 9 45









