

BARBER - Kinzer PPS GAL RE 0011389

Remington Arms Co., Inc.
Product Service
Legal Case #:4943

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
208954	11/2/2010	11/3/2010	11/17/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		William	Ludwig	904 Maxine Ave.	Crane	MO	65633		C 417-229-1223

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD Shot hole in truck	Cause:4006	Altered Adjustments or Components		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C Unexplained Discharge				

Customer wrote in a note with the gun - "Please inspect and make the gun safe. It went off and shot the floor board of my truck. Please install x-mark pro trigger". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	6223494	AS	3/1/1969
Date Purchased	Where Purchased	Accessories	Original Owner			
	WYETH CO ST JOE MO		U			

CONCERN:WENT OFF,SHOT THUR FLOOR OF TRUCK

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Quote to repair under BLM program						

Repair/Replacement Cost	Repair/Replacement Date
\$60.23	11/17/2010

11/15/10: I called cust. He was not home. Left msg w/wife for cust. to contact me. I will have factory quote to repair for \$37 under BLM program. df 11/16/10: Cust. called. We went over report. He is ok w/quote to repair. I emailed factory to prepare quote. df 11/17/10: Factory did repair & is shipping out COD. I called cust. & he is ok with that. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/3/2010
	Product Type		RF

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4943&Type=Case>

11/17/2010

	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	POOR MAINTENENCE
Barrel	Description		22" 30-06 SPR
	Date Code		AS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	DIRTY/STICKY
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	WORKS SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY WITH A DRIED AND STICKY LUBRICATION RESIDUE
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

A large, dark, circular tire tread pattern is visible in the background, partially obscured by the software window. The tire has a prominent tread pattern with several grooves and sipes. The software window is a standard Windows-style application with a title bar, menu bar, and toolbar. It contains various input fields, buttons, and a table of data. The overall image is in black and white, with high contrast.

BARBER KINZEL PPS GAL RE 001439

RE Inquiry - Repair Inquiry

Order Number: **RE00288954** Serial: 6223494 - Model: 700 - Center Fee Colber: 30 Repairman:
Qty Repair: 01 OF SPRIG SKU: 29879 Status: Parked 11/3/2010 7:24:09 AM

ADDRESS INFORMATION

Customer: ☒ Received from Return To: ☐ Received from

Name: **WILLIAM LUDWIG** **WILLIAM LUDWIG**

Address: **904 MAXINE AVE** **904 MAXINE AVE**

Address 2: PO Box: PO Box:

City: **CRANE** **CRANE**

State: **MO** Zip Code: **65633** Country: **US** **MO** Zip Code: **65633** Country: **US**

FFL: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐

Warranty / Condition | Problems | Estimate | History / Status | Shipping / Billing

Date	Code	User ID	Desc1	Desc2	
11/2/2010 11:54	New	schultsm	Repair Added		<input type="checkbox"/> Shipping Hold
11/2/2010 11:54	Expedite	schultsm	From: Check In	To:	<input type="checkbox"/> Interface Hold
11/3/2010 7:24	Maint	Travisbw	Repair Maintenance	Status: Repair	<input type="checkbox"/> Estimate Sent
11/3/2010 7:24	Parked Ext...	Travisbw	Placed in PS Back Rack	hold for disp	<input type="checkbox"/> Parts Received
					<input type="checkbox"/> Passed Inspection
					<input type="checkbox"/> Return as Received
					<input type="checkbox"/> Has Been Approved
					<input type="checkbox"/> Internal Repair
					<input type="checkbox"/> Exclude TATC

Current Status: **Parked**
11/3/2010 7:24:09 AM
Transfer Number: **Travisbw**
Repair Bench
Repair Location
ILN
Current Location
ILN
Transfer Number

Repair Search Refresh Class

Remington

4943

X

22"
2.5"
1004
AS3/69

Please inspect and make the gun safe.
It went off and shot thru the floor
Board of my truck.

Please install X-mark adjustable trigger

Number:

6223494

Model: 700



RE00208954

Rocky
William Ludwig

L

Mr. William E. Ludwig
904 Maxine Ave.
Crane, MO 65633

Remington 700 BDC 30-06
Ser. 6223494

ph: 417-723-0140