Remington Arms Co., Inc. Product Service Legal Case #:5291

Case Information

RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 1/4/2011 12/3/2010 1/18/2011 11/29/2010

217387

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact C 817-648-9490

Incident James Michael Manary 2410 Speedway Dr. Wichita Falls TX 76308

E jmichaelmanary@yahoo.com

Incident Information

Claims Codes Medical Treatment **Medical Status**

PD Shot hole in truck door

Cause: 4038 Could Not Duplicate Concern

Unknown

S C FSR

12/3/10; Customer called in. He stated on 11/29/10 he had a FSR & shot hole in truck door. No injury. df

Concern:1007 Fired on Safe Release

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/3006 SPRG

SKU 25793

Bbl. Serial C6203961 EH

DOM

Date Purchased

Where Purchased **BEST PRODUCTS #002**

Accessories TWO PIECE BASE **Original Owner** N

10/21/1987

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date

APV APV

Per Ilion - Repair @ п/с

Repair/Replacement Cost Repair/Replacement Date

1/18/2011

12/3/10: Sending ARS, ltr, form, box. Box order# 1165214. df 1/18/11: Per Ilion - Could not duplicate concern. TA dirty & hard off safety. Replace TA, clean & test fire @ n/c. I called cust. & he apprvd repair. He was please we are doing the repair @ n/c. He did not bring up the truck at all. I will email factory. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
Examination	Exam Date		1/6/2011	
	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4038	Could Not Duplicate Concern		
	Description		22" 3006 SPR	
	Date Code		EH	
	Bore Plugged	False		
Barrel	Bulged	False		
	Fired	False		
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5291&Type=Case

1/18/2011

	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		
Bolt	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
	Condition	Slightly Worn; Functioning		
Extractor	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
	Block Condition	Select		
Locking	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select	<u> </u>	
	Exterior Condition	Slightly Worn; Functioning		
Overall	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	Select		
D	Condition	Slightly Worn; Functioning		
Receiver	Bulged	False		
	Description		M/700 SAFETY	
Safety	Function	Slightly Worn; Functioning		
	Sub-Assembly	Non-ISS		
	Lift	Select	.013	
Sear	Notch	Slightly Worn; Functioning		
	-	Test Fired	False	
Feeding Test	Tests	False		
	Condition	Slightly Worn; Functioning	DIRTY	
Triones	Pull	Select	4#	
Trigger	Altered	False		
	Sub-Assembly	M/700 Non-Bolt Lock		
Non-Remington Components	Description		TWO PIECE BASE	

E+10/ E+10/ 4[±]

5291

December 3, 2010

+

James Manary 2410 Speedway Dr. Wichita Falls, TX 76308 Ph: 817-648-9490

Ref: #5291

Dear Mr. Manary,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

Fax: 336-548-7872

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

D JAN 1) 2011

RY.

enclosure

C6203961 Model: 700

RE00217387

could not duplicate concern.

T. A. DIRTY + HARD Off SALLY.

JUPHACIT PA, CLEAN + TRESTETIE

At The N/C

230145

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

30°C4

Reset

Print

Number: Model	Serial Number: C6203961				
Are you the original owner?: YES NO					
Are you trie original ow	nei:. 🗆 165 🖭 N				
Name: J. Michael Manary	Date of Purchase:				
Address (no	PO Boxes):	and the second s			
2410 Speedway					
City: Wichira Fall	State: 7x	Zip: 76308			
Phone (Daytime): (817) 648-9490	Fax:				
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) imichael manary @ /ahoo.com					
E-mail Address: I would like to receive future e-mail updates from Remington.					
moving rifle from Fired					
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	racters left				
Ammunition Information:					
Manufacturer: Hornady	Type: Ballisti	c Typp			
Other (i.e. bullet weight/type, shot size, powder):					
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					

http://www.remington.com/asp/factory_repair_form.asp

12/1/2010

Brand of cleaning solution used:				
How often do you clean the bore? (Months or Number of				
rounds) Imonth or 6 rounds				
How often do you clean the action? (Months or Number of rounds)				
How often do you clean the trigger assembly? (Months or Number of rounds)				
Brand of lubricant used: µopp5				
How often do you lubricate the bore? (Months or Number of rounds)				
How often do you lubricate the action? (Months or Number of rounds)				
How often do you lubricate the trigger assembly? (Months or Number of rounds)				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☐ YES ☑ NO				
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) ?				
What were the services performed?)				
Ship your INSURED firearm by either UPS or Parcel Post to:				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357				
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper				

return address will be refused.
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

Reference # 101130-000188

Status Unresolved

Assigned To Administrators Dell -

Product Firearms

SLA Not specified

Queue CSR

Date Created 11/30/2010 07:56 PM

Initial Response None

Last Updated 12/02/2010 04:53 PM

Customer SmartSense 0 (on -3 to +3 scale)

Staff SmartSense 0 (on -3 to +3 scale)

Rifle misfire

Discussion Thread

Customer (James Manary)

11/30/2010 07:56 PM

I am writing this with a concern, Yesterday, my Remington 700 30-.06 fired when I switched it from safety to fire, and caused damage to my truck. When I purchased the rifle my mother in law told me that there was a problem with the Remington 700 rifles and I told her she was crazy. Now, I am concerned about my safety and that of my family. Do you have a recall or is there a replacement. I have had many 700's in the past and never had a problem until now. I look forward to your reply.

J. Michael Manary

This e-mail, including any attached files, may contain confidential and privileged information for the sole use of the intended recipient. Any review, use, distribution, or disclosure by others is strictly prohibited. If you are not the intended recipient (or authorized to receive information for the intended recipient), please contact the sender by reply e-mail and delete all copies of this message.

Primary Contact

First Name: James Last Name: Manary

Organization:

Login: james.manary@halliburton.com

Contact Type:

Email: james.manary@halliburton.com

Email - Alternate #1: Email - Alternate #2:

Office Phone: Mobile Phone: Fax: Assistant Phone: Home Phone: Street

Street City State/Province Postal Code Country

Additional Information



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/3/2010	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASE CHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref # 5291 rifle			

LABEL INFORMATION

MAIL LABEL TO: James Manary

2410 Speedway Dr.

Wichita Falls, TX 76308

Ph: 817-648-9490

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 DEC 7, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969067626309 REF 1:JAMES MANARY/CD/DMF REF 2:5291/RIFLE

HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DC 0.00 CO 0.00 SD 0.00 DC 0.00 PR 0.00 SD 0.00 DC 0.00 PR 0.00 SP 0.00 TOT PUB CHG 9.45 PUB+HANDLING 9.45





