Remington Arms Co., Inc. Product Service Legal Case #:5349

$\sim$	T ^	. •
Case	Inform	iation

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 217657 1/6/2011 12/8/2010 1/7/2011

Customer Information

Business First Name Last Name Street City State Zip Contact Type Age 1216 Ivy Ave. H 318-855-4056 Incident Dale Nesselhauf Deer Park 77536 TX

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

ΡI

PD Cause:4038 Could Not Duplicate Concern S Concern: 1007 Fired on Safe Release

C FSR

12/8/10: Customer called in. He stated this rifle had a FSR. No date given. No damage, No injury. He sent his M/721 in under RE# 211483. df

Firearm Information

Model/Ga. SKU Serial Bbl. DOM Mfg. Type CF/BA 700/308 WIN 25709 C6893313 OO 7/12/1994 Remington Where Purchased **Original Owner** Accessories

Date Purchased

U

Unknown

JERRYS SPORT CENTER INC TWO PIECE BASE

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Release Date Settlement Reimbursement Date Settlement Date APV APV

Per Ilion - Quote to replace TA

## Repair/Replacement Cost Repair/Replacement Date

12/8/10: Sending ARS, ltr, form, box. Box order# 1166705. df 1/10/11 Nesselhauf called and does not want to pay the discounted price. He is willing to pay \$47. I told him Dell would call him after receiving the paperwork from the repairman but that they had already discounted the price.cm 1/19/11: Per Ilion - Could not duplicate concern. TA functioning as designed. Can offer to replace TA at 1/2 normal cost & test fire quote. Customer called & spoke to CSR. Apprvd & gave credit card #. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/7/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 308 WIN
	Date Code		00
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		<del></del>

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5349&Type=Case

1/19/2011

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Like new; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.016
	Notch	Like new; Functioning	
	Toots	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	4#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

,016

December 8, 2010

Dale Nesselhauf 1216 Ivy St. Deer Park, TX 77536 Ph: 318-855-4056

Ref: #5349

Dear Mr. Nesselhauf,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure



could not duplimate concern. T.A. Functioning AS DESIGNED. CAN offen to suplace TPA, AT 1/2 Nonwal cost, test Cine.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

»Pṛint	Reset		
Model	Seri	ial	
Number: 700	Number: C 689	33/3	
Are you the original ow	ner?: 🖺 YES 🖺 NO	)	
Name: PAte Nessel HAUF	Date of Pu	ırchase:	
Address (no	PO Boxes):		
1216 IVY Ave De			
City: Deer Park	State: TX	Zip: 77536	
Phone (Daytime): 318 <b>QSS</b> 46 <b>S</b> 6	Fax:		
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)			
E-mail A			
I would like to receive future	<del></del>		
Please describe your proble  gun Fired going Fram  500 cha		ence:	
Ammunition I	nformation:		
Manufacturer: Whas ICR	Type: 164gr Bal	Listic silvertio	
Other (i.e. bullet wei powder):	ght/type, shot size,		
Handload Information:			
Powder Used:	Powder Weight:	1	
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleania	ng and Lubrication):		

http://www.remington.com/asp/factory\_repair\_form.asp

12/6/2010



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		12/8/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PLEASECHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref # 5349 rifle			

## LABEL INFORMATION

MAIL LABEL TO: Dale Nesselhauf
1216 Ivy St.
Deer Park, TX 77536
Ph: 318-855-4056

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

# REPEASE COMPLETE ALL PARTS OF THIS FORM: AND SEND TO THE MEDIA COORDINATOR

DEC 9, 2010 ALL CURR USD ACT UT 10.0 LBS 1 OF 1 4XX596 SVC GNDCOM SVC GNUCOM ACT WITTACKING# 124XX5969065079548
REF 1:DALE NESSELHAUF/CD/DMF
REF 2:5349/RIFLE HANDLING CHARGE 0.00 SVC T/P USD HANDLING CHARGE OF SINGLE-PIECE PUB RATE CHRGS: RS 0.50 0.00 DV 0.00 DC 0.00 SD 0.00 0.00 DGD 0.00 SP 0.00 PR AH 0.00 TOT PUB CHG 10.54 10.54 PUB+HANDLING





