Remington Arms Co., Inc. **Product Service** Legal Case #:4902

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

10/29/2010 12/29/2010 212441 12/3/2010

Customer Information

Street State Zip Age Type Business First Name Last Name City Contact

6168 E. UV Ave. Incident

H 269-649-5753 Nuyen Vicksburg MI PO Box 3 E jpman999@sbcglobal.net

Incident Information

Codes Repair Est. **Medical Treatment Medical Status** Claims

PΙ

S

PD Cause:4038 Could Not Duplicate Concern

Unknown Concern: 1007 Fired on Safe Release

C FSR

10/29/10: Customer sent in email. He stated he bought rifle 20 yrs ago. Had FSR twice. It was very cold when it happened. Wants it fixed, df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type

CF/BA 700/270 WIN 29709 S6227957 Remington AN 3/23/1993

Date Purchased Where Purchased Accessories **Original Owner** U

D & R SPORTS CENTER

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Repair @ n/c goodwill gesture

> Repair/Replacement Repair/Replacement Cost Date

\$64.73 12/29/2010

10/29/10: Sending ARS, ltr, form. df 12/8/10: Per Fred S. - Could not duplicate concern. TA is dirty & sticky causing part to bind. Replace TA, clean & test fire for 1/2 normal cost - quote. df 12/8/10: I spoke w/customer. I went over report & he refused our quote. I reduced the charges further and customer stated he would not pay anything & would not sign a liability waiver. I spoke w/Danny E. Danny will get back w/me. df 12/29/10: I will do repair @ n/c - goodwill gesture. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/6/2010
	Product Type		RF
	Action Type		A

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4902&Type=Case

12/29/2010

	Assigned To	Ħ	T.NAGLE
Cause	4038	Could Not Duplicate Concern	IMPROPER MAINTENENCE
Barrel	Description	Could Hat Bupholite Concern	24" 270 WIN
	Date Code	\dashv	AN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
15010	Handle	Slightly Worn; Functioning	=
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	RUSTY
Extractor	Cut Condition	Slightly Worn; Functioning	RUSTY
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	-
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES/MARS
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.015
Sear	Notch	Slightly Worn; Functioning	DIRTY,STICKY
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	Select	6#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

14/00/10 10.10.12 🖔 FrmRepairMain : FGl Repairs Repair Tools CSR Tools Reports Table Maintenance Add Repair Estimate Repair Expedite Repair Inquiry System Location LANGE COMPANY OF THE PARKET 🖫 frmREInquiry - Repair Inquiry Senal: \$5227957, Model 700 'Genter Fire Caliber: 270. Repairmen: WIN Produced: 03/23/1993 SKU: 29709 Repair Number: RE00212441 Status Repairing 12/6/2010 2:25:31 PM

• Received from / Return To C Received from Verify Repair ADDRÉSS INFORMATION Customer Name: LARRY NUYEN LARRY NUYEN Address 1: PO 80X 3 PO BOX 3 PO Box. PO Box Address 2: City VICKSBURG VICKS MI VICKSBURG State MI Zip Code: 49097 ¿Zip Code: 49097 Country: US Country: US FFL Contact / Condition | Problems | Estimate | History / Status | Shipping / Billing Shipping Hold Repairing 3

Inlerface Hold 12/6/2010 2:25:31/FM

Status: Repa

Status: Repa

Faste Received Repair Bench

Research Repair Constant

Repair Const Date | Code | Use ID | Desc1 | Desc2 | 12/3/2010 7.5... New lopatafi Repair Added 12/6/2010 2:2... Maint Travishw Repair Maintenance Passed Inspection A STATE ILN Finetum as Received. ILN Transfer Number TOWNSHIP TO THE PROPERTY OF TH Internal Repair Refresh Close Repair Search nagletj :ILN/Prod Monday, Dec 6 2010 1:56 PM

DECEEVE Looming	
BY:	

4902

COPY 6#

October 29, 2010

Larry Nuyen PO Box 3 Vicksburg, MI 49097 Ph: 269-649-5753

Ref: #4902

Dear Mr. Nuyen,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Mr. Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

S6227957 Model: 700 RE00212441 could not dup to wate concerns.

T.A. ES dirty & Sticky CAUSING
parts to BIND. Taphae TPA, clean
+ Test fine At 1/2 Normal costs.

Quole

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

	<u> </u>				
Model Number:	Serial Number:				
700.55	56227957				
Name: Larry Nuyen	Date of Purchase: 3				
Address (no P	O Boxes):				
6168 E. UV' Ave					
City: VICKS byrg	State: M Zip: 49097				
Phone /	Fav: - / - /				
(Daytime): 269-649-5753	Fax: 269-649-5754				
E-mail Address: J PMAN	1999@sbcg/sbal.ne				
Please describe y	our problem:				
GUN SOMETIMES F.	'res when				
safety is pushed	aff				
Sqre19 /5 pas	,				
	·				
	Age -				
500 chara	cters left				
NOTE: Prior to shipping your firearm, cor	ntact the Repair Center for services				
provided and estimat					
WARNING: DO NOT SEND LIVE					
FIREARM OR IN THE SAME BOX W					
VIOLATION OF FEDERAL LAW. IF YOU					
SHELLS PLEASE SEND THEM IN A SEF NAME, ADDRESS (WITH ZIP CODE),	(
SERIAL NUMBER OF					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and					
handling. Preferably, ship in a					
firearm box. (Note: Original boxes may not be returned.)					
:: Remove all accessories from your firearm to prevent loss or damage.					
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not					
responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.					
Print	Reset				
11111	, coset				

http://www.remington.com/asp/general_repair_form.asp

10/29/2010



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		10/29/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACKA(10 lbs	
PLEASECHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 4902 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Larry Nuyen
PO Box 3
Vicksburg, MI 49097
Ph: 269-649-5753

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

TRLEASE COMPLETE ALLEVARIS OF THIS FORM, AND SEND TO THE MEDIA COORDINATOR:

4XX596 NOV 1, 2010 SVC GNDCOM ACT WI IRACKINGH 1Z4XX5969067374911 REF 1:LARRY NUYEN/CD/DMF NOV 1, 2010 ALL CURR USD ACT WI 10.0 LBS 1 OF 1 REF 2:4902/ RIFLE HANDLING CHARGE 0 00 SYC T/P USD SINGLE-PIECE PUB RATE CHRGS: DV 0.00 DC 0.00 COD 0.00 DCO 0.00 RS Ø.50 50 0.00 PR AH 0.00 3.00 SP 0.00 PUB+HANDL INC TOT PUB CHG 3.24 8.24









