BARBER - Kinzer PPS GAL RE 0012176

Remington Arms Co., Inc. Product Service Legal Case #:5069

Case Information

Date Opened Date Opened(PS) **Date Closed Incident Date** Obsolete RE# Pre Lit Lit 210024 11/11/2010 11/12/2010 11/12/2010

Customer Information

First Name **Last Name** Street City State Zip Contact **Business** Age Type Gordon H Schoeneweg 82555 N 13th Ave Burwell NE 68823 H 308-730-1594 Incident

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

C

PD Cause:4038 Could Not Duplicate Concern Unknown

S Fired when lifting the bolt

Concern:1020 Fired on Bolt Opening

11/18/10 Per letter with rifle, the rifle can discharge when lifting the bolt. Doesn't happen all the time but has happened a number of times (4-5) the last few years.cm

Firearm Information

Model/Ga. SKU DOM Serial Bbl. Mfg. Type 248800 DR 9/1/1968 CF/BA 700/30-06 SPR n/a Remington

Date Purchased

Where Purchased

Accessories

Original Owner

TWO PIECE SCOPE BASE **BONITZ BROS HARRISBURG PA**

N

Reimbursement

CONCERN: DISCHARGED WHEN LIFTING BOLT

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Settlement Reim. Date Cash Date APV

Per Ilion, replace TPA, clean at BLSM price

Settlement

Repair/Replacement Repair/Replacement

Cost

Release of Claims

Date

Release Date

30.23

11/18/2010

11/18/10 Called Gordon with results and he approved repair. Per Ilion, could not duplicate concern. Trig set screws altered. Trig assm dirty/rusty. Can offer to replace TPA, check over, clean, test under BLSM price \$20 + shipping.cm

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner]	F.SUPRY
Exam Date		11/12/2010
Product Type		RF
Action Type		A
Assigned To		F.SUPRY
4038	Could Not Duplicate Concern	
Description		22" 30-06 SPR
Date Code		DR
Bore Plugged	False	
Bulged	False	
Fired	False	
Fired while Obstructed		
	Examiner Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged Fired	Exam Date Product Type Action Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged False Bulged False Fired False

BARBER - Kinzer PP	Mazele/Repondentition	Slightly Worn; Functioning	<u>]</u>
	Firing Pin	Slightly Worn; Functioning]
Bolt	Shroud	Slightly Worn; Functioning]
	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning]
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False	
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRACTHES/MARS
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.007
Sear	Notch	Like new; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

FrmRepairMain - FGI Repairs File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance S	ystem
🖻 frmREInquiry - Repair Inquiry	<u>x</u> 1
Repair Number: RE00210024 Seriat 248800 Model 700 Center Fire Caliber 3005 Repairment Bruce Travis Verify Repair: Status ApproveHold 11772/Z010102805. ADDRESS INFORMATION:	
Customes Received from Return To:	
Address 2 PO Box PO Box	
Crity BURWELL BURWELL State NE Zip Code: 68823 County: US NE Zip Code: 68823 County: US	
Dete	
11/12/2010 9: Maint Travisbw Repair Maintenance Status: F Parts Received Repair Bench Repair Location	
11/12/2010 10. Estimate Travistow Estimate Update Status: A Return as Received Current Location	
Internal Repair Transfer Number	
☐ Exclude TATC	The state of the s
Repair Search Refresh > 2 Close ;	
The state of the s	
The second secon	
the state of the s	
supryfi = LLN/Prod frmRepairMah D1102R7XPIL	Thursday, Nov 11 2010 8:17 AM
## start ODMS-Deckton (Carl On mRepair tain F.) E. DMS-Glocal Sett. (5) Indoor, Microsoft	グロの『衣具配刊》 in to AM



BY:----



5069

Factory Repair Instructions

(NO≀E:	Please prin	t and com	ipiete this t	orm, and ti	nen include it with	your firearm.)

, , , , , , , , , , , , , , , , , , , ,	
Model Number: REM 700	Serial Number: 248 800
Are you the original owner?:	
Name: GORDON H. SCHOENEWEG	Date of Purchase: /979
Address (no PO Boxes):	
82555 N. 13th AVE.	
City: BURWELL,	State: NEBRASKA Zip: 68823
Phone (Daytime): 308-730-1594	Fax:
E-mail Address: I would like to receive future e-mail updates from I	Remington.
Please describe your problem: RIFLE CAI	V DISCHARGE WHEN
LIFTING BOLT (NO HAND	ON TRIGGER) DAGEROUS
SITUATION. DOESNIHAP	PEN ALL THE TIME BUT
HAS HAPPENED A NUMB	
THE LAST FEW YEARS.	
	and the second s
Ammunition Information:	
Manufacturer: WINCHESTER Y REM	Type: 30-06 SPRG.
Other (i.e. bullet weight/type, shot size, powder): /8	0 GR + 150 GR
Handload Information: NONE	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: #0 PPF'S	NO. 9 SHOOTERS CHOICE
How often do you clean the bore? (Months or Number of	
How often do you clean the action? (Months or Number	
How often do you clean the trigger assembly? (Months of	
TOTAL CLEANING AFTER	
Brand of lubricant used: Candenies A	

E-MAIL- BLUEEAGLE03@ LIVE, COM

How often do you lubricate the bore? (Months or Number of rounds) WHEN CIFA WING (12	RND
How often do you lubricate the action? (Months or Number of rounds)	PP.
How often do you lubricate the trigger assembly? (Months or Number of rounds) ONCE A YEAR.	
(LIGHTLY)	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO / KEEP GUN CLEAN ALL THE TIME AND	
Comments: AFTER EACH USE, STORED IN A DRY LOCATION	
contract the second	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? NEVER	_
What were the services performed? N/A	
The second secon	* **
Compared to the formation of the first of th	
Ship your INSURED firearm by either UPS or Parcel Post to:	
REMINGTON ARMS CO., INC	

248800 Model: 700



YOUR FIREARM OR IN THE SAME BOX WITH THE FYOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

nage in shipping and handling. Preferably, foreturned.)

pss or damage.

e the box. Shipments without a proper

st. Remington is not responsible for purchase insurance from your carrier.

lelines

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

could not diplicate concern.

TRIO, Set Schews Altered, TIZZO
ASSM. DIRTY/MISTY, CAN offer
to replace TPA, chick only clean
of Test Fire under bolt Lock
Program Roil #20.00 + 5 h.p

Q LOTE BARBER - Kinzer PPS GAL RE 0012180