I IIIICISPIAY Lage 1 of 2

-BARBER - Kinzer PPS GAL RE 0012299

Remington Arms Co., Inc.

Product Service

Legal Case #:5469

Case Information

Incident Date RE# **Date Opened** Date Opened(PS) **Date Closed** Pre Lit Lit Obsolete

220543 1/25/2011 12/20/2010 1/26/2011

Customer Information

Business First Name Last Name Street City State Zip Age Contact Type

3214 N Northshore Blvd W 620-669-6439 Smith Wichita KS Incident Brian 67205

Incident Information

Medical Medical Claims Codes Repair Est. Treatment Status

PΙ

PD Altered Adjustments or Cause:4006

Components Unknown Fired on safety

Concern: 1007 Fired on Safe Release release

C

12/20/10 Per call from Smith, he bought his 700 new about 25 yrs ago. About 3 weeks ago it fired when he released the safety. It cut his thumb when it recoiled back but he is ok. He has not been able to duplicate it but once since.cm

Firearm Information

Model/Ga. SKU Serial DOM Bbl. Mfg. Type CF/BA 700/270 WIN n/a B6529660 XD 12/1/1983 Remington

Y

Date Purchased Where Purchased Accessories **Original Owner**

TWO PIECE BASE

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV

Per Ilion, replace TPA, clean, test fire at 1/2 normal cost

> Repair/Replacement Repair/Replacement Cost Date

12/20/10 Mailing box and ARS.cm 1/28/11 Per Ilion, will follow down. Trigger assm dirty, rusty, set screws altered. Trigger will not return properly. Replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		1/26/2011	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5469&Type=Case

1/28/2011

r munispiay Page 2 of 3

- BARBER - Kinze	ARBIGAL RE 0012	300	T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		22" 270 WIN
	Date Code		XD
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	BEDDED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY,TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	2#

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5469&Type=Case

1/28/2011

Trigger BER - Kinzer	Aberedal RE 0012	Тиче	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

721/83 7012/83

5469

December 20, 2010

Brian Smith 3214 N Northshore Blvd Wichita, KS 67205

Subject: #5469, Model 700

Dear Mr. Smith,

Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

WILL follow down.

T.A. dirty, Rusty, set SCREWS

Altered Trig will Not return

PROPERTY. Repma TRA, CLEAN

+ Test Rire At 1/2 NORMA(
LOST.

B6529660 Model: 700 RF00220543

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 Phone 800-243-9700 • www.remington.com

Q. de Mådison, Ne 127025

BARBER - Kinzer PPS GAL RE 0012302

BARBER - Kinzer PPS GAL RE 0012303

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700	Serial Number: 865 2 9 660			
Are you the original owner?: YES NO				
Name: BRYAN SMITH «	Date of Purchase: 1984 ?			
Address (no PO Boxes): 3214 N NORTH SHORE BUD				
City: WICHITA State: KS Zip: 67205				
Phone (Daytime): (3/2) 590-2020	Fax:			
E-mail Address:(if e-mail address is provided, notification				
sent) BRYANSMITH COMERTONSAGE-mail Address:	-(··· , COpc.)			
I would like to receive future e-mail updates from Rem	nington.			
Please describe your problem and date of occurrence:				
GUN FIRED WHEN TAKEN	OF OF SAFETY			
TWO TIMES IN A ROW. 15- TIME W/				
HANDLOAD AMOUNITION,	24D TIME WITH			
HE AMMUNITION.				
1,0,0				
	∑			
500 characters left				
Ammunition Information: HAND LOADS				
Manufacturer:	Type:			
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			

BARBER - Kinzer PPS GAL RE 0012304

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brend of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your lirearm was serviced by a Remington authorized repairman/gunsmith?) MEVER SERVICES
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
(1) WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/20/2010 REQUESTED BY:	christy	
QUANTITY: 1 WEIGHT PER PAC		ìE:	10
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL	· I WILL MAIL	xx	
DESCRIPTION:	I WILL WATE		
B6529660	700		

LABEL INFORMATION

MAIL LABEL TO:	Brian Smith 3214 N Northshore Blvd Wichita, KS 67205
RETURN ITEM TO:	Rem Prod Service

REFASE COMPLETE ALL RATIOS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

```
4XX596 DEC 21, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969066199596
REF 1:BRIAN SMITH/CD/CM REF 2:700/B6529660

HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 DGD 0.00 SD 0.00 DC 0.00 PR 0.00 SD 0.00 DC 0.00 PR 0.00 SP 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 9.49
```







