BARBER - Kinzer PPS GAL RE 0012324

Remington Arms Co., Inc.

Product Service Legal Case #:5383

le Information

**Incident Date** RE# Date Opened(PS) **Date Closed** Pre Lit Obsolete **Date Opened** Lit 1/5/2011 17500 1/5/2011 12/7/2010

Gomer Information

Last Name Street City Contact First Name State Zip ype **Business** Age H 865-458-2516 17714 Rausin Rd Philadelphia TN kident John W Smith 37846 E dsjfsj@aol.com

Indent Information

Claims Codes Repair Est. Medical Treatment Medical Status

Pl

 $\mathbf{P}$ S Fired when chambering a

Cause: 4006 Altered Adjustments or Components

Unknown

round

Concern: 1008 Fired on Bolt Closing

 $\boldsymbol{C}$ 

12/10 Per email sent to Remington.com, incid # 101125-000053, "Experienced a problem with my Model 700 .243 G6445693. Fired we on and rebolted round into chamber the weapon discharged. My left hand was on the forehand stock and my right hand was on the bolt. Thrown has not been modified and this was the first time I had used the weapon while hunting. Is there a recall issue or known issue with this rifle Is there a fix that I can have performed on the weapon? This is not a case of misuse or inadvertant trigger pull."cm

Firem Information

Mfg. Remington Type

Model/Ga. 700/243 WIN SKU n/a

Serial Bbl.

DOM

Date Purchased

CF/BA Where Purchased

Accessories

Original Owner

G6445693 KZ3 1/1/2005

LEGENDS OUTDOOR ADVANTAGE

U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Reim. Cash

Settlement Date APV Date APV

Per Ilion, replace TPA, clean and test fire at 1/2 normal cost

> Repair/Replacement Repair/Replacement Cost Date

12/7/10 Mailing ARS.cm 1/17/11 Per Ilion, trigger assm set screws altered. trigger has no return. Replace TPA, clean and test fire at 1/2

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date	]	1/5/2011
	Product Type	]	RF
	Action Type	]	A
	Assigned To	]	T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 243 WIN
	Date Code		KZ3
	Bore Plugged	False	
	Bulged	False	
		(	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5383&Type=Case

1/17/2011

BARBER	REMOVER PPS GAL RE 0 12325		
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D :	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.014
Sear	Notch	Slightly Worn; Functioning	
<del> </del>	Toots	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG WILL NOT RETURN PROPERLY
Tuingan	Pull	Select	2.5#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

BARBER - Kinzer PPS GAL FOOT 12326 CONTROL OF THE STATE O

2.5 pt 6/04

5383

December 10, 2010

John Smith 17714 Rausin Rd Philadelphia, TN 37846

Subject: #5383, Model 700


Dear Mr. Smith,

Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



BY:

G6445693 Model: 700



T.A. set screws altered trighas Noteturn. Replace TPA clean 178+ Pine AT 1/2 Narmal wast.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700	Serial Number: 4 6 44 5 6 9 3					
Are you the original owner?: YES NO						
Name: WUKNOWN.	Date of Purchase:					
Address (no PO Boxes):						
City:	State: Zip:					
Phone (Daytime):	Fax:					
E-mail Address:(if e-mail addréss is provided, notification	of receipt and shipment will be					
sent)						
E-mail Address:						
I would like to receive future e-mail updates from Rer	ington.					
Please describe your problem and date of occurrence						
this happened on us	t After Keturning home in it. V. Without AMMO in it. V- 20-2010					
500 characters left						
	<u></u>					
Ammunition Information:	Type: Express core-kort					
1 characters left						
Ammunition Information:  Manufacturer: Rening Tow	Type: Express core-kort					
Ammunition Information:  Manufacturer: Reming Tow  Other (i.e. bullet weight/type, shot size, powder):	Type: Express core-kort					
Ammunition Information:  Manufacturer: Reming Tow  Other (i.e. bullet weight/type, shot size, powder):  Handload Information:	Type: Express core-korr					

L	Firearms Care (Cleaning and Lubrication):
	Brand of cleaning solution used: 3 + / - pi/
	How often do you clean the bore? (Montins or Number of rounds)
ماسسسيب	How often do you clean the action? (Months or Number of rounds)
	How often do you clean the trigger assembly? (Months or Number of rounds)
<u>, , , , , , , , , , , , , , , , , , , </u>	Brand of lubricant used: 3 + / o.'/
	How often do you lubricate the bore? (Months or Number of rounds)
	How often do you lubricate the bore? (Months or Number of rounds)  How often do you lubricate the action? (Months or Number of rounds)
-	How often do you lubricate the trigger assembly? (Months or Number of rounds)
The same of the sa	Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
	YES ' (CO)
	When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	What were the cervices performed?)
	Remington Arms Co., Inc.
	Attn. Atmosocition 2 itteres.
	14 Hoefier Avenue
	Ilion, NY 13357
	●WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE: THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODE SERIAL NUMBER OF YOUR FIREARM.
	:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
	:: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

BARBER - Kinzer PPS GAL RE 0012329

A form was submitted on REMINGTON - PROD.

Reference #

101125-000053

Status Waiting

**Assigned To** Administrators Christy -

**Product** Firearms

SLA Not specified

Queue CSR

**Date Created** 11/25/2010 01:11 PM

**Initial Response** 12/07/2010 09:24 PM

**Last Updated** 12/07/2010 09:24 PM

**Customer SmartSense** 0 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale) **Discussion Thread** 

Response (Christy -)

12/07/2010 09:24 PM

Mr. Smith, I apologize for the delay in responding. We can inspect the rifle to determine what could have caused the incident you described. I can send you a prepaid UPS ground shipping label to cover shipping to the factory at no charge. After inspection we would contact you with the results. If you would like me to send that to you, let me know if the Rausin Rd address is where it should be mailed and the rifle returned afterward.

Sincerely, Christy Mitchell 800-243-9700, ext 8684

Customer (11)

11/25/2010 01:11 PM

Hello,

A form was submitted on the site. Please see submitted information below:

Form Title: Contact Us First Name: John W Last Name: Smith Email: runner45@aol.com

Address 1: 17714 Rausin Road

Address 2:

Telephone: 865-458-2516

City: Philadelphia State: TN

Zip Code: 37846 Country: USS

Experienced a problem with my Model 700 .243 G6445693. Fired weapon and rebolted round into chamber the weapon discharged. My left hand was on the forehand stock and my right hand was on the bolt. The gun has not been modified and this was the first time I had used the weapon while hunting. Is there a recall issue or known issue with this rifle? Is there a fix that I can have performed on the weapon? This is not a case of misuse or inadvertant trigger pull. Thanks

**Primary Contact** 

First Name: 1 Last Name: 1 Organization:

> Login:∖l Title:

Contact Type: Email:

Email - Alternate #1:

Email - Alternate #2:

Office Phone: Mobile Phone: Fax: **Assistant Phone:** 

Home Phone: Street City

State/Province **Postal Code** Country

Additional Information



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	12/10/2010 F	REQUESTED BY:	christy	
QUANTITY:	1 \	<b>NEIGHT PER PACKA</b>	GE:	10
PLEASE OHECK ONE				
MEDIA				İ
COORDINATOR			xxx	
TO MAIL	<u> </u>	WILL MAIL		
DESCRIPTION:				
	700			

MAIL LABEL TO: John W Smith
5900 Rustic Dr.
Uniontown, AR 72955 (

RETURN ITEM TO: Rem Prod Serv

John Smith
17714 Rausin Rd,
Philadelphia, TN 37846

DEC 13, 2010 ALL CURR USD ACT UT 10.0 LBS 1 OF 1 4XX596 SVC GNDCOM TRACKING# 1Z4XX5969067810332 REF 1: JOHN W SMITH/CD/CM REF 2:700 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 0.00 COD DV 0.00 DC 0.00 SD 0.00 0.00 DGD SP 0.00 0.00 PR AH 0.00 PUB+HANDLING TOT PUB CHG 8.74

