→BÄRBER - Kinzer PPS GAL RE 0012407

Remington Arms Co., Inc. **Product Service** Legal Case #:5190

Case Information

Date Opened Date Opened(PS) **Date Closed** Incident Date RE# Pre Lit Lit Obsolete 213993 12/10/2010 11/23/2010 12/13/2010

Customer Information

Last Name Street City Zip Contact First Name State Type Business Age Jason Starbuck 3001 Shadow Oaks Way Wilsonville AL 35186 H 205-422-4790 Incident

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause:4038 Could Not Duplicate Concern

Unknown

S Fired on safety release Concern: 1007 Fired on Safe Release

C

11/23/10 Per call from Jason, he has a 700 that was a gift a few years ago. He has had no alterations made to it and it has fired when the safety was released.cm

Firearm Information

Mfg. Type Remington CF/BA

Model/Ga. 700/308 WIN

SKU 25715

Serial Bbl. D6584146 RT

DOM 11/15/1999 11:58:12 AM

Date Purchased

Where Purchased

Accessories **Original Owner**

U

DAVIDSON SUPPLY CO

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Release of Claims Settlement

Release Date

Reimbursement

Cash Settlement Date APV

Reim.

Cash Date **APV**

Per Ilion, replace TPA, clean at no charge as goodwill

> Repair/Replacement Cost

Repair/Replacement Date

62.23

12/16/2010

11/23/10 Emailing ARS and letter, ordering box.cm 12/16/10 Per Ilion, could not duplicate concern. TA functioning as designed, as a good will gesture will replace Trigger assambly, clean + test fire at n/c. Spoke with Jason by phone and gave update.cm

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		12/13/2010
Product Type		RF
Action Type		A
Assigned To		T.NAGLE
4038	Could Not Duplicate Concern	
Description		26" 308 WIN
Date Code		RT
Bore Plugged	False	
Bulged	False	
Fired	False	
	Examiner Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged	Examiner Exam Date Product Type Action Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged False Bulged False

PrintDisplay

PrintDisplay			Page 2 of 2
√ ∙BARBER ۱	- Kinzer PPS GAL RE 001 Fired while Obstructed	2408	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
Trican	Pull	Select	3.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

V - 5 - · · · ·	-:- FCI 0:			entialise y laws	TC/ TJ/ T/	, TT.76.			1 2 4		
File Add R	ain - FGI Repairs epair Estimate	Repair E	xpedite Repa	ir Inquiry	Repair Tools	CSR Tools	Reports	Table Maintenance	System	Location	
<u> </u>	ction Enteria	FIV ALIA	៩ បានប្រាស	20.26							
	Repair Number: The Property Repair Number: The Property Repair Curity Repair Curity Repair Re	ATION: stomer ON STARBUT SHADOW LSONVILLE ZIP Cod Problems Code New Expedite Maint	Serial Di MIN Pro JCK OAKS WAY e' 35186	Country US	FFL ping / Biling De	Return To SIASON STAR SOULS ON STAR SOULD SOULS ON STAR SOULS ON STAR SOULD SOULS ON STAR SOULS ON STAR SOULS ON STAR SOULD SOUL	Status: BUCK W OAKS WAY	County: US Current S Ne 12/11/2010 Repair In Repair Lor	eived from altus 3.54.31 AM negí Sench sation cation	<u> </u>	
nagletj IIN	∬Prod \$ frmRepair	New Arrange States	mRepairMain	NBC-WKT	€ 11 Mcr	。NAGLETJ	. E	Monday, Dec.	3 2010 Part Searc 2010		4. 11:52 A
	Alrèg	edy 1 to	u pla 13 le	Led				BY:			

5190

RT 11/99 3.5th

November 23, 2010

Jason Starbuck 3001 Shadow Oaks Way Wilsonville, AL 35186

Subject: #5190, Model 700

Dear Mr. Starbuck,

You should receive an email with the UPS ground prepaid shipping label within the next 24-48 hours. You should receive the box in about a week. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
christy.mitchell@remington.com

D6584146

Model: 700

RE00213993

T.A. functioning As Designed

AS A Good-Will Gesture and

supprese TP.A., clean + tet fine

At NK

230145

November 28, 2010

Remington Arms Company, Inc. 870 Remington Drive P.O.Box 700 Madison, NC 27025

To Whom It May Concern:

My name Jason Starbuck and I have been around guns all my life from .22 rifles all the way up to .50 caliber sniper rifles. Watching through the eyes of my relatives I have seen many different companies go through the hands of my family, but only one company remains solid; Remington, or so I thought.

Enclosed is my Remington 700 .308 Tactical Rifle I received as a gift from my relative who served in the armed services. Although it should have been in my hands in 1999, my relative did not make it back from his tour and I received the rifle just last year. Words could not describe my facial features as I saw the rifle. It was more then I had asked for and meant more to me then just another gun to hunt with. It is a memory that once will tell a story to my children.

The rifle has brought nothing but fear since using it. Just recently I was hunting from my tree stand and the rifle discharged as I flipped the safety off to take aim. Another occurrence happened while I was walking and again it discharged as I flipped the safety to take aim. Now, the rifle remains wrapped up in a sheet, locked in my diamond metal case as an item not to talk about or mention in my house.

After realizing that there is a mechanical problem with this rifle I did what any person would do, search the internet. The end result was thousands of sites from CNBC and Sean Hannity voicing there opinions on these rifles to attorneys asking for your help to sue Remington. I on the other hand am not one of those people. I am asking your company to please take the necessary time to inspect my rifle and replace any parts or in the end the rifle if you feel it is necessary. Although this rifle has significance to me and my family I would not want my children to handle it at this time or in the future if it is not fixed.

Remington has and continues to be the rifle of my choice. Companies in general cannot all be flawless but they can make up what has gone wrong in the past to prevent reoccurring issues in the future. I work for the largest tobacco company in the world, believe me when I say I understand what your employees must be facing. I stand by your values and the name Remington.

Sincerely,



www.remington.com

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/23/2010	REQUESTED BY:	christy	
QUANTITY: //		WEIGHT PER PACKA	GE:	10
PLEASE OHEOKONE?				
MEDIA / Em	ail to him at:			
COORDINATÓR inst	3113@hotmail:com	(that first letter is a si	mall J)	
TO MAIL		I WILL MAIL		
DESCRIPTION:				
	700)		
D65	584146			

LABEL IN

MAIL LABEL TO: Jason Starbuck ins3113@hotmail.com 3001 Shadow Oaks Way Wilsonville, AL 35186 Email to him at: (that first letter is a small J) ins3113@hotmail.com RETURN ITEM TO: Rem Prod Service 4XX596 NOV 24, 2010 ALL CURR USD SVC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969067005088 1 OF 1 REF 1: JASON STARBUCK/CD/CM REF 2:700/D6584146 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 1.00 COD 0.00 RUBASE COMPUBILE AUGRARIS (OF STHIS FOF DV 0.00 SD 0.00 0.00 DGD DC 0.00 SP 0.00 0.00 PR 90.00 HA PUB+HANDLING TOT PUB CHG 9.24

213993

77.23





