Remington Arms Co., Inc. Product Service Legal Case #:5225

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

218840 1/13/2011 11/29/2010 1/14/2011

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact

H 303-271-9790

Incident Bob Szulczewski 117 Kimball Ave. Golden CO 80401 W 303-525-5767

E brenovator@aol.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4038 Could Not Duplicate Concern

Unknown

S Concern: 1008 Fired on Bolt Closing

C FBC

11/29/10: Customer called in. He stated that his rifle fired on bolt closing. No damage, No injury. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/300 RUM 26010 S6492894 KY 5/7/2004 10:19:27 AM

Date Purchased Where Purchased Accessories Original Owner

SPORTS SOUTH INC Y

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date APV APV

Per Ilion - Quote to repair

Repair/Replacement
Cost
Repair/Replacement
Date

11/29/10: Sending ARS, ltr, form. df 1/21/11: Per Ilion - Could not duplicate concern. TA & action dirty & has sand in action. Can offer to replace TA, clean & test fire @ 1/2 normal cost. Customer provided written approval & credit card number. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/14/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
		1	

ĺ	Description		26" 300 RUM SS FL, DRILLED FOR BRAKE
	Date Code		KY
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.016
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY,SAND IN ACTION
T-:	Pull	Select	7#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	]

# Remington Arms Company, Inc. 870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

**ESTIMATING REPORT** 

Parts/Repairs Fax

800-243-9700 336-548-7801

www.remington.com info@remington.com

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order Number RE00218840 Account # - R-	Description/Serial Number S6492894	•	Est	te Received - timate Date - rrent Date -	1/13/2011 1/14/2011 1/21/2011
Customer BOB SCZULCZEWSKI 117 KIMBALL AVE.			Return To BOB SCZULC 117 KIMBALI		
GOLDEN. CO 80401 US			GOLDEN, CO	80401 US	
Phone (H) (303)-271-9790 Phone (W)		Fax Email	BRENOVATOR	R@AOL.COM	
Please Circle One VISA MC AMEX DISCOVER Card No	)		Exp. Date		
PO Number  Daytime Phone (	Time To Call	<del></del>	_ Open Acct	. R	
If You Desire Any Change Please Use T	tice: We process checks electronic	ally throu	gh Check 21	x	
	Problems				THE PARTY
Reported	For	ind 📉	Taning by the territory of the	Padari.	and the way they were
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO	TER M1	<u>23</u>	T 50 20 1 1 1 1 1 201	TO PRODUC	and the second
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU	TER MI	23	FORWARD	TO PRODUC	T SERVICE F
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO	TER MI ICT SERVICE  Technician's Compactor Com	23	FORWARD	TO PRODUC	T SERVICE F
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO  ProblemNotes could not duplicate cond assm,clean and test fire:  Estimate **C.O.D./S	TER M1: CT SERVICE  Technician's Common cern.trigger assm dirty and at 1/2 normal cost	23 ments has sanc	FORWARD	TO PRODUC	T SERVICE F
M100 SEE CUSTOMERS LET M123 FORWARD TO PRODU FOR INSPECTIO  ProblemNotes could not duplicate cond assm,clean and test fire a	TER ICT SERVICE  Technician's Commodern trigger assm dirty and at 1/2 normal cost  Shipping and Handling Char	nents	FORWARD	TO PRODUC	T SERVICE F

			<u>Y/N</u>	<u>Unit</u>	Percent	Amt
Part				<del></del>		
F306372B	700 SS XMP EA TRIG ASSB RH SILVER (OS)	1	N	\$115.00	50%	\$57.50
Service						
4000114	GR-SHIPPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000119	GR-TEST	1	N	\$23.00	50%	\$11.50
				Sub Total:		\$86.00
				Est. Sales 7	ſax:	\$1.73
				Grand To	tal:	\$87.73

26" K45/0"

5775 November 29, 2010

Bob Szulczewski 117 Kimball Ave. Golden, CO 80401 Ph: 303-271-9790

Ref: # 5225

Dear Mr. Szulczewski,



Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

could not duplicate concern.
T.A. + Act. Dirty + has SAND
IN ACTION. CAN offen to
Replace TPA clean TRST
Cire At 1/2 NORWAL COST.

PISA REDACTED

EXS. 8/13

AUTHORIZE 10 4/5000

But the think

JAN 1 7 2017

1322

BY

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Print	Reset	
5 1 1 1		

Model SENDERE SE	Serial						
Number: 700 / 300 42522 MAG	Number: 56.492894						
Are you the original owner?: ☒ YES ☐ NO							
Name: Date of Purchase:							
MOBERTK DZULCZEWSK, 2004-1005							
Address (no	PO Boxes):						
City: GOLDEN State: (0 Zip: 8041)							
City: 6040 est	State: (0   Zip: 8041)						
Phone (Daytime): 3 / 3 - 525 - 5447	Fax: 3+3-271-9790	•					
E-mail Address:(if e-mail address is provid	The state of the s						
be sent) BRENZYATOR (2)	AOL, CEM						
E-mail A							
WI would like to receive future e							
Please describe your proble	10 to						
FIRES WHILE ROUND	15 BEING CHAMBERTED						
HAPPEN APPROX, 3	Times Twice Tair						
FALL DURING HUNTING	SEASON AND ENCE IN						
2008 During same p							
500 cha	racters left						
Ammunition I	nformation:	WY Ln					
Manufacturer: / con ny tax	Type: Power Level TIT	•					
Other (i.e. bullet weight/type, shot size,							
powder): 180 GR							
Handload Information:							
Powder Used: Powder Weight:							
Case/Hull Used: Primer Used:							
Bullet Type/Shot Size: Reloader Used:							
Firearms Care (Cleaning and Lubrication):							

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of CLEANES AFIER TARGETY PRACY OR MUNICIPAL FIRED OR NOT
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: BORE SCANDOR BROOK FAIL CLP
How often do you lubricate the bore? (Months of Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES \( \subseteq \) NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services  performed?)  \[ \int \frac{1}{2} \text{NA} \cdot \frac{1}{2} \text{RTGO} \]
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process ..... checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:		11/29/2010	REQUESTED BY:	Dell
QUANTITY:			WEIGHT PER PKG:	10 lbs
RIFASE CHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref # 5225 Rifle			

### LABEL INFORMATION

MAIL LABEL TO: Bob Szulczewski
117 Kimball Ave.
Golden, CO 80401
Ph: 303-271-9790

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

## APLEASE COMPLETIE ALL PARTIS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION

4XX596 SVC GNDCOM NOV 30, 2010 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 TRACKING# 1Z4XX5969066739672 REF 1:BOB SZULCZEWSKI/CD/DMF REF 2:5225/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD RS 0.50 DV 0.00 DC 0.00 COD 0.00 DGD 0.00 SD 0.00 AH 0.00 0.00 PR SP 0.00 TOT PUB CHG 10.54 PUB+HANDLING 10.54







