

BARBER - Kinzer PPS GAL RE 0012512 Remington Arms Co., Inc.
Product Service
Legal Case #:5367

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
217401	1/4/2011	12/8/2010	1/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		James	Taylor	117 Village Creek Dr	Newport	AR	72112		E tmajet@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

12/8/10 Per email sent to Remington.com, incid # 101206-000048, "My Rem 700, in 300 WinMag fired when I switched the safety from "S" to "F". The muzzle was pointed in a safe direction, so a bruised thumb was the only damage. Could you advise me if this is affected by the recall, or if it is a freak accident? I had stored the rifle in a gunsafe for a week with a round in the chamber(3+1). When about to hunt, I started walking, holding at the fore stock and moved the safety with my right thumb, not touching the trigger or other parts, it fired."cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	27535	E6447241	CS	4/17/1998
Date Purchased	Where Purchased	Accessories	Original Owner			
6/24/2010	ZANDERS SPORTING GOODS * GLENN		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

12/8/10 Mailing ARS.cm 1/17/11 Per Ilion, could not duplicate concern. Trigger assm set screws altered. Replace TPA, clean, test fire at 1/2 normal cost.cm 1/18/11 Emailed inspection/quote to Taylor. Awaiting reply.cm 1/18/11 Owner called and approved through Consumer Dept.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 300 WIN MAG
	Date Code		CS
	Bore Plugged	False	

BARBER - Kinzer PPS GAL RE 0012513

Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.015
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	MIN TRIG RETURN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	





