BARBER - Kinzer PPS GAL RE 0012586 Remington Arms Co., Inc.

Product Service Legal Case #:4867

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

209057 11/3/2010 10/27/2010 11/4/2010

Customer Information

Last Name Street Type **Business** First Name City State Zip Age Contact C 314-420-9051

4152 Tesson St Incident Tucker Darrel St. Louis MO 63123 F 314-551-5333

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ΡI

PD Could Not Duplicate Concern Cause:4038

Unknown

S FSR

Concern:1007 Fired on Safe Release

C

10/27/10 Per phone call, Tucker has 2 700's, one made in the '90's and one in the '80's. He has had two FSR's with the '80's model but never sent it for inspect afterward. He has seen information on the Bolt Lock Program and wants to have the bolt lock removed and for us to check the issue of the FSR.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM CF/BA 700/30-06 SPR n/a 6891385 WZ 8/20/1975 Remington

Where Purchased Accessories **Date Purchased Original Owner**

K MART ENT ROYAL OAK MICHIGAN U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Settlement Release Date Reimbursement Date Settlement Date APV APV

Per Ilion, replace TPA at BLM price

> Repair/Replacement Repair/Replacement

Cost Date

37.00 11/8/2010

10/27/10 Faxing ARS.cm 11/8/10 Per Ilion, could not duplicate concern. Check over, Replace TPA, clean and test fire under bolt lock program for \$20.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/4/2010
	Product Type		RF
	Action Type		A

, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	- Kinzer PPS GAL RE 00 Assigned To]	F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 30-06 SPR
Barrel	Date Code		WZ
	Bore Plugged	False	
	Bulged	False]
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACTION DIRTY
Overall	Stock Condition	Slightly Worn; Functioning]
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	<u> </u>
	Tests	Test Fired	False
Feeding Test	10363	False]
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	·

BARBER - Kinzer PPS GAL RE 0012588

Remington.

4867

October 27, 2010

Darrel Tucker 4152 Tesson St. St. Louis, MO 63123

Subject: #4867, Model 700

Dear Mr. Tucker,

Regarding your contact with Remington and the incident you incurred, you should receive a faxed prepaid UPS ground shipping label for shipment of the firearm to our factory within 24 hours. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
christy.mitchell@remington.com

PA 17.0

Ø. G 77,00



Reminston 700 ADL

Sevial NO. 689/385


could not diplicate concern

checkown inlacetor, clear test
fill under bolt Lock onogram

for # 7000

Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Add Repair	Estimate Repair	Expedite	Repair Inquir	Repair Tool	s CSR Tools Re	ports Table Mai	intenance Sys	stem	:		
			,	٠.							
100							Abbiera				
# 6 DEI					5 6 7 5 6 7 7 T			මැති			
Minke	nquiry - Rep	Ellelliel		A DECEMBER		8 (1988) <u>(18</u>			Marie Control		٠.
Repair Numbe	RE00209057	Senal: 6	891385 Model 700 Produced: 08/20/19	Center Fire Calib	er 3006 - Repaiman	Bruce Travis		172			٠٠;
Verify Repai	772.	orna	1000C#1. 08/20/13	3380.2000	Status	ApprovalHold 11/4/	2010 2:44:21,PM				
ADDRESS	NFORMATION	Notes							100		• : •
	Customer			ceived from P	eturn To	A, C	Received from			"1 ".	
Name	DARREL TUCKE	3	·		ARREL TUCKER		Ď				
Address	* <u>*</u>		annode beliebe homen announce		152 TESSON ST			140	Mr.		٠.,
Address	THE REAL PROPERTY AND ADDRESS.		PO Box		T 10110	P0.86x					
a terrain a company of the contract of the con	r ST.LOUIS : MO ZipCode	l63123	Country US		T. LOUIS 10 Zip Code: 63123	Country: US					
3,3,0		, Juli 19	Courily, 103		. о гар свее, дозгаз	Country's Just			134	No. of the last of	;; · ·
				XFFL	1	www.					
Contact / Co	ndition Problems E	stimate: Histo	sy / Status Shippir	g/Billing							
Date	Code	User ID	Desc1	Desc2	Shipping Hold	Currer App	nt Status				
11/3/201		valentds	Repair Added		Interface Hold	11/4/20	10 244:21 PM				
11/3/201	0 6:3 Expedite	valentds .	From Check In	To:	Estimate Sent	Market Committee	ravisbw roveRack		7 / 1		
11/3/201	0 6:3 Expedite	valentds	From: Product Ser	vices To:	Parts Receive	Repai	Location				
11/4/201		Travisbw	, Repair Maintenan		F Return as Rec	COST HAZZZIA	ILN Location	No.	March 2004		
11/4/201	0 2:4 Estimate	Travisbw	Estimate Update	Status:	The second of th	roved	ILN . San A		THE PERSON		
4-	Property Section (Control of the Control of the Con	32/33/06 - NO SEC		COS SON TO SEE THE	I Internal Repair	220 S. V. S. V. 23 VK. 192	er Number		MAGNET		
a Barring	v 200 st. st. st. st. st. Strikterbesse v vervalet	6.727600 6.727600	45,200 (100 to 100 to	(4) (5) (5) (5) (5) (4) (5) (7) (4) (5) (4)	J JE KOUGE IAIL	A Company		<u> </u>	y j	Asim	
Repair	Search					Refre	sh Clo	se /	£ 1.4		
Ý 190 9230		22.000		. 00							
	A Second	The state of the s		C. S. C.							
	S. S.	يتعرق				· ·			137		, ,
	The state of the s		and the state of the state of	*#	- 10 miles		. A. S		10 mg/s		:
		130		$X_{i,j}$		极为情况	1				
			New York	2.334	STANKE S					AND THE PROPERTY OF THE PROPER	
					112 114 44	Commence of the second		200			٠
				10000				200 T 18 V			
	•		704	V 4 2 7	TG representation		477.3	FRIE	diame.		;
				7 (B)	(\$.7.2 \$ -5.	164:11	711 80				. :
							Simbon C.L.	•			
				* ***							, ,
											1



October 27, 2010

Darrel Tucker 4152 Tesson St. St. Louis, MO 63123

Subject: #4867, Model 700

Dear Mr. Tucker,

Regarding your contact with Remington and the incident you incurred, you should receive a faxed prepaid UPS ground shipping label for shipment of the firearm to our factory within 24 hours. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

BARBER - Kinzer PPS GAL RE 0012590

10/27/2010 12:00 TIME NAME

3365487823 TEL SER.# : BROC0J148005

DATE, TIME FAX NO./NAME DURATION

10/27 12:00 13145515333 00:00:25 STANDARD

Remington

FACSIMILE TRANSMITTAL SHEET Darrel Tucker Date: To: Christy Mitchell Company: From: Fax No.: Fax No.: Phone No.: Phone No.: Number of pages including Cover Sheet: **COMMENTS:** your citle before shipping. Thanks, BARBER - Kinzer PPS GAL RE 0012591



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	10/27/2010 REQUESTED BY: christy	
QUANTITY: /	\ 1 WEIGHT PER PACKAGE:	10
1	Fax to: 314-551-5333 I WILL MAIL	
DESCRIPTION:	700	

LABEL INFORMATION

MAIL LABEL TO: Darrel Tucker
Fax to him

4152 Tesson St
St. Louis, MO 63123

RETURN ITEM TO: Remington Product Service

TPLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

1 OF 1 ALL CURR USD OCT 27, 2010 ALL CURI ACT UT 10.0 LBS 4XX596 SVC GNDCOM TRACKING# 124XX5969067016129 REF 1: DARREL TUCKER/CD/CM REF 2:700 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRCS: COD 0.00 RS 0.50 SD 0.00 DV 0.06 00.0 DGD SP 0.00 DC 0.00 0.00 PR AH 0.00 PUB+HANDLING 8.78 TOT PUB CHG 8 78

Remington.

FACSIMILE TRANSMITTAL SHEET						
То:	Darrel Tucker	Date:	19/27/10			
Company:		From:	Christy Mitchell			
Fax No.:	314-551-5333	Fax No.:				
Phone No.:		Phone No.:				
Number of p	nages including Cover Sheet:					
COMM	ENTS:					
PI	Pasa include a co	py of N	y letter with			
	pase include a co your rifle before	chipping	,			
Thanks;						
Christy Mitchell						
		,				

PRIVILEGED AND CONFIDENTIAL

This facsimile is intended only for the use of the individual or entity to which it is addressed and may contain information that is privileged, confidential and exempt from disclosure. If you are not the intended recipient please do not disseminate, distribute, or copy this communication. Instead, please notify the sender immediately by return fax or by telephoning the number above and discard all copies of this fax.

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025-0700 Phone 336-548-8700 • www.remington.com

BARBERTURN SERVICE GAL RE 0012594

SHIP TO: PRODUCT SERVICES REMINGTON ARMS CO., INC. 14 HOEFLER AVE. ILION NY 13357

,

CUSTOMER SERVICE 800-742-5877

ACKAGE CONTENTS: FIREARMS

EF 1:DARREL TUCKER/CD/CM

IMPORTANT NOTICE TO ANYONE HANDING OVER GOODS TO UPS

This document is a receipt only and you are named on the attached label/document exclusively for identification purposes. The contract of carriage is between UPS and lis customer There is no contract between you and UPS. By handing over the goods to UPS, you agree that UPS collects the goods on behalf of lis customer and accepts no agree that UPS collects the goods are anyone other than its customer for any loss, delay, or damage to goods resulting from negligence or any other council.

THIS RECEIPT IS TO BE RETAINED BY THE CUSTOMER RETURNING THE MERCHANDISE

UPS GROUND TR#: 1Z 4XX 596 90 6701 6129

International Striptory (Incise - Libridge in Herinder may be authorized to the natural collection and code internations conclusive statisticated by the Constitution for the Unification (Contention). The desired international Contention on the Contention on the Content for the International Contention on the Content for the International Contention. The desired international Contention on the Contention Registration Contention on the Contention on the Contention Registration Contention on the Contention Registration Contention on the Contention on the Contention Registration of Contention on the Con

DARREL TUCKER 4152 TESSON ST SAINT LOUIS MO 63123


10 LBS

1 OF 1

RS

PRODUCT SERVICES
REMINGTON ARMS CO., INC.
14 HOEFLER AVE.

ILION NY 13357



NY 135 0-01

UPS GROUND

TRACKING #: 1Z 4XX 596 90 6701 6129



BILLING: 3RD PARTY DESC: FIREARMS RETURN SERVICE

REF 1:DARREL TUCKER/CD/CM

REF 2:700

HS 12.0.17

LP2442 09.08 10/2010

10/27/2010 16:00

FAX 3365487823 BROC0J148005

DATE, TIME FAX NO./NAME DURATION

10/27 15:59 13145515333 00:00:30 STANDARD

Remington.

FACSIMILE TRANSMITTAL SHEET Darrel Tucker Date: To: Christy Mitchell Company: From: 314-551-5333 Fax No.: Fax No.: Phone No.: Phone No.: Number of pages including Cover Sheet: **COMMENTS:** Your rifle before chipping. Thanks.

BARBER - Kinzer PPS GAL RE 0012595