

BARBER - Kinzer PPS GAL RE 0012616

Remington Arms Co., Inc.

Product Service

Legal Case #:4985

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
209325	11/4/2010	11/5/2010	11/5/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City State	Zip	Age	Contact
Incident	Uncle Sam's Loans	Roger Muncy	Uncle Sam's Loa	200 Main St	Man WV	25635		W 304-583-6969

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4006 Fires when safety is released	Altered Adjustments or Components Concern:1007 Fired on Safe Release	Unknown	
C				

11/15/10 Per note with rifle, gun fires when safety is released.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	25860	B6663685	BF	1/1/1985
Date Purchased	Where Purchased	Accessories	Original Owner			
	COTTER AND COMPANY 18051	TWO PIECE SCOPE BASE AND RINGS	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean at 1/2 normal charges						
	Repair/Replacement Cost	Repair/Replacement Date				

11/15/10 Per Ilion, trig assm has been altered. Connect will not return under sear. Check over, replace TPA clean and test fire at 1/2 normal charges. Anne Harper contacted dealer, dealer is contacting owner. Awaiting reply.cm

Approved 11/24/10.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/5/2010
	Product Type		RF

BARBER - Kinzer PPS GAL RE 0012617		A	
	Action Type		
	Assigned To	F.SUPRY	
Cause	4006	Altered Adjustments or Components	
Barrel	Description	22" 243 WIN	
	Date Code	BF	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	STANDARD M/700 SAFETY	
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Not Functioning	

BARBER - Kinzer PPS GAL RE 0012618

Trigger	Pull	---Select---	N/A
	Altered	True	ALTERED AND CHANGED SCREWS CONNECTOR WILL NOT GO UNDER SEAR
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE AND RINGS

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

frmREInquiry - Repair Inquiry

Repair Number: **RE00209325** Serial: 88653685 Model 700 Center Fire Caliber: 243 Repairman: Bruce Travis
 SKU: 29874 Status: ApproveHold 11/5/2010 1:22:25 PM

Verify Repair

ADDRESS INFORMATION

Customer: ☐ Received from ☐ Return To ☐ Received from ☐

Name: **UNCLE SAMS LOANS** **UNCLE SAMS LOANS**

Address 1: **200 MAIN STREET** **200 MAIN STREET**

Address 2: PO Box: PO Box:

City: **MAN** **MAN**

State: **WV** Zip Code: **25635** Country: **US** **WV** Zip Code: **25635** Country: **US**

FFL: ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition Problems Estimate History / Status Shipping / Billing

ID	Date	Code	User ID	Desc1	Desc2	Status
11/5/2010 9:2...	Maint	Travisbw	Repair Maintenance	Status: F		
11/5/2010 1:2...	Estimate	Travisbw	Estimate Update	Status: A		
11/5/2010 1:2...	ApprovalH...	System	Immediate SAP Allocation			
11/5/2010 1:2...	Expedite	pencefl	From: Repair Bench	To: Appr		
11/5/2010 3:3...	ApprovalH...	BatchJob	Quotation Control			

☐ Shipping Hold ☐ Interface Hold ☒ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return as Received ☐ Has Been Approved ☐ Internal Repair ☐ Exclude TATC

Current Status: ApproveHold 11/5/2010 1:22:25 PM
 Repairman: Travisbw
 ApproveRack: Repair Location
 ILN: Current Location
 ILN: Transfer Number

Repair Search Refresh Close

supryll - ILN/Prod frmREInquiry D1102R7XPIL Wednesday, Nov 3 2010 1:25 PM

start DMS - Desktop frmRepairMain - FGI Repairs DMS - Global Ser... Inbox - Microsoft...

RECEIVED

NOV - 3 2010

BY:

Attn Service Dept 4985

22"
BFI/85

Gun fires when safety is released.

B6663685

Model: 700



RE00209325

TRIG. ASSM has been altered.
cockect will not return under
sear. Check over, replace TPA,
clean + test fire at 1/2
normal charges

Quote

80.03

ROGER MUNCY
304-583-6969
UNCLE SAM'S LOANS
200 MAIN ST.
MAN WV 25635

8 LBS

1 OF

SHIP TO:

ARMS SERVICES DIVISION/REPAIR
REMINGTON ARMS COMPANY
14 HOEFLER AVE.
ILION NY 13357-1816