

**BARBER - Kinzer PPS GAL RE 0012647**

Remington Arms Co., Inc.  
Product Service  
Legal Case #:5336

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
216795	12/30/2010	12/8/2010	1/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Vedder	W3195 49th St.	Mauston	WI	53948		H 608-847-4375 E larno@merr.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1007	Fired on Safe Release	Unknown	
C	FSR			

12/7/10: Customer called in. He stated he had a FSR years ago. No damage, No injury. He stated he saw tv show & feels that we have a problem. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6899649	DZ	9/8/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	FABER BROS CHICAGO	SCOPE BASE	N			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV

Per Ilion - Quote to repair

**Repair/Replacement Cost Repair/Replacement Date**

12/8/10: Sending ARS, ltr, form, box. Box order# 1166472. df 1/17/11: Per Ilion - Could not duplicate concern. TA set screws altered. Replace TA, clean & test fire @ 1/2 normal cost - quote. df Customer apprvd & paid for repair. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		DZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Firing Pin	Slightly Worn; Functioning		

## BARBER - Kinzer PPS GAL RE 0012648

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	MIN TRIG RETURN HAS HAD BLP
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

22"  
029/7  
JH  
.012

5336

[COPY]

December 8, 2010

Larry Vedder  
W3195 49<sup>th</sup> St.  
Mauston, WI 53948  
Ph: 608-847-4375

Ref: # 5336

Dear Mr. Vedder,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

**Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service".** Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,  
D. Fulcher  
Consumer Affairs Administrator  
Remington, H&R, Marlin  
Phone: 1-800-243-9700  
Fax: 336-548-7872

RECEIVED  
JAN 06 2011

BY:.....

enclosure

Serial Number:

6899649

Model: 700



RE00216795

could not duplicate concern.  
T.A. set screws altered.  
Replace TPA, clean + test fire  
AT 1/2 normal cost.

Quote

BARBER - Kinzer PPS GAL RE 0012650

Print

Reset

<b>Model</b> Number: <input type="text" value="700"/>		<b>Serial</b> Number: <input type="text" value="6899649"/>	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: <input type="text" value="Larry Vedder"/>		Date of Purchase: <input type="text" value="Early 1980's"/>	
Address (no PO Boxes): <input type="text" value="W3195 49th St."/>			
City: <input type="text" value="Mauston"/>		State: <input type="text" value="Wi"/>	Zip: <input type="text" value="53948"/>
Phone (Daytime): <input type="text" value="608-847-4375"/>		Fax: <input type="text"/>	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <input type="text" value="larno@merr.com"/>			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <div style="border: 1px solid black; padding: 5px;"> <p>in the late 80's or early 90's the rifle discharged when turning the safety off while never touching the trigger two different years. I took it to the gunsmith in Baraboo, WI. He cleaned it and said he couldn't see anything wrong. I have not fired the gun since then. I would feel much safer with the X mark pro trigger.</p> </div>			
500 characters left			
<b>Ammunition Information:</b>			
Manufacturer: <input type="text" value="Remington"/>		Type: <input type="text" value="Core lock"/>	
Other (i.e. bullet weight/type, shot size, powder): <input type="text" value="150 gr."/>			
<b>Handload Information:</b>			
Powder Used: <input type="text"/>		Powder Weight: <input type="text"/>	
Case/Hull Used: <input type="text"/>		Primer Used: <input type="text"/>	
Bullet Type/Shot Size: <input type="text"/>		Reloader Used: <input type="text"/>	
<b>Firearms Care (Cleaning and Lubrication):</b>			

BARBER - Kinzer PPS GAL RE 0012651

Brand of cleaning solution used:

How often do you clean the bore? (Months or Number of rounds) *used only 3 gun seasons in w. and was cleaned after every season*

How often do you clean the action? (Months or Number of rounds)

How often do you clean the trigger assembly? (Months or Number of rounds)

Brand of lubricant used: *Rem oil*

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >  YES  NO

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? *Early 1990's*

What were the services performed? *Checked To See Why it fired when safety was turned off*

Ship your INSURED firearm by either UPS or Parcel Post to:  
  
**Remington Arms Co., Inc.**  
**Attn: Arms Service Division**  
**14 Hoefler Avenue**  
**Ilion, NY 13357**

**WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.**

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper

**BARBER - Kinzer PPS GAL RE 0012652**

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



www.remington.com

Remington Arms Company, Inc.  
 870 Remington Drive  
 P. O. Box 700  
 Madison, NC 27025-0700

### ARS LABEL REQUEST FORM

DATE:	12/8/2010	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PKG:	10 lbs
<b>PLEASE CHECK ONE</b>			
MEDIA COORDINATOR TO MAIL		I WILL MAIL	XXXXXX
DESCRIPTION: Ref # 5336 rifle			

### LABEL INFORMATION

MAIL LABEL TO: Larry Vedder W3195 49 <sup>th</sup> St. Mauston, WI 53948 Ph: 608-847-4375
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

**PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR**

4XX596      DEC 8, 2010      ALL CURR USD      1 OF 1  
 SVC GNDCOM      ACT WT 10.0 LBS  
 TRACKING# 1Z4XX5969067428158  
 REF 1:LARRY VEDDER/CD/DMF  
 REF 2:5336/RIFLE

HANDLING CHARGE 0.00  
 SINGLE-PIECE PUB RATE CHRGS:      SVC T/P USD  
 DV 0.00      COD 0.00      RS 0.50  
 DC 0.00      DGD 0.00      SD 0.00  
 AH 0.00      PR 0.00      SP 0.00  
 TOT PUB CHG 8.74      PUB+HANDLING 8.74







