PrintDisplay –₃ BARBER - Kinzer PPS GAL RE 0012894

Remington Arms Co., Inc.

Product Service Legal Case #:5123

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

213528 12/9/2010 11/17/2010 12/10/2010

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact

Incident John H Young 678 Croft Ferry Rd East Gadsden AL 35903 H 256-492-6397

Incident Information

Claims Codes Repair Est. Medical Medical Treatment Status

PΙ

PD Cause:4006 Altered Adjustments or

Fired on safety Cause. 4000 Components Unknown

S release Concern:1007 Fired on Safe Release

C

11/17/10 Per call from Young, last year he had his 700 fire when removing the safety two times. He put it up and has not used it since. It has a bolt lock. He wants us to do what we have to in order to make it safe. He has a grandson that may be using it in the future.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/7MM REM MA n/a 6248734 PS 6/1/1969

Date Purchased Where Purchased Accessories Original Owner

SLING,AFT MKT STK,MUZZLE BRAKE Y

CONCERN:FSR

Ammunition Information - None Defined
Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Date Date

Settlement APV APV

Per Ilion, replace TPA, clean under BLSM program price of \$20 + shpg

Repair/Replacement Cost Repair/Replacement Date

40.23 12/14/20

11/17/10 Mailing ARS.cm 12/14/10 Per Ilion, will follow down. Trigger assm and action very dirty. Set screws altered. Replace TPA, clean and test fire under BLSM program price for \$20 plus shipping.cm 12/14/10 Young said he sent it to the factory to have all this done about 3 years ago. This serial number is not in ARMS so it must have been sent before 1999. He says he cleans the trigger and rifle every year however the pictures show that it is not clean. He reluctantly will pay the \$37.cm

Examination[Remington/CF/BA]

Part	zer PPS GAL RE 001289 Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/10/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	POOR MAINTENENCE
	Description		24" 7MM REM MAG SS, AFT MKT MB
	Date Code		PS
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
·····	Firing Pin	Slightly Worn; Functioning	7
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	Ħ
	Condition	Slightly Worn; Functioning	7
Extractor	Cut Condition	Slightly Worn; Functioning	=
	Ext/Eject Test	False	Ħ
	Block Condition	Select	<b>=</b>
Locking	Lug Condition	Slightly Worn; Functioning	=
_	Notch Condition	Select	<u> </u>
	Exterior Condition	Worn; Functioning	VERY DIRTY
Overall	Stock Condition	Select	AFT MKT
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	=======================================
Receiver	Bulged	False	<b>=</b>
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	╡
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
,	. 1000.	Test Fired	False
Feeding Test	Tests	False	
eeding rest	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN VERY DIRTY
Tuissa	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
		M/700 Bolt Lock	BLI SCREWS ALTERED
	Suo-Assembly	IMI 100 BOIL LOCK	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5123&Type=Garber - Kinzer PPS GAL RE 06/12469010

COBARBER - Kinzer PPS GAL RE 0012896

BRAKE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5123&Type=Case

12/14/2010

BARBER - Kinzer PPS GAL RE 00128972/10/10 09:11:13 👣 frmRepairMain - FGI Repairs. File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Location 🖪 frmREInquiry - Repair Inquiry Repairman Bruce Travis Repair Number: RE00213528 MM-REM MAG Status Approval Fold 12/10/2010 5:44:517 Verily Repair ADDRESS INFORMATION Customer Return To JOHN YOUNG JOHN YOUNG Name: Address 1: 678 CROFT FERRY RD EAST 678 CROFT FERRY RD EAST Address 2 PD Box: PO Box City: GADSDEN GADSDEN State: AL Country: US AL Country: US Zip Code: 35903 Zip Code: 35903 Contact / Condition | Problems | Estimate | History / Status | Shipping / Billing | 3 **2011年2月1日** 净化 类杂层系 Current Status Date Description Code: The User ID The Description of the User ID The Description of the User ID The Description of the User ID The ID The User ID The ID Th Shipping Hold ApprovalHold Interface Hold 12/9/2010 8:5... New Repair Added 12/10/2010 5:44:51 AM Travisbw Estimate Sent 12/9/2010 8:5... Expedite To: lopatafi From: Check In ApproveRack □ Parts Received 12/10/2010 5:... Maint Travishw Repair Maintenance Status: N Repair Location Passed Inspection A ILN 12/10/2010 5:... Estimate Travisbw Estimate Update Status: A. Return as Received Current Location 12/10/2010 6:.. ApprovalH. System Immediate SAP Allocation T Has Been Approved ILN Transfer Number Internal Repair Exclude TATC Repair Search Refresh Close nagletj - ILN/Prod Thursday, Dec 9 2010 4:12 PM 🖎 frmRep...

To d		<u></u>	. به د ا	\	
	GEC	1	3	2010	i.
В	Y:				

24" ps 6/69 3#

5123

November 17, 2010

John H Young 678 Croft Ferry Rd East Gadsden, AL 35903

Subject: #5123, Model 700

Dear Mr. Young,

Enclosed is a UPS ground prepaid shipping label. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure

6248734 Model: 700



will follow down T.A. + Action weny dirity. Set screws Altered.

Replace TRA clean + Test fine

under BLP Con # 20.00 + Ship

Quite

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025
Phone 800-243-9700 ● www.remington.com

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 Para	Serial Number:			
Are you the original owner?: TYES NO				
Name: JOHN H. Young	Date of Purchase:			
Address (no PO Boxes): 678 200 F	TFerry Ro.E			
city: Stadsien	State: AL Zip: 35913			
Phone (Daytime): 356 - 492 - 6397	Fax:			
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be			
sent)				
E-mail Address:				
I would like to receive future e-mail updates from Ren	nington.			
Please describe your problem and date of occurrence:				
500 characters left Ammunition Information:	<b>Z</b>			
Manufacturer:	Туре:			
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			

## BARBER - Kinzer PPS GAL RE 0012900

Firearms Care (Cleaning and Lubrication):				
Brand of cleaning solution used:				
How often do you clean the bore? (Months or Number of rounds) $ extstyle = b$				
How often do you clean the action? (Months or Number of rounds)				
How often do you clean the trigger assembly? (Months or Number of rounds)				
Brand of lubricant used:				
How often do you lubricate the bore? (Months or Number of rounds)				
How often do you lubricate the action? (Months or Number of rounds) $\vdash \vdash \vdash \vdash \vdash$				
How often do you lubricate the trigger assembly? (Months or Number of rounds)				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?  YES  NO				
When was the last time that your firearm was serviced by a Remington authorized				
repairman/gunsmith?) About 5 Tois lens ov:				
What were the services performed?)				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357				
(E)WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.				



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	11/17/2010 REQUESTED BY:	christy
QUANTITY:	1 WEIGHT PER PACKAGE:	10
HTEVER CHECK ONE:		
MEDIA		
COORDINATOR		xxx
TO MAIL	I WILL MAIL	
DESCRIPTION:		
	700	
	·	

## LABEL INFORMATION

MAIL LABEL TO:	John H. Young 678 Croft Ferry Rd East Gadsden, AL 35903		
RETURN ITEM TO	: Rem Product Service		

## PLEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION:

```
4XX596 NOV 18, 2010 ALL CURR USD 1 OF 1
TRACKING# 1Z4XX5969066001146
REF 1:JOHN H YOUNG/CD/CM
REF 2:700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS:
DV 0.00
COD 0.00 RS 0.50
AH 0.00 PR 0.00 SD 0.00
TOT PUB CHG B 74

PUB+HANDLING 8.74
```









