

BARBER - Kinzer PPS GAL RE 0012937

Remington Arms Co., Inc.

Product Service

Legal Case #:4771

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
205339	10/7/2010	10/8/2010	10/8/2010				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Lyndon	Zuiderveen	8300 South Forward Rd	McBain	MI	49657		H 231-590-4533 E zuiderveenl@michigan.gov

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fires on safe release	Concern:1007 Fired on Safe Release	Unknown	
C				

10/14/10 Per letter with rifle, this gun will fire when you take the safety off. It has done it 2 times this last hunting season. He saw on our site there there is a safety update that can be done on the rifle.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	A6885630	AA	2/9/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	WILLIAMS SPTG CADILLAC MI		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.23	10/14/2010				

10/14/10 Per Ilion, could not duplicate concern. Check over, replace TPA, clean and test fire under bolt lock program price of \$20 + S&H.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/8/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		AA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

<b>BARBER</b>		<b>Kinzer PPS GAL RE 0012938</b>	<b>012938</b>
Bolt	Condition	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	STANDARD M/700 BOLT LOCK SAFETY	
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	
	Altered	True	
	Sub-Assembly	M/700 Bolt Lock	

supryfl - ILN/Prod
frmRepairMain
D1102R7XPIL
Tuesday, Oct 12 2010
9:48 AM

PS 14827

22"  
AA 3/8"  
3.5"  
011

4771

Lyndon Zuiderveen  
8300 South Forward Rd.  
McBain, MI 49657  
231-590-4533  
zuiderveenl@michigan.gov

Remington 30-06 Model 700 Serial No. A6885630

Bolt 5630

This gun will fire when you take the safety off. It has done it 2 times this last hunting season. I seen on your web site that there was a safety update that could be done on the rifle.

Please inspect and repair. Please call if you need anymore info.

Thank you.

could not duplicate concern.  
check over; replace TPA, clean +  
test fire under bolt lock  
program for \$20.00

Quote

A6885630

Model: 700



RE00205339