Remington Arms Co., Inc. **Product Service** Legal Case #:5333

Case Information

RE# Date Opened(PS) **Incident Date** Pre Lit Lit Obsolete **Date Opened Date Closed** 1/4/2011

12/28/2010 12/8/2010 216431

X

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Jim Gosselin 917 Countryside Blvd Manchester NH 03102

H 603-622-2512 E jim.gosselin@comcast.net

Incident Information

Claims Codes Repair Est. Medical Treatment **Medical Status**

ΡĮ

Cause: 4038 Could Not Duplicate Concern PD

Concern: 1008 Fired on Bolt Closing

Unknown

S C FBC

12/7/10: Customer called in. He stated he had a FBC last week but did not have a date. No damage, No injury. df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type

CF/BA 710/270 WIN 27408 71229422 PZ 6/2/2005 8:52:14 PM Remington

Where Purchased Accessories Original Owner **Date Purchased**

6/1/2006 WAL-MART DC 6003R-REGULAR SCOPE BASE

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date

Settlement APV APV Per Ilion - Check

over, clean, test @ n/c

> Repair/Replacement Repair/Replacement Cost Date \$27 1/14/2011

12/8/10: Sending ARS, ltr, form. df 1/14/11: Per Ilion - Could not duplicate concern. TA functioning as designed. Check over completely, clean & test @ n/c. Gun shipped to cust. on 1/11/11. df 1/18/11: Customer called in. He was irate with me. He is upset that the factory could not duplicate the issue he experienced & stated he was going to consult with an attorney & join a class-action lawsuit. Stated the gun could kill someone. Then he hung up. df

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		1/4/2011
Product Type		RF
Action Type		A
	Examiner Exam Date Product Type	Examiner Exam Date Product Type

	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		PZ
Darre!	Bore Plugged	False	
	Dulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Massina	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Received	Bulged	False	
	Description		M/710 SAFETY
Safety	Function	Slightly Worn; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	5.5#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	

Unint
r Pom

Reset

Model Number: 7/0	Serial S			
	Number: 7/22 9472			
Are you the original owner?:				
Name: JAMES GOSSEIN	Date of Purchase:			
Address (n	no PO Boxes):			
91) COUNTRYSIDE				
City: MANCHESIZA	State: N (4 Zip: 03102			
Phone (Daytime): <u>C03~623~25/2</u>	Fax:			
E-mail Address:(if e-mail address is prov	vided, notification of receipt and shipment will			
be sent) Jim gosscl	IN A COMERST. NET			
E-mail	Address:			
☑ I would like to receive future	e e-mail updates from Remington.			
	olem and date of occurrence:			
I was out tanget shooting 1/30/10 when putting the First Round into the chamben closning				
1/30/10 when	putting The First			
ROUND into The	e chambra cherina			
The Bolt The or				
	Toot Adout as ROUND			
Ammunition	n Information:			
Manufacturer: Remington	Type: 270 130 62			
Other (i.e. bullet w	/eight/type, shot size,			
powder):	Could not dupli conte com			
	checkover completely, c			
	iformation: + Test fine At N/c			
229422	Powder Weight: # 230145			
22/422 : 710	Primer Used:			
	Reloader Used:			
RE00216431				

BARBER - Kinzer PPS GAL RE 0012980

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds) しょとと
How often do you clean the trigger assembly? (Months or Number of rounds) CACK TIME Brand of lubricant used: Remington oil
Brand of lubricant used: Remingtow oil
How often do you lubricate the bore? (Months or Number of rounds) とこと ていいしょう
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services
performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

BARBER - Kinzer PPS GAL RE 0012981

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/8/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
RUEASECHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5333 rifle			

LABEL INFORMATION

MAIL LABEL TO: Jim Gosselin

917 Countryside Blvd. Manchester, NH 03102 Ph: 603-622-2512

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

2010 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 DEC 8, 2010 TRACKING# 1Z4XX5969065606521
REF 1:JIM GOSSELIN/CD/DMF
REF 2:5333/RIFLE SVC GNDCOM HANDLING CHARGE 0.00 SVC T/P USD RS 0.50 SINGLE-PIECE PUB RATE CHRGS: 0.00 COD DV 0.00 DC 0.00 AH 0.00 SD 0.00 0.00 DGD SP 0.00 0.00 PUB+HANDLING TOT PUB CHG 7.42





