BARBER - Kinzer PPS GAL RE 0012996^{Remington Arms Co., Inc.}

Product Service

Legal Case #:5406

Case Information

Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete RE# 12/13/2010 1/20/2011 X 1/11/2011 218400

Customer Information

Last Name Street City Zip Contact Type Business First Name State Age

3387 Ashland Rd Reidsville NC 27320 H 336-346-6968 Incident Charlie King

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡĪ

PD shot hole in door of

Cause:4054 As received Follows Down

Fired when closing S

Concern:1008 Fired on Bolt Closing

Unknown

bolt

C

12/13/10 Per call from King, he bought his 710 2nd hand 4-5 yrs ago. He accidentally shot a hole in the door of the truck but thought it was something he did. He put it up but tried it again this year and it fired when closing the bolt.cm

Firearm Information

SKU DOM Mfg. Model/Ga. Serial Bbl. Type

Remington

CF/BA

710/270 WIN

27408 71087168 RW 11/26/2002 2:28:50

AM

Date Purchased

Where Purchased

Accessories

Original

Owner

11/1/2006

BANGERS LP SCOPE, RINGS, BASE, SLING N

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Cash Reim. Cash Release of Claims Settlement **Release Date** Date Reimbursement Date Settlement APV **APV**

Replace at no charge as a gesture of goodwill

Repair/Replacement Repair/Replacement

Cost

Date

153.00

1/24/2011

12/13/10 Mailing ARS.cm 1/20/11 Repair at no charge as a gesture of goodwill.cm 1/24/11 Ilion is replacing with a new 770 model.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner	,	B.TRAVIS
	Exam Date		1/12/2011

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5406&Type=Case

1/24/2011

BARBER - KI	inzer PPS GAL RE 0012997 Product Type	1	RF
Examination	Action Type	7	A
	Assigned To	=	T.NAGLE
Cause	4054	As received Follows Down	O/S TPA NO LONGER AVAILABLE
	Description		22" 270 WIN
	Date Code	╡	RW
	Bore Plugged	False	7
l	Bulged	False	뒥
Barrel	Fired	False	=
İ	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	, .
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
<u> </u>	Ext/Eject Test	False	٦
	Block Condition	Select	Ī
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	<u> </u>
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
l	Fore End Condition	Select	Ī
Receiver	Condition	Slightly Worn; Functioning	
,	Bulged	False	Ī
	Description	<u> </u>	M/710 SAFETY
Safety	Function	Like new; Functioning	7
	Sub-Assembly	Non-ISS	าี
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
.(

Page 3 of 3

BARBER - Kinzer F	PS GAL RE 0012998	Test Fired	False	
Feeding Test	Tests	False		
Trigger	Condition	Slightly Worn; Functioning	HAS MIN TRIG RETURN	
	Pull	Select	2#	
	Altered	False	DID NOT APPEAR TO HAVE BEEN ADJUSTED	
	Sub-Assembly	Other Remington		
Non-Remington Components	Description		SLING	

*

5406

... December 13, 2010

72" /U

Charlie King 3387 Ashland Rd Reidsville, NC 27320

Subject: #5406, Model 710

Dear Mr. King,


Thank you for your patience. Enclosed is a UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com Rep. n/c godail.





NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 7/0	Serial Number: 7/087168			
Are you the original owner?: (ES) NO				
Name: CHARLLE KING &	Date of Purchase: NOVEMBER 2006?			
Address (no PO Boxes): 3387 ASHLAND ROAD				
City: REIDSUILLE	State: N.C. Zip: 27320			
Phone (Daytime): 336-348-6968 Fax:				
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be			
sent) Acre 306 MALL Com.	nana, KING3 @ G MAIL. COM			
E-mail Address:				
I would like to receive future e-mail updates from Rer	nington.			
Please describe your problem and date of occurrence				
Two years ago during dear seasons ? chambrand a found into the rible and it discharged. The round put a hole in the side of my peck-up and seat				
I did not use the gun until December 8th 2010.?				
were walking to a dear stand of	and the nill discharged			
again. I am a				
County Dame Warden.				
500				
characters left				
Ammunition Information:				
Manufacturer: WineHesTER	Type: 270 cal. 160 GR.			
Other (i.e. bullet weight/type, shot size, powder): WINCHESTER 270 CML 160 GR				
BALLISTIC TIP.				
Handload Information: N/A				
Powder Used: Powder Weight:				
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			

Firearms Care (Cleaning and Lubrication): REMINGTON CLEANING PRODUCTS
Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) HAVE NOT USED WEAPON ENOUS
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
NO NO
When was the last time that your firearm was serviced by a Remington authorized
repairmen/gunsmith?) NEVER, APPROXIMATELY 6 rounds have been fixed.
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefier Avenue Ilion, NY 13357
①WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
1 50





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE: 12/1	3/2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKA	GE:	10
PLEASE CHECKONE:			
MEDIA			į
COORDINATOR		XXX	
TO MAIL	I WILL MAIL		
DESCRIPTION:			
	710		
710	087168		

LABEL INFORMATION

MAIL LABEL TO:	Charlie King 3387 Ashland Rd Reidsville, NC 27320	
SEELISM TENATO	D D I I	
RETURN ITEM TO:	Rem Product Service	

LIPLEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

```
1 OF 1
                DEC 13, 2010 ALL CURR USD
ACT WT 10.0 LBS
4XX596
SVC GNDCOM
TRACKING# 1Z4XX5969066644596
REF 1:CHARLIE KING/CD/CM
REF 2:710/71087168
HANDLING CHARGE 0.00
                                                SVC T/P USD
SINGLE-PIECE PUB RATE CHRGS:
                                                 RS 0.50
                                  0.00
                          COD
                                                  SD 0.00
DV 0.00
DC 0.00
                          DGD
                                  0.00
                                                  SP 0.00
                                  0.00
                          PR
AH 0.00
                                                      8.20
                                  PUB+HANDLING
 TOT PUB CHG 8.20
```



