Remington Arms Co., Inc.
Product Service
Legal Case #:4805

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 209164
 11/3/2010
 10/20/2010
 11/4/2010
 10/20/2010
 X

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Laszlo Lengyel 281 Cricklewood Circle Lansdale PA 19446 C 215-896-4534 E ljlengyel@yahoo.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4015 Improper Maintenance

Concern: 1007 Fired on Safe Release

Unknown

S C FSR

10/20/10 @ 11:59am - I spoke w/customer. He stated that his rifle fired when he moved the safety from safe to fire this morning. Rifle was pointed in the air. Safety is now stuck and will not move. dmf

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 710/3006 SPRG
 27410
 71155221
 LY
 2/1/2004 7:44:56 PM

Date Purchased Where Purchased Accessories Original Owner

Date I di chased Where I di chased Accessories Original Owner

Cabela's SCOPE BASE Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Settlement Release Date Reimbursement Settlement APV APV

Per Ilion - Quote to repair @ 1/2 normal charges

Repair/Replacement Cost Repair/Replacement Date

10/20/10: Sending ARS & letter by email. Sending box. Order# 1150401. dmf 11/5/10: Per Fred S. - Trigger assemb is contaminated with a partially dried & sticky substance. Residue causing parts to work sluggish. Replace tpa, clean & test fire @ 1/2 normal charges - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		11/4/2010	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		F.SUPRY	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4805&Type=Case

11/5/2010

1 ago 2 01 J

## BARBER - Kinzer PPS GAL RE 0013009

Cause	4015	Improper Maintenance	WILL FOLLOW DOWN
	Description		22" 30-06 SPR
	Date Code	7	LY
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	<b></b>
	Fired while Obstructe		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	·
Bolt	Face	Slightly Wom; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Wom; Functioning	
Extractor	Cut Condition	Slightly Wom; Functioning	
_	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Wom; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
Iviagazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description	]	STANDARD M/710 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Talassa	Condition	Slightly Worn; Not Functioning	DRIED AND STICKY LUBE RESIDUE.PARTS WORK SLUGGISH
Trigger			

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4805&Type=Case

11/5/2010

Altered	False
Sub-Assembly	Other Remington

File		Estimate Repair	Expedite	Repair Inquiry	Repair Tools	CSR Tools	Reports	Table Maintenanc	e System				
. 6				PPS GAL	RE 0013	3011							
	Repair Numbe	nguiry - Rej	MARCHANIA	ITV 155221: Model 710 (	enie Fre Calhe	r 30 - Repair	man: Bruce T	<del> </del>					
,	Verily Repai	j v	06 W/SC	OPE Produced: 02/01	/2004 SKU: 2741	0 (		Mold 11/4/2010 1:45	27 PM				
		NFORMATION Customer  LASZLO LENGYT	L	<b>.</b> Recei	ALLERS EXCEPT TO	turn To SZLO LENGYEL		C Received	frain .			N.	
	Address Address	XX		90 Box [		CRICLEWOOD O	CIRCLE PO	Box (					
2	100000	LANSDALE PA Zip Code		Country US	IAI PA	NSDALE Zip Code: 1		Country: US					
	10000				FFL (TTT)				<u>- 189</u>				
	Contact / Co	ndition   Problems   E	stimate: History	/ Status   Shipping /	Billing		Tradition Committee	Current Status	Wang Til	7 .			
2	Date 11/3/201		Use ID conscion	Desc1 Repair Added	Desc2	[ Interface	Hold	ApprovalHold 11/4/2010 1:45:2					
	11/3/201	0 10: Expedite 8 11: Maint	schultsom Travistiw	From: Check In Repair Maintenance	To: Status: Re	Estimate Parts Res	ceived	Travisbw Repair Bench Repair Location					
	11/4/201		Travisbw System	Estimate Update Immediate SAP Alloca	Status: Ap	I Heturn a	s Received	ILN Current Location					
	11/4/201		System			☐ Has Beer Internal F	Repair	ILN Transfer Numbe					
	Repair	Search				F Exclude	IAIL	Refresh	Close	A.			
			41 Text (					A STATE OF THE STA					
				LEI?									
						\$ 15 T	7512						
						44		خلزل					
				***			es il						
					- 200	***************************************							
-								15 (E)					
							- A The advances of A species of	Marie and the second second					
Z Si	upryfi∹ILN/Pi	od		frmREInquiry			D1	102R7XPIL		Wednesday, Nov.	i 2010	1:25 PM	
∄,st	art (	JDNS - Darktoo	/ Com	rRepairMain	ce dive e do	Delso. 1	Jan D	ie dat   DAI	genggain)	G-Massa	THE RESERVE OF THE RESERVE OF THE PARTY AND	roebo	District

	C	رَحَرَ	1	15 E	ر س
	配C Nov	-	5	2010	الل
В	Y:				


## UPS Electronic Return Label: View/Print Label

- 1. Ensure that there are no other tracking labels attached to your package.
- 2. Fold the printed label at the dotted line. Place the label in a UPS Shipping Pouch. If you do not have a pouch, affix the folded label using clear plastic shipping tape over the entire label. Take care not to cover any seams or closures.
- 3. Drop-off
  - O Take this package to any location of The UPS Store®, UPS Drop Box, UPS Customer Center, UPS Alliances (Office Depot® or Staples®) or Authorized Shipping Outlet near you. Items sent via UPS ReturnsSM Services(including via UPS Ground) are accepted at Drop Boxes, to find your closest UPS location visit <a href="https://www.ups.com/content/us/en/index.jsx">www.ups.com/content/us/en/index.jsx</a> and select Drop Off. <a href="https://docator.org/property-ups-accepted-
  - O Daily Pick up customers: Have your shipment(s) ready for the driver as usual.

TRIG. ASSM. is contain inated with which to part find its destrainty lubrication of the light of the land of the constant shows the changes find of 1/2 nonmal changes



FOLD HERE



+,0/2/17

Sonh

BARBER - Kinzer PPS GAL RE 0013012

Semailed my letter & factory form to customer. NES October 20, 2011 Label will be consided

2:00pm ET 10/20/10

Spiperately by Corty Rudson.

Laszlo Lengyel 281 Cricklewood Circle Lansdale, PA 19446 Ph: 215-896-4534

Email: ljlengyel@yahoo.com

Subject: # 4805

Dear Mr. Lengyel,

A prepaid UPS shipping label to cover shipment of your firearm to our factory for examination is being sent in a separate email.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Fred Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,

Dell Fulcher

Consumer Affairs Administrator

Remington, H&R, Marlin

Well Fil you

Phone: 800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

E-mail: dell.fulcher@remington.com

df enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



October 20, 2010

Laszlo Lengyel 281 Cricklewood Circle Lansdale, PA 19446 Ph: 215-896-4534

Email: ljlengyel@yahoo.com

Subject: # 4805

Dear Mr. Lengyel,

A prepaid UPS shipping label to cover shipment of your firearm to our factory for examination is being sent in a separate email.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Fred Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,

Dell Fulcher Consumer Affairs Administrator Remington, H&R, Marlin

Phone: 800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

E-mail: dell.fulcher@remington.com

df enclosure

$\overline{}$		_
_		
$\sim$	nnt	
	11111	

Reset

Model Number:	Serial Number:						
Are you the original ow	ner?: 🗆 YES 🗆 NO						
Name:	Date of Purchase:						
Address (no	PO Boxes):						
City:	State: Z	lip:					
Phone (Daytime):	Fax:						
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)							
E-mail A							
☐ I would like to receive future e							
nas et	Please describe your problem and date of occurrence:						
Ammunition I	40.000						
Manufacturer:	Type:						
Other (i.e. bullet wei powder):	ght/type, shot size,						
Handload Information:							
Powder Used:	Powder Weight:	*** ** ** ** ** **					
Case/Hull Used:	Primer Used:						
Bullet Type/Shot Size:	Reloader Used:						
Firearms Care (Cleaning and Lubrication):							

http://www.remington.com/asp/factory\_repair\_form.asp

10/20/2010

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES □ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling.  Preferably,  ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		10/20/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACKA	\(\(\) 10 lbs
RLEASEICHECKIONE MEDIA COORDINATOR TO MAIL	•			
DESCRIPTION:	Ref# 4805 Rifle			

## LABEL INFORMATION

MAIL LABEL TO: Laszlo Lengyel
281 Cricklewood Circle
Lansdale, PA 19446
Ph: 215-896-4534
Email: ljlengyel@yahoo.com

RETURN ITEM TC Remington Arms
Attn: Product Service/Supry
Ilion, NY
Please email ARS label to customer

# PLEASE COMPLETE ALL PARTISION THE CONTROL OF THE PARTISION OF THE PARTISIO

ljlengyel@yahoo.com

4XX596 OCT 20, 2010 ALL CURR USD ACT WT 10.0 LBS SVC CNDCOM 1 OF 1 TRACKINGH 124XX5960067281502 REF 1:LASZLO LENGYEL/CD/DMF REF 2 REFA 4805/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: DV 0 00 SVC T/P USD COD 0.00 DC 0.00 RS 1.00 DGD 0 00 SD 0.00 AH 0.00 PR 0.00 101 PUB CHG 7 S5 SP 0.00 PUB+HANDI TNG

# REMINGTON ARMS SERVICE Quotation BARBER - Kinzer PPS GAL RE 0013019 PO Box 700

Estimating Report

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 AII PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

www.remington.com

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBE PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXI

IF WE DO NOT RECEIVE YOU	IR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS REC	CEIVED, POSTAGE D	or or go	COTE TO
Repair Number RE00209164	Serial Number / Description 71155221 Model 710 Center Fire Caliber: 30 -06 W/SCOPE		Customer.	Dell
Customer: LASZLO LENGYEL 281 CRICLEWOOD LANSDALE, PA 19	CIRCLE	Return To: LASZLA 281 CRI LANSD		
	COVER Card No PO Number:			
Daytime Phone: (			Date:	
Reported M123 - FORWARD T	Problems Four O PRODUCT SERVICE FOR INSPECTION M12	ıd	O PRODUCT SERVICE FOR	INSPECTION

## Technition Comments

trigger assm is contaminated with a partially dried and sticky lubrication residue causing parts to work sluggish.replace trigger plate assm, clean and test fire at 1/2 normal charges.

Material	Type	STIMATE (note: C.O.D./Shipping and Handling Description	Charges a	re NOT Includ	led in this (	Quote.) 🦠 🖔	Disc	Amount
Waterial	1960	Description	Needed	vi ai i anty	From Inv	Trice	Disc	Asnount
F301265	Part	710 REC. INSERT ASSB. COMPLETE	1	Billable	1	58.00	50	29.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	0	17.00
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50

Sub Total:

57.50

Est Sales Tax:

## Fuld APP BEH Marke PPS GAL RE 0013020

From: Sent:

Laszlo Lengyel [ljlengyel@yahoo.com] Thursday, November 11, 2010 3:30 PM

To:

Fulcher, Dell Marie

Subject:

RE: Laszlo Lengyel - Ref# 4805/RE00209164

Sorry, yes \$60.95

## --- On Thu, 11/11/10, Fulcher, Dell Marie < Dell. Fulcher@remington.com > wrote:

From: Fulcher, Dell Marie < Dell.Fulcher@remington.com > Subject: RE: Laszlo Lengyel - Ref# 4805/RE00209164

To: "Laszlo Lengyel" ljlengyel@yahoo.com> Date: Thursday, November 11, 2010, 9:05 AM

The quote is for \$60.95. May I get approval for that?

Thank you,

Dell Fulcher | Consumer Affairs Administrator Remington Arms Company, Inc. 870 Remington Dr., PO Box 700, Madison, NC 27025-0700 Phone: 1.800.243.9700 | Fax: 336.548.7872

Freedom Group Family of Companies Remington | Bushmaster Firearms | DPMS / Panther Arms | Marlin | H&R | Dakota Arms Parker Gun | L.C. Smith | EOTAC | INTC | Advanced Armament Corp | Barnes Bullets

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system. Thank you.

From: Laszlo Lengyel [mailto:ljlengyel@yahoo.com] Sent: Thursday, November 11, 2010 8:32 AM

To: Fulcher, Dell Marie

Subject: RE: Laszlo Lengyel - Ref# 4805/RE00209164

I approve the repairs quoted for ref#4805/RE00209164 not to exceed \$60.94.

American Express

REDACTED 5007

Laszlo J Lengyel

--- On Wed, 11/10/10, Fulcher, Dell Marie < Dell. Fulcher@remington.com > wrote:

From: Fulcher, Dell Marie < Dell.Fulcher@remington.com > Subject: RE: Laszlo Lengyel - Ref# 4805/RE00209164

To: "Laszlo Lengyel" <ijlengyel@yahoo.com> Date: Wednesday, November 10, 2010, 9:14 AM

You can mail the quote in with check, money order, or credit/debit card number.

You can also send me an email with your approval & card number and I can get the repair started that way.

Dell Fulcher | Consumer Affairs Administrator Remington Arms Company, Inc. 870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 | Fax: 336.548.7872

Freedom Group Family of Companies Remington | Bushmaster Firearms | DPMS / Panther Arms | Marlin | H&R | Dakota Arms Parker Gun | L.C. Smith | EOTAC | INTC | Advanced Armament Corp | Barnes Bullets

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system. Thank you.

From: Laszlo Lengyel [mailto:ljlengyel@yahoo.com] Sent: Wednesday, November 10, 2010 9:07 AM

To: Fulcher, Dell Marie

Subject: RE: Laszlo Lengyel - Ref# 4805/RE00209164

how do I make payment?

--- On Mon, 11/8/10, Fulcher, Dell Marie < Dell. Fulcher@remington.com > wrote:

From: Fulcher, Dell Marie < Dell.Fulcher@remington.com > Subject: RE: Laszlo Lengyel - Ref# 4805/RE00209164

To: "Laszlo Lengyel" < ljlengyel@yahoo.com> Date: Monday, November 8, 2010, 9:51 AM

The issue was addressed & the findings are stated on the quotation. BARBER - Kinzer PPS GAL RE 0013022

Product Service found the trigger assembly is contaminated with a partially dried and sticky lubrication residue causing the parts to work sluggish.

On the Model 710, the whole Receiver Insert Assembly has to be replaced.

They are offering to do the repair at 50% off.

Dell Fulcher | Consumer Affairs Administrator Remington Arms Company, Inc. 870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 | Fax: 336.548.7872

Freedom Group Family of Companies Remington | Bushmaster Firearms | DPMS / Panther Arms | Marlin | H&R | Dakota Arms Parker Gun | L.C. Smith | EOTAC | INTC | Advanced Armament Corp | Barnes Bullets

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system. Thank you.

From: Laszlo Lengyel [mailto:ljlengyel@yahoo.com] Sent: Saturday, November 06, 2010 4:50 PM

To: Fulcher, Dell Marie

Subject: Re: Laszlo Lengyel - Ref# 4805/RE00209164

### Dell Fulcher

I sent this rifle in because it fired after the safety was moved from safe to on. Per your estimate, none of this was addressed, the tech merely cleaned the assembly and replaced the trigger plate, then wants to charge me \$60.00. What about the non intentional discharge of the rifle? Please advise.

### Laszlo

--- On Fri, 11/5/10, Fulcher, Dell Marie < Dell. Fulcher@remington.com > wrote:

From: Fulcher, Dell Marie < Dell. Fulcher@remington.com>

Subject: Laszlo Lengyel - Ref# 4805/RE00209164
To: "ljlengyel@yahoo.com" <ljlengyel@yahoo.com>

Date: Friday, November 5, 2010, 5:58 PM BARBER - Kinzer PPS GAL RE 0013023

Please see attachment.

If you do not receive the attachment, please let me know and I will send it again or mail it.

Thank you,

Dell Fulcher | Consumer Affairs Administrator

Remington Arms Company, Inc.

870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 | Fax: 336.548.7872

Freedom Group Family of Companies Remington | Bushmaster Firearms | DPMS / Panther Arms | Marlin | H&R | Dakota Arms Parker Gun | L.C. Smith | EOTAC | INTC | Advanced Armament Corp | Barnes Bullets

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system. Thank you.