BARBER - Kinzer PPS GAL RE 0013188
Remington Arms Co., Inc.

Product Service Legal Case #:4878

Case Information

RE# **Date Opened** Date Opened(PS) Date Closed **Incident Date** Pre Lit Obsolete

10/25/2010 10/28/2010 10/28/2010 207955

Customer Information

First Name Last Name Street City Zip Contact Type Business State Age 181 Hall Rd 40874 H 606-374-6654 Incident James **Brock** Warbranch KY

Incident Information

Codes Claims Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause:4038 Could Not Duplicate Concern

S Concern: 1020 Fired on Bolt Opening Fired when opening bolt

C

Unknown

11/2/10 Per letter with rifle, he shot the gun 3 times target practicing. The 4th time he went to pull the trigger it wouldn't fire. He put the safety on then when he went to work the shell out the gun went off.cm

Firearm Information

Model/Ga. **DOM** Mfg. SKU Serial Bbl. Type

Remington CF/BA 770/30-06 SPR 85633 M71597008 AE 3/18/2010 4:30:26 PM

Date Purchased Where Purchased Accessories **Original Owner**

WAL-MART STORE 1247 SCOPE,RINGS,BASE U 10/4/2010

CONCERN: WENT OFF WITH SAFETY ON

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/770/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion, replace TPA as goodwill gesture

Repair/Replacement Repair/Replacement

Cost Date 42.77 11/2/2010

11/2/10 Per Ilion, could not duplicate concern. As a gesture of goodwill we will replace the TPA, check over and test fire.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/28/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 30-06 SPR
	Date Code		AE
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	


PrintDisplay Page 2 of 2

	: - KinggepRPS GAL RE 00 Shroud	Like new; Functioning	
Bolt	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Like new; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Like new; Functioning	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
D	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/770 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Like new; Functioning	
	Toota	Test Fired	False
eeding Test	Tests	False	
	Condition	Like new; Functioning	
Tricacor	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	

BARBER - Kinzer PPS GAL RE 0013190

File Add Re	The second second second second second	Expedite Repair In	iquiry Repair Tools CSR Tool	s Reports Ta	able Maintenance	System	in Contration	100010 de un de Arente de 1-31.	28 E3 2
Repail Number: Venly Repail		QUIV at: M71597008 : Model 770 06 SPRG Produced: 03/18/	Center Fie Caliber 2010 SKU: 85533 Status	Don Spraker Repairing 10/28/201	0 5 49 05 AM				
ADDRESS INF Name Address 1 Address 2	Customer	© Receiv	red from Return To DAMES BROCK 181 HALL ROAD		Received from				
City State		P0 Box US	WARBRANCH KY Zip Code 40874	PO Box: Country: US					,
Date 10/27/2010	12: New bordenla	Desci Repair Added	Desc2 Shipping Hold Interace Hold Status: Estim	R 10/28/20	nt Status epairing II (II 5 4905 AM orak erd)				
10/28/2010	95 Meint Travisbw	Repair Maintenance	Status Repa Paris Received Paris Received Passed Inspect Relum as Received Has Been Appr	ion Repair aved Curren	ear Bench Location ILN t Location ILN er Number				
RepairSi	earch		Γ.Exclude IATC	Refre	sh Close				
	, r - Ang								
ecci - edo José e edo Algoria		and the state of t							and the second second second
supryfi-	ILN/Prod Chibox - Marceair	frmRepairt			R7XPIL	Thursday, Oct	28 2010 උද්දේශ	7:57 AM ○プラリと 同じ	COT VIC

27.0° 15.77 42.77



Remington.

Factory Repair Instructions (NOTE: Please print and complete this form, and then include it with your firearm.)					
Model Number: 71597008	Serial Number: 47700 85 633-9				
Are you the original owner?: Layes and NO					
Name: James Brock	Date of Purchase: 10-4-2010				
Address (no PO Boxes): 8 Hall	Road				
					
city: Warbranch	State: Ky Zip: 4/08 74				
Phone (Daytime): (a Dlo) 374-6654	Fax:				
E-mail Address:					
Please describe your problem: T 5hn+ the gun 3					
times target Dractine.					
Then the 4th time there were I					
went to oull the trigger it wouldn't					
fire So I Dut the safter backon.					
then when I went to work the					
shell out the oun went off.					
Ammunition Information:					
Manufacturer: Federal Type: 30-06					
Other (i.e. bullet weight/type, shot size, powder): 150-grain					
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					
Brand of cleaning solution used: 1/01, 7					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
Thow often do you clean the trigger assembly: (Mondra of Number of Tourids)					
22-1-65-1-2-1-2-1-2-1-2-1-2-1-2-1-2-1-2-1-2-1-					
Brand of lubricant used:					

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds).

新株は18.12 株型は新丁一、1g数の新元の12.18 平

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

Ship your INSURED firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357



I YOUR FIREARM OR IN THE SAME BOX WITH THE F YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND-

nage in shipping and handling. Preferably, e returned.)

iss or damage...

e the box. Shipments without a proper

st. Remington is not responsible for purchase insurance from your carrier.

Charge repairs will be processed using the ronowing guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

> Could not duplicate concern. A> A Good-W. II Gestiene will replace TPA, check oven And TRST FILL

WARR AWY