

BARBER - Kinzer PPS GAL RE 0013336

Remington Arms Co., Inc.
Product Service
Legal Case #:5420

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
214103	12/10/2010	12/14/2010	12/14/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Appleton Scheels	---	Appleton Scheel	4301 W. Wisconsin Ave	Appleton	WI	54913		W 920-830-2977
Incident		Josh	Arndt	838 Emily St.	Menasha	WI	54952		H 920-725-4540

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent gun in for consumer. Consumer stated gun will fire when put in fire position. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM08 REM	84151	G6941066	LE	2/3/2010 8:23:19 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION	SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:FIRES WHEN PUT IN FIRE POSITION

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - check over & test fire @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$42	1/5/2011				

Per Ilion - Red powder residue on action. Check over at bench, TA is functioning as designed. Will clean, safety inspect & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/14/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 7MM08 REM
	Date Code		LE
	Bore Plugged	False	
	Bulged	False	

BARBER - Kinzer PPS GAL RE 0013337

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	RED POWDER RESIDUE ON/IN ACTION
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		STANDARD XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE

12/14/10 11:03:16

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Location

frmREInquiry - Repair Inquiry

Repair Number: **RE00214103** Serial: G6941066 Model: 700 Center Fire Caliber: 7.5
MM-08 REM LEFT / HAND Produced: 02/03/2010 SKU: 84151 Repairman: Status: New 12/12/2010 6:18:27 AM

Verify Repair...

ADDRESS INFORMATION

Customer: Appleton Scheels Received from: Appleton Scheels Return To: Appleton Scheels Received from:

Name: Appleton Scheels Address 1: 4301 West Wisconsin Avenue Address 2: PO Box: City: Appleton State: WI Zip Code: 54913 Country: US

FFL:

Contact / Condition Problems Estimate History / Status Shipping / Billing

Date	Code	User ID	Desc1	Desc2
12/12/2010 6:18:27 AM	New	lopatafl	Repair Added	
12/12/2010 6:18:27 AM	Expedite	lopatafl	From: Check In	To:
12/14/2010 10:11:11 AM	Maint	Travisbw	Repair Maintenance	Status: New

Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return as Received ☐ Has Been Approved ☐ Internal Repair ☐ Exclude TATC ☐

Current Status: New
12/12/2010 6:18:27 AM
lopatafl
Repair Bench
Repair Location
ILN
Current Location
ILN
Transfer Number

Repair Search Refresh Close

nagletj - ILN/Prod frmRepairMain NAGLETJ Tuesday, Dec 14 2010 10:33 AM

start 2 Microsoft 2 Microsoft Part Search b... SAP Logon 710 My Excite - W... frmRepairMai... 11:03 AM

RECEIVED
DEC 17 2010

BY:.....

F

014649

APPLETON SCHEELS

Fox River Mall
4301 West Wisconsin Ave
Appleton, WI 54913
920.830.2977

REPAIR
TAG

5422

CUSTOMER <u>JOHN ARUNT</u>		INVOICE NO. F 014649	
ADDRESS <u>838 Emily St. Menasha WI 54952</u>		DATE RECEIVED <u>12-3-10</u>	
MODEL OR SERIAL NO. <u>G6941066</u>	PHONE <u>(920) 725-4540</u>	DATE RECEIVED <u>12-3-10</u>	
TROUBLE REPORTED <u>Fires when put in fire position</u>		PROMISED	DELIVERED
<u>Rem. 700LH 7mm-08</u>			
DESCRIPTION OF MATERIAL USED		AMOUNT	
<u>Customer Requests description of repairs done</u>			
<u>Insurance for: \$750.00</u>		#109	
<u>W/Scope</u>		TOTAL MATERIALS	
		LABOR	
RECEIVED BY <u>K. Gibson</u>		TAX	
Thank You! CASH ON COMPLETION OF WORK →		TOTAL	

2011
LEZ/10
34

Serial Number

G6941066

Model: 700



RE00214103

Red powder residue on action.

check over at bench, T.A.
is functioning as designed.
will clean, safety inspect + test
fire at 1X/c

warranty







