

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

BARBER - 5.22.06r0003629

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/BR	12-19-03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate - Scope Crosshair Shows	Front 25 Rear 25		
BL	12-22-03	Headspace	Min +.005		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min +.005		
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Fitting Pin Indent	.015 - .018 - .019 Aug 2014		
JS	12-29-03	Gear/Trigger Engagement	Avg. .0281		
JS	12-29-03	Gear lift	.0112		
SW/JS	1/13/04	Change out Bolt Head			
SW/JS	1/13/04	Headspace Min +.007			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace After proof Min +.007			
JS	1-15-04	200 Rd. Jack Function test	Bolt difficult to close on. Rds. 81-100; 121-140	200	207
SW	1-15-04	Headspace Min +.007	(Front Takedown screw loose , center was loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

Confidential - Submitter LS.27.0610003629 Order

ET20008

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-20

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min + .007
☒ Sear Engagement: 1st. .0246 2nd. .025 3rd. .0248
Ave. .0248 spec. .020" to .025" 83
☒ Trigger Pull: 1st. 4.222 2nd. 4.777 3rd. 4.759
Ave. 4.586 spec. 4 lb. to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive
wear: Bolt stop excessive wear, locking lugs same wear
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of
note: magazine Box protruding

TLW1303

Remington Confidential

ET20009